### Union Texas Petroloum

P. O. Box 1290 Farmington, N.M. 87499 (505) 325-3587

June 7, 1934

State of New Mexico Energy and Minerals Department Oil Conservation Division P.O. Box 2088 Santa Fe, New Mexico 87501 JUN 11 1322

420 225

#### Gentlemen:

Attached please find Union Texas Petroleum Corporations request for an exemption from the provisions of the New Mexico Natural Gas Pricing Act for the Zachry No. 29 well, located 937 feet from the North line and 1785 feet from the West line of Section 33, T29N, R10W, N.M.P.M., San Juan County New Mexico.

We would appreciate your signing in the place provided below and dating one copy of this letter and returning it to us. Please show the date which this application was received into record, so that our files will be complete.

Very Truly Yours,

UNION TEXAS PETROLEUM CORP.

Rudy! D. Motto

Area Operations Manager

RDM:svr

This application was received

on **E///87** (Date)

and placed on record on

- White

Title: (pance)

### **Union Texas** Petroleum

P.O. Box 1290 Farmington, N.M. 87499 (505) 325-3587


231

JUN 1 384

June 7, 1984

State of New Mexico Energy and Minerals Department Oil Conservation Division P.O. Box 2088 Santa Fe, New Mexico 87501

Zachry No. 29 937' FNL; 1785' FWL Sec. 33, T29N, R10W, NMPM San Juan County, New Mexico



#### Gentlemen:

Pursuant to the provisions of the New Mexico Oil Conservation Commissions Order R-5436, Section 62-7-5 NMSA 1978, Union Texas Petroleum Corporation requests an exemption for the above referenced replacement well from the provisions of New Mexico Natural Gas Pricing Act.

Attached for your consideration is a copy of an area plat showing the referenced proration unit, location of all wells thereon and the ownership and location of all wells offsetting it.

The original well on the subject proration unit was the Zachry No. 15-E well and was located 950 feet from the North line and 1650 feet from the West line of Section 33, Township 29N, Range 10W, N.M.P.M. of San Juan County, New Mexico. This well was dually completed as a Basin Dakota and Wildcat Gallup well. The Gallup formation was producing with the aid of a downhole pump and rod string when the rods paraffined in the tubing. While attempting to pull the rods the tubing string parted and fell in the hole. While attempting to recover the tubing string the Gallup zone had to be squeezed off to facilitate fishing operations. The Gallup formation would not produce which necessitated drilling a replacement well which was named the Zachry No. 29.

The Zachry No. 29 was spudded December 3, 1982 and a copy of the AFE is attached as required in Rule 6(a) (see attached form 9-331 dated 12-8-82).

The replacement well resulted from mechanical failure. The description of the nature and cause of the failure is described in paragraph 3 above along with the explanation of how it was determined. The history of the attempted repair work is attached. The projected well costs are shown on the attached AFE and the actual well costs are shown on the last line of column 10 of



State of New Mexico Energy and Minerals Department Oil Conservation Division Page 2

the attached drilling record. Since this well had to be squeezed off with cement to facilitate the fishing of the tubing and rods from the top of the packer set below the Gallup zone and above the Dakota zone, we evaluated the potential of recompletion in the Gallup zone as zero. Without squeezing the Gallup zone off to fish the tubing and rods from the hole we also jeopardized the Dakota zone in addition to the Gallup zone.

The Zachry No. 29 replacement well resulted in a well producing at a commercial rate.

Proof that the Gallup formation was plugged and abandoned is contained on Form 9-331 (Sundry Notices and Reports on Wells) and the replacement well was not completed until January 18, 1983 as proof of the requirements of Rule 6(d).

Union Texas Petroleum Corporation respectfully requests that this exemption be approved as soon as practical.

Very Truly Yours,

UNION TEXAS PETROLEUM CORPORATION

Rudy D. Motto

Area Operations Manager

RDM: svr

cc: Mr. Frank Chavez, Superintendent District III Office New Mexico Oil Conservation Division 1000 Rio Brazos Road Aztec, New Mexico 87410

> Gas Company of New Mexico P.O. Box 26400 Albuquerque, New Mexico 87125 Attn: Gas Supply Department

Mr. D. W. Pickels Mr. G. R. Johnson Mr. T. K. Woolley Mr. W. N. Hahne

## DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

(		Approve	d. 1 Ng. 42 <u>-</u> R	1424
5. LEASE	त्र हो है। इ.स.च्या	30	355	
SF 0807	24-A-=	<del>-</del>	- E	
6. IF INDIAN,	ALLOTTEE	OR TRI	BE NAME	
<u>.</u>	# = 5 7	Ę		
7. UNIT AGRI	EEMENT N	AME	-	
	4 TE 5	₹.	_ = = =	
8. FARM OR I	EASE NAM	E E		
Zachry		₹		
9. WELL NO.	5-5-	Ξ	3.7	
15 <b>-</b> E	<u> </u>	<u> </u>	7 7 7	
10. FIELD OR	WILDCAT N	AME		
· Wildcat	Gallup;	Bāsi	n Dako	ta
11. SEC., T., R	., M., OR B	LKAN	D SURVE	Y OR
AREA		Ų		
Sec. 33, T	-29N, R	-10W,	M.P	.M.
12. COUNTY O	R PARISH	13. S	TATE	
San Juan	<u> </u>	%e	w Mexi	СО
14. API NO.	_ = =	:	- 112	
15. ELEVATION	vs (show	DF,- K	B, AND	WD)
5633 R.	К.В.			
			<u> </u>	
EIVED				
- I V I!		3-		
NOTE Report	results of mu	Itiple co	noietion or	zone
3NOTE Report to	on Form 9-3	330.) -	<del>-</del>	
GICALI SU DVES		•		
TON, N 🖭		<u>=</u> .		•
		<u>-</u>		
	· · · ·			1
all pertinent de ectionally drilled to this work.)*	tails, and I, give sub	give pe surface	rtinent d locations	ates
מעם.	<u>-</u>	-		
R.K.B.	-7.	,		
01.		•	-	
OK. Spot	ted 10	gal.	sanc o	ם מ
ate of 3 b t with 2%	bl/Min.	at 3	UU P.S	· I ·
				nd
ut well in	with 4	00 P.	S.I.	
		:		

_	SUNDRY NUTICES AND REPURIS UN WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different							
reservoir. Use Form 9-331-C for such proposals.)						8.	FARM O	
1. oil		gas					Zachry	
well		gas well	$\mathbf{\nabla}$	other	. 1	0	WELL NO	

2. NAME OF OPERATOR Supron Energy Corporation 3. ADDRESS OF OPERATOR P.C. Box 808, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 1) AT SURFACE: 940 Ft./North; 1650 Ft./West line AT TOP PROD. INTERVAL: Same as above AT TOTAL DEPTH: Same as above

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly st including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertin
- Set Baker retrievable bridge plug at 5913 i
- 2. Ran 5-1/2" RTTS packer and set at 5830 ft.
- 3. Pressure tested plug to 2500 P.S.I. Test
- 4. Re-set packer at 4890 ft. and established a
- Mixed and pumped 150 sacks of class "B" cen 150 sacks of class "B" with 0.4% Halad 9. Standing pressure.
- Tagged dement at 5355 ft. and cleaned out to 5715 ft. with 4-3/4" bit. 6
- 7. Pressure tested casing to 2000 P.S.T. for 15 minutes, sheld OK.
- 8. Pulled retrievable bridge plug.
- 9. Milled on junk on top of packer.

Subsurface Safety Valve: Manu. and Type

10. Packer fell to 6404 ft.

TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL

PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON\*

(other) Abondoned Gallup

18. I hereby certify that the foregoing is true and correct

\_\_ TITLE Production Supt. DATE

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

SEP 0-3 19825

\*See Instructions on Reverse Side

FARMETCIO .

٠:\_

STATES

DEPARTMENT OF

230.70

.

40 38

GEOLOGICAL

THE INTERIOR

SURVEY

# Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and particularly with regard to local, area, or regiona regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

requirements. Consult loca Federal in accordance with be described Item 4: If there are no applicable State requirements, locations on Federal or Indian land should State or Federal office for specific instructions. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significants. If the same of the same of present of cement of cement plugs; much or other material placed below, between and about one same of parting of any casing, liner or tubing pulled and the depth to too of any last in the holds of parting of any casing, liner or tubing pulled and the depth to too of any last in the holds of parting of any casing, liner or tubing pulled and the depth to too of any last in the holds of parting of any casing, liner or tubing pulled and the depth to too of any last in the holds of parting of any casing, liner or tubing pulled and the depth to too of any last in the holds of parting of any casing, liner or tubing pulled and the depth to too of any last in the holds.

offices,

LEASE

.2

Ver

gal.

301000 ball sealers, Swabbed well Swabbed sand and 50 ball sealers. zone with, 48,000 lb. of 20-40 NCL from 6400 ft. to 5900 ft per bbl. of nitroren and 8al. 7-1/2% HCL and 700 SCE nitrogen per barrel and 50 GPO : 1976 O - 214-149 Dakota of 15% Shabbed well. 600 SGF 6400 ft. and spotted 500; gal. of the hole with the packer and treated /82. of 30 lb. cross-linked gelled 1% KCL vater. Svabbing and cleaning Dakota zone as of 8/1 conditioned for final inspection looking to approval of the abandonment 15% MCA acid and 7-1/2% NCA actd. gal. gal. Acidized with 1000 3000 packer at with 1000 with Set RTTS Carne out Acidized Acidired 13. 12. 14, 16.

#### UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

	.02	. ,	
	•		
SF	080724-A	-	

7. UNIT AGREEMENT NAME

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

CHINDRY	NOTICES	AND	<b>REPORTS</b>	ΩN	WFIIS
2011DU I	HULLO	שווח	NEL OU 12	UIT	TILLLO

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9-331-C for such proposals.)

1.	oil well	X)	gas well	X	other		
2.	NAM	E OF	OPERA	TOR		 	

Supron Energy Corporation

3. ADDRESS OF OPERATOR

P.O. Box 808, Farmington, New Mexico

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 940 ft./N; 1650 ft./W line AT TOP PROD. INTERVAL: Same as above AT TOTAL DEPTH: Same as above

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE. REPORT, OR OTHER DATA

8. FARM OR LEASE NAME Zachry 9. WELL NO. 15-E 10. FIELD OR WILDCAT NAME Wildcat Gallup; Basin Dakota 11. SEC., T., R., M., OR BLK. AND SURVEY OR **AREA** Sec. 33, T29N, R10W, N.M.P.M. 12. COUNTY OR PARISH 13. STATE San Juan ∺ New-Mexico 14. API NO.

15. ELEVATIONS (SHOW DF; KDB, AND WD) 5621 GL

REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE **CHANGE ZONES** ABANDON\* (other) Abandon Gallup Zone

SUBSEQUENT REPORT OF: RECEIVED MAY 28 1982 (NOTE: Report results of multiple completion or zone change on Form 9-330). U. S. GEOLOGICAL SURVEY

FARMINGTON, N. M.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This well was a Gallup-Dakota dual completion. The Dakota was flowing and the Gallup was being pumped. During a pump-changing operation, the Gallup tubing parted, leaving a bad fishing job. We will not be able to circulate the well in order to recover the junk on top of the packer with the Gallup perforations open. Therefore, we request permission to plug and abandon the Gallup zone and make the well a single Dakota completion. The Gallup zone will be abandoned according to the following procedures:

- 1) Set retrievable bridge plug at about 5900 ft.
- 2) Put about 10 gallons of sand on top of bridge plug.
- 3) Run packer and set at about 4900 ft.
- Squeeze Gallup perforations with about 250 sacks of cement.
- Drill out cement and pressure-test to 2000 P.S.I.

61	Cloan	innt	$\alpha f f$	nacker	and	D1177	nacker	(Over)
8.15	Ciedii	eat 4 (12)	. S. 1. Ita.	Pack Stu	anu	pari	packer.	(Over)

18. I hereby certify that the foregoing is true and correct

SIGNED A-CILIXII	1 E. Kalky	TITLE Production Supt.	DATE May 27,	1982
rkennetn	E. Roady		-	

۸	APP	R	0	V	E	D
d	DIDITIONS OF	APP	ROVA	L, IF	Αħ	Y:

(This space for Federal or State office use)

JUN 02 1982 JAMES F. SIMS DISTRICT ENGINEER

See Instructions on Reverse Side

กต์รฐกล

4, #800 Dilbio

MARKE HUMAGH F

ώρτ∵π<u>α</u>αυγ 15. 10. 10.

1 60 1 6 22 132 3

ELLE REPORTS

regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and for State are shown below or will be issued by, or may be obtained from, the local Federal and for State and either are shown below or will be issued by, or may be obtained from, the local Federal and for State and either are shown below or will be issued by, or may be obtained from, the local Federal and for State and Educations. General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and

90 Y

Instructions

accordance with Federal requirements. described in or Indian land should be Item 4: If there are no applicable State requirements, locations on Federal State or Federal office for specific instructions.

SAVOS CH

Consult loca

.\_:<u>\_</u>

: · ·

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and for State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

GPO : 1976 O - 214-149

Run single string of tubing to the Dakota zone.

Mr. John Keller on 5/26/82 were verbally approved by procedures above The

#### August 17, 1982

JUN 1 1 1984

1

RECEIVED

Mr. Tom Coers
District Vice President
P.O. Box 1899
Bloomfield, New Mexico 87413

Dear Sir:

I sent you a letter stating that we had P & A the Pierce "A" No. 2-E Gallup zone of that well. That well is still producing and has not been plugged.

The Zachry No. 15-E Gallup zone has been plugged and abandoned.

This well is located 990 feet from the North line and 1650 feet from the West line of Section 33, Township 33 North, Range 10 West, N.M.P.H. of San Juan County, New Mexico.

The tie in, meter, meter tube and building which you have installed may be removed at your convenience.

The Dakota zone will continue to produce as connected.

The Pierce "A" No. 2-E well is still producing from both the Gallup and Dakots zones.

UNION THANS PETROLIUM

Rudy D. Motto

Field Operations Manager

#### RDM:bjs

cc: Hr. Perry McFarland

Mr. Bruno Giovanini

Mr. Bob Large

Mr. Bryant Roundy

Mr. Derald Ferrari

Mr. Don Wells

Mr. Joe Stewart

FORM 755-091 11-76

fite.

## **GAS** COMPANY OF NEW MEXICO

August 12, 1982

Supron Energy Corporation P. O. Box 808 Farmington, N.M. 87401 Attn: Kenneth Roddy

Subject:

Zachry 15-E

Sta.#4957K8

(C)33-29N-10W

#### Gentlemen:

phone call

In accordance with our letter to you dated \*8-11-82, we have suspended the changing of charts and servicing of our equipment on the above named well effective

8-17-82

We will be pleased to reinstitute service on this well upon your notification that it is again economically capable of producing into our lines.

Very truly yours,

James R. Large

Dispatch Manager

/sw

cc: Mr. E. R. Corliss, Engineering

Mr. R. J. McCrary, Prorations

Mr. Mike Lambert, Gas Supply

Mr. Richard Thomas, Gas Supply

Ms. Nylene Dickson, Economic Analyses

Mr. Bryant Roundy, Kutz

Mr. Derald Ferrari, Kutz

File

You reported well P&A'd.

Form approved. Budget Bureau No. 42-R1425

# ŧ

, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		ITED STATES		verse side)		
	DEPARTME	NT OF THE IN	HERIOR		G. LEARE DENIGNATIO	N AND BERIAL NO.
_	GEO	OGICAL SURVE	Υ		SF 080724A	
APPLICATI	ON FOR PERMIT	TO DRILL, D	EEPEN, OR PLI	JG BACK	6. IF INDIAN, ALLOTT	EE OR TRIBE NAME.
1s. TTPE OF WORE						NAME:
	DRILL 🗵	DEEPEN [	j <b>PLU</b> C	BACK [	J DAIL AGENTALY	NAML
b. TIPE OF WELL. OIL. X	GAN -			MULTIPLE	b. FARM OR LEASE NA	AME
2. NAME OF OPERATOR	WELL OTHER		ZONE (A)	ZONI;	Zachry	
Union Texa	s Petroleum Corp	poration			9. WELL NO	•
3. ADDRESS OF OPERAT	ruk		RECE	VED	29	
P.O. Box 8	08, Farmington,	NM 87401	5 -		10. PIELD AND POOL,	OR WILDCAT
At MUTIBER 937	(Report location clearly a ft./North; 1785	nd in accordance with	any State requirements	°, 1982	Armenta Gall	
,,,,	200,00200, 2700		<u>-</u>		11. SEC., T., R., M., OR AND SURVEY OR A	
At proposed prod.	Same as abo	ve	U. S. GEOLOG	ICAL SURVEY	Sec. 33 729N	, RlOW, N.M.P.M.
14. DISTANCE IN MIL	ES AND DIRECTION FROM N	EAREST TOWN OR POST	OFFICE FARMINGT	011, N. M.	12. COUNTY OR PARISE	1 13. STATE
6-1/2 mile	s Southeast of E	loomfield, Ne	w Mexico		San Juan	New Mexico
15. DISTANCE FROM PI	OPOSED*		6. NO. OF ACRES IN LE		O THIS WELL	T MCW MCXICO
PROPERTY OR LEAD		855 ft.	2284.30	i	W SE 40.00	
18. DISTANCE FROM P			9. PROPOSED DEPTH	20. R	OTARY OR CABLE TOOLS	
OR APPLIED FOR, ON	THIS LEASE, FT.	120 ft.	<b>599</b> 5	R	otary	· · · · · · · · · · · · · · · · · · ·
	whether DF, RT, GR, etc.)				22. APPROX. DATE WO	
5620	Gr.				October 20,	1982
		PROPOSED CASING	AND CEMENTING P	ROGRAM		<del></del>
RIZE OF HOLE	RIZE OF CARING	WEIGHT PER FOOT		——-i——	QUANTITY OF CEME	
<u> 13-3/4"</u>	10-3/4" K-55	. 40.55	300 f		eu. ft. (Circu	
<u>9-7/8*</u> 6-3/4*	7-5/8" K-55 5-1/2" J-55	26.40 15.50	4650 f		cu. ft. (Top of	f the Ojo Alamo)
•	1	1	1	1	_	
					. using natural :	
					ately 240 cu. ft o 800 PSIG for l	
					rch base, permal	
				•	ing to T.D. with	*
					20 cu. ft. of 65	
						tely 640 cu. ft.
					ement. W.O.C.	Pressure test . of approximate
						. <i>OI apploximate</i> w 5-1/2" pipe to
					ely 142 <b>c</b> u. ft.	
						. Run new 2-3/8"
					l head. Run pum	p and rods.
	nit and tanks.				<u>-</u>	
	this well has p.	_		_	DOITEL. roductive zone and propose	d new Droductive
	o drill or deepen direction				ared and true vertical depth	
24	/				<del></del>	
3, 1	1 1/1/1	r.	ield Operation	ne Manage	DATE SEPTEM	no= 6 1002
Rudy D	Motto	TITLW		- nanaye	DATEGEPLEMI	7E1 . U <sub>1</sub> 1704
(This space for Fe	deral or State office use)					
PERMIT NO.		<del></del>	APPROVAL DATE		APPROVE	
					AS AMEND	ED
APPROYED BY	OVAL IF ANY	TITLE .			NOV AO TO	92
		(/.			1101,06,130	الله الله
	11.ED ( 16.	of a		į	FUAMES F. SIM	s
1	_)4%	116		1	DISTRICT ENGIN	EER

# WELL LOCATION AND ACREAGE DEDICAT 1 PLAT

att discourse must be form the outer harmdeless of the fination

			A11 611	IANCES MUSI M		outer bounder!	71 14 114 3	771100	···		<del></del>	
(1).010101	4 C DD9			.• \	Leon	CHRY					¥ел №. *29	•
UNIT U	Section	ROLEUM	Township			≥ude	Cow				27	
Unii Letter	300.00		-		ı	LO WEST		-	JUAN			
Actual Fastage Lace	Disposed We	1	29 N	ORTH		LU WEST		AIV	O DAIV		· · · · · · · · · · · · · · · · · · ·	
937	leet from		ORTH	line and	178	35	Irel from	ehe .	WEST		line	
Ground Level Elev.		ducing Form		11.10	Pool						led Acreages	
5620	G	ALLUP			A	rmenta				NE N	W 40.00	Acre
1. Outline the	- octeac	e dedicate	d to th	e subject w			il or har	hure	marks on t	the plat	below	
J. Outline the	. zerezb				<i>-</i> , -				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	<b>,</b>		
2. If more the	on one l	case is d	ledicate	d to the wel	l. outlir	e each and	identify	the c	wnership	thereof	(both as to	workin
interest and							•		•			
		•										
3. Il more than						ed to the we	ll, have	the i	nterests o	f all on	ners been o	consoli
dated by co	mmuniti	tation, un	itization	, force-pooli	ing. etc?							
□ v (	⊠ N₀	16	war ia *	yes;" type o	.f. sansal	idatia.						
Yes [	<b>△</b> 1/10	) ans	MCI IP	yes, type o	or Conso							
If answer is	"no;" ]	ist the ow	ners an	d tract desc	riptions	which have	actually	bee	n consolid	ated. (U	se reverse	side o
this form if		_					<del>.</del>			<del></del>		
No allowable	e will be	assigned	to the w	ell until all	interes	s have been	n consoli	idate	d (by com	munitiz	ation, uniti	zation
forced-poolis	ng, or oth	erwise) or	until a	non-standar	d unit, c	liminating s	uch inter	rests	, has been	approv	ed by the C	ommis
sion.												
						1		71	-	CERTI	FICATION	
}	il	Ĺ	J.			ļ				<b>U</b>		
		7				1		-11	I hereby o	ertily the	t the informat	ion con
	ı	$\mathcal{G}$	- 1			•			_	_	e and complet	
	1	1	1	•		!		-11	//		ge and belitt/	/
<i>1785</i>		<b>-</b> �		•				11	0		M-H	
	1		H			l		14	Name	AVI	Ilin.	
-· <del></del>	- t		-					-11	Rudy D.	Motito		
	1		J		·			1	Position			
	1		• 1		- 1				Field O	perati	ons Manag	ger.
•	1		- 1		i	•		11	Сопралу			
	. !		- 1		:				Union To	exas P	etroleum	Corp
									Date			
	,			33	J			11	August	t_10,	1982	
								11		THE PARTY OF THE P	A STATE OF THE PARTY OF THE PAR	
•	i		j		1				I herely d	35/0111	E 16/1/F FA ON I	ocotion
	Í		[		,				H.O	bia bioi -	os pione C	m field
	ı		į.		,	•		$\Pi$	note de	, .		lme er
	l l		1		1			11	under	JY( upervisip)	Lond thin至	N Lome
•	1.		1		1			11	المرقية	d correct	المناه المناه	ol my
-	1				Ì				know horge	ey Kabalik	EXICH.	1
	- +		†		7			1	VV	MESP	IFFILER	
	1	•			i			11	· · · · · · · · · · · · · · · · · · ·	A STATE	LILET.	
	i		1					"	oto Suveyed		000	
	i		1		!			11:	July	30. I		
	Ī		l		1	•		1 1	nd/or Land S			
	1		· 1		1			11	James	P. Le	ese P	
						<del></del>			× on		1. De	عجو
			==:=				12000	1 I		•		
330 000 00	1970 ##80	23	0 2640	3000	1900	1000	.00 6		1463			-

Ferm 9-331 Dec. 1973

# UNITEL JTATES

	Form A	pproved	ı	
	& _ Budget	Bureau	No. 42-R142	4
LEASE	2017 2017 2017	8	200	_

DEPARTMENT OF THE INTERIOR	SF 080724-A 2 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1 all ger	Zachry
well well other	9. WELL NO.
2. NAME OF OPERATOR	29
Union Texas Petroleum Corporation	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR P.O. Box 808, Farmington, New Mexico 87499	Armenta Gallup  11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA HOUSE
below.)	Sec. 33. T29N R10W NEW P.M.
AT SURFACE: 937 ft./N; 1785 ft./W line AT TOP PROD. INTERVAL: Same as above	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH: Same as above	San Juan 2 5 New Hexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO. 현목과 한 기원으로 한 대한
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
DECUECT FOR ADDROVAL TO: CURSTOURNE DEPORT OF	5632 R.K.B.
TEST WATER SHUT-OFF   REQUEST FOR APPROVAL TO:  SUBSEQUENT-REPORT OF:  RECEI	VFD
FRACTURE TREAT	
SHOOT OR ACIDIZE DEC. 10	1982 NOTE: Report results of multiple completion or zone change on Form 9-330.)
PULL OR ALTER CASING	"(NOTE: Report results of multiple completion or zone change on Form 9–330.)
MULTIPLE COMPLETE U. S. GEOLOGIC	CAL SURVEY
CHANGE ZONES	
(other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinent	rectionally drilled, give subsurface locations and
1. Spudded 14-3/4" surface hole at 7:30 P.M. 12/	3/82.
2. Drilled 14-3/4" surface hole to 316 ft. R.K.B	
3. Ran 7 joints of 10-3/4", 40.50#, H-40 casing	
4. Cemented with 295 cu. ft. of class "B" with 2 12/4/82. Cement circulated to the surface.	* CaCl <sub>2</sub> . Plug down at 6:30 A.M.
5. Waited on cement for 12 hours.	
	-
Subsurface Safety Valve: Manu. and Type	
18. I hereby certify that the foregoing is true and correct	
Kenneth E. Roday	t. DATE <u>December 8, 1982</u>
/ (This space for Federal or State offic	e use)
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY.	DATE
	AGGEPTED FOR RECORD
*See Instructions on Reverse Sig	DEC 15 1482

OPERATOR

FARMINGTON DISTRICT SMM BY \_\_\_\_

	<b>.</b>				• • • • • • • • • • • • • • • • • • •	MLL.	8/2/1982		
UNION TEXÁS PE	COMPANY NAME AND NO. IF OTHER THAN UTPC) TO TEXAS PETROLEUM (X) UNICON PRODUCING COMPANY								
GINATING OFFICE Western Divis	ion		pment Drilling		L OR DEVEL)	AFE NO. 4-8803	SUP.No		
8/15/1982	EST. FINIS 9/06/19		TOTAL COST s 530,500	UTP INT. %.	530,500	OPERATING PART	NER'S AFE No		
JECT AND LOCATION	(USE BLOC)	S FOR DESIR	ED COMPUTER PRINT	OUT NAME	EAP PROJECT C	ATEGORY N	ON-ETA		
A O H R Y : ec. 33-29N-10W utz Canyon	EXPANSION  COST SAV. COST								
an Juan County,	New Mex	ico			IMPLEMENTS AN AR PF	HOR APPROVAL	]		
OPOSAL.									
It is pro		o drill a	5995' develop	ment Gallu	p well in the Ku	tz Canyon ar	ea of		

The proposed location is south and east, and within a two mile radius of six Gallup producers. Average initial potentials for these six wells is 75 BOPD & 300 MCFD, with all si having been completed since September, 1981. Recent contract negotiations have resulted in Southern Union releasing their right of first refusal on the casing head gas for the Gallup in this area. Therefore, it will be possible to produce the Gallup completions at their maximum rate. Reserves of 50 MBO and 200 MMCFG have been assigned the Gallup for economic analysis.

All permits required from governmental agencies will be obtained prior to performing this work and proper precautions will be taken to avoid damage to the environment.

PROVAL DATE P	ARTNERS (*OPERATOR)	, IN°	TEREST (%)	REUPPLEMENTAL AFE	USEONLY
į		•	1. CUM. AMOU PREVIOUSL	NT TOTAL COS	T UTP COST
į			2. THIS SUPPLE	EMENT	
} 1			TOTAL (1) +	(2)	
į			(2) ÷ (3	1)	*
	<b>第二年</b> 第二十二年	ESTIMA	ATED COST		
EW DRILLING WELLS AND/OR CAPITAL WORKOVERS ONLY	PRODUCTIVE	DRY HOLE	EXPENSE WORKOVERS OR OTHER PROJECTS	TOTAL COST	UTP'S COST
NGIBLE EQUIPMENT	211,400	73,200	CAPITAL BUDGET		
TANGIBLE COSTS	319,100	178,500	OPERATING EXPENSE		
TAL COST	530,500	251,700	OTHER		
UTP'S COST	530,500	251,700	TOTAL	•	
A A A A CCOUNT	CHARGES STATES	STANGENS .	OFENING DEPARTMENT	EXPL MOR. BATE	المرابية
3310 XX 433	3137488034	141 / 1 ( )	WKL == 8/25/82	( Ting 6 12 85	MAYSIZIN
5091111		Servicion Contre	9/1/2 am 8/25/62	GMW/ 11	MGR/DMECTOR ' GA'
WAST TO COMPONE	G CONTROL	13/12	DATE	. 1/2/24 8/248	۷
YES NO	40360	ADWIN, DATE		V.P.	VANALAM G:
IDGET STATUS			DATE	1 RDi 4/5/82	$N$ $\lesssim i$ $j$
moco & was weenno	_	TREAS. DATE	BATE	VPARM DATE UT	JEU T 1942
2777. SUTE LOS (C.	ON. DATE LEASE SATE	5-41/9/267	DATE		
<u></u>	-				

\* ZACHRY 15E ID: 3637 \* AFE : **‡** UNDESIGNATED \* \* KUTZ CANYON EAST OPERATED \* \* SAN JUAN , NM 

AAPG TYPE : DW SPUD DATE : 1/28/1981

WORK-OVER START DATE: 4/23/1982

OPERATOR : UNION TEXAS

CONTRACTOR : AZTEC WELLSERV

\* CONTRACTOR:

K.B. ELEV : 0

GROUND ELEV: 0

CASING HD FLANGE ELEV: 0

LOCATION : 940 FNL, 1605 FWL, SEC 33,29N-R10W

EST. COST : \$ 428700

ACTUAL COST : \$ 464974

PROPOSED (ACTUAL) T.D.: 6600

OBJ. FORM.: GALLUP

PLUG BACK TOTAL DEPTH: 0

API WELL #: 24459

COMPLETION DATE : 5/29/1981

WORK-OVER COMPLETION DATE : 1/ 1/1800

#### OWNERS

	AFTER F	AFTER PAYOUT %								
OWNER	WORKING	NET	WORKING	NET	ROYALTY	OVERRIDE	WORKING	OVERRIDE		
UNICON	100.0000	82.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000

#### MUD PROPERTIES

HPHT % % % CONCENTRATIONS (PPM)

DATE WEIGHT VIS PV YP W.L. PH PF OIL SAND SOLID CAKE GEL CHLORIDE CALCIUM SALT TYPE MUD

BIT RECORD

BIT SERIAL JET SIZE RPM BIT WEIGHT DRILLED CONDITIONS DEPTH
DATE NO. NO. SIZE TYPE 1 2 3 1 2 1 2 FEET HOURS T B GAUGE IN HOLE

#### HYDRAULICS

------

	PUMP	STROKE		LINER		ANNULAR VELOCITIES	JET	SURF.PRESS	BIT HYD
DATE	NO.	LENGTH	SPH	SIZE	GPM	DRILL PIPE COLLAR	VEL	(PSI)	H.P.

#### DEVIATION RECORD

------

SURVEY DATE	DEPTH	DEPTH	(FROM VERT)		1	2	HTD	LOCATION	
		VERT.	DEVIATION	DIRECTION	COORDI	NATES		BOTTOM HOLE	

CASING CEMENT
----SIZE WEIGHT GRADE JOINT COND TOP BOTTOM

0 6545

5 1/2 15.50 K-55 ST&C

TUBING RECORD

SIZE WGHT GRADE JOINT TOP BOTTH REMARK PACKER DEPTH PACKER REMARK

# WELL TEST RECORD

DATE LEN. OIL GAS WATER PROD. TUBNG CASNG SITP CHK PUNF \*STROKE\* FLUID PUMP INPUT API
OF TEST HRS. BBL MCF BBL METH. PRESS PRESS PSI SIZ SIZE LEN /MIN LEVEL DEPTH GAS GRAV REMARKS

DRILL STEM TEST

#### DRILLING RECORD

-----

													\$\$\$	CUMM	ULATIV	E AVERA	GE \$\$\$				
																		FORMATION			
DATE					COST										FOOT		DAY	DRILLED			
**** HI																					
5/27/82			0.0		0	0.0	0	0	30	0	0	0	0	0	0	0	0				
5/28/82	6545		0.0		0	0.0	0	0		0	0	0	0	0	0	0	0				
**** MI	SSING																				
6/19/82	6545	0	0.0	0	236131	0.0	0	0	53	0	0	236131	0	0	0	0	4455				
6/20/82	6545	0	0.0	0	4154	0.0	0	0	54	0	0	240285	0	0	0	0	4449				
**** MI	SSING	DATA	****																		
6/22/82	6545	0	0.0	0	4660	0.0	0	0	56	0	0	244945	0	0	0	0	4374				
6/23/82	2 6545	0	0.0	0	4380	0.0	0	0	57	0	0	249325	0	0	0	0	4374				
6/24/82	6545	0	0.0	0	4500	0.0	0	0	58	0	0	253825	0	0	0	0	4376				
6/25/82	2 6545	0	0.0	0	4484	0.0	0	0	59	0	0	258309	0	0	0	0	4378				
6/26/82	6545	0	0.0	0	4484	0.0	0	0	60	0	0	262793	0	0	0	0	4379				
6/27/82	2 6545	0	0.0	0	4918	0.0	0	0	61	0	0	267711	0	0	0	0	4388				
**** H	ISSING	DATA	****																		
6/29/82			0.0	0		0.0		0	63	0	0	272751		0	0	0	4329				
6/30/82	2 6545	5 0	0.0	0		0.0		0		0	0	278161		0	0	0					
7/ 1/82			0.0	0	4892	0.0	0	0	65	0	0	283053		0	0	0					
7/ 2/8			0.0			0.0		0			0	288405		0	0	0					
7/ 3/82			0.0	0		0.0		0		0	0	293872			-	0					
7/ 4/8	2 6545	5 0	0.0	0		0.0		0		0	0	298303		0	0	0					
7/ 5/82			0.0	0	0	0.0	0	0		0	0	298303		_	-	0					
7/ 6/8			0.0		0	0.0	0	0	70	0	0	298303	0	0	0	0	4261				
**** RE					_		_	_			_		_	_	_						
7/ 6/8	2 6268	3 0	0.0	0	0	0.0	0	0	70	0	0	298303	0	0	0	0	4261				7/ 7/82
****		TTV	/• _1	1 570	D112A :	_ WAT	N / D (	20/75													
ZWRITE (						U NAT	R+ (F)	L 2003	31												
%0utput 50555		MIGGE	i COO	2 <b>8</b> 61	1		7/0/	מי גם	71	Λ Λ (	۸ ۸	4884	۸۸	Λ	۸	70	2	6 308211	Λ	0 ****	
ZWRITE		TTV	/+ -+	1570	D1170 ÷					V V+(	, v	TOOT	V+V	V	٧	12	2	0 300211	U	V *****	
ZOutput						. 13 THE	R+ (F)	L 200J	. ,												
51369		W1(16)	1 400	3867	•																
7/ 9/8			0.0	٥	ARRA	0.0	۸	٥	73	2	4	313095	0	0	****	52183	4288				
7/10/8			0.0					0				318302				53050					
7/11/8			0.0			0.0		Õ	75	2	6	323483			****		4313				
**** H					0101		٠	v	, ,	_	•	020 100	٠	•	*****	VW/41	1010				
7/13/8			0.0		5377	0.0	0	0	77	2	6	328860	0	0	****	54810	4270				
7/14/8			0.0					0	78	2	6	334004				55667	4282				
7/15/8			0.0					Õ	79	2	6	339488			****		4297				
7/16/8			0.0					Ō	80	2	6	344672				57445	4308				
7/17/8								ō	81	2	6	350027				58338	4321				
7/18/8			0.0					0	82		6	355127				59188	4330				
7/19/8			0.0		_			0	83	2	6	355127				59188	4278				
7/20/8			0.0					0	84	2		360327				60055	4289				
7/21/83			0.0			0.0		0	85	2	A	365527				60921	4300				

7/23/82	6545	0	0.0	0	4267	0.0	0	0	87	2	6	374994	0	0 **** 62499	4310
7/24/82	0	0	0.0	0	3952	0.0	0	0	88	2	6	378946	0	0 **** 63158	4306
7/25/82	. 0	- 0	0.0	0	2349	0.0	0	0	89	2	6	381295	0	0 **** 63549	4284
**** MIS	SING D	r ata	****												
7/27/82	0	0	0.0	0	4244	0.0	0	0	91	2	6	385539	0	0 **** 64257	4236

#### DRILLING RECORD

\$\$\$ CUMMULATIVE AVERAGE \$\$\$

													***	CUNIT	REHITA	E HAEVE	105 333	
	TOTAL	DRIL	LED		DAILY	MUD	MUD	MUD	****	CUMM	ULATIVE	*****	FT/	FT/	COST/	COST/	COST/	FORMATION
DATE	DEPTH	FEET	HRS.	ROP	COST	WT	VIS	COST	DAY	FEET	HRS.	COST	HR.	DAY	FOOT	HOUR	DAY	DRILLED
7 <b>/28/8</b> 2		0	0.0	0	2500	0.0	0	0	92	2	6	388039	0	0	****	64673	4217	
7/29/82	6545	0	0.0	0	2500	0.0	0	0	93	2	6	390539	0	0	****	65090	4199	
7/30/82	6600	0	0.0	0	7779	0.0	0	0	94	2	6	398318	0	0	****	66386	4237	
7/31/82	6545	0	0.0	0	2600	0.0	0	0	95	2	6	400918	0	0	****	66820	4220	
8/ 1/82	6545	0	0.0	0	2600	0.0	0	0	96	2	6	403518	0	0	****	67253	4203	
8/ 2/82	6600	0	0.0	0	0	0.0	0	0	97	2	6	403518	0	0	****	67253	4159	
8/ 3/82	6600	0	0.0	0	2200	0.0	0	0	98	2	6	405718	0	0	****	67620	4139	
8/ 4/82	6600	0	0.0	0	2600	0.0	0	0	99	2	6	408318	0	0	****	68053	4124	
8/ 5/82	6600	0	0.0	0	2600	0.0	0	0	100	2	6	410918	0	0	****	68486	4109	
8/ 6/82	6600	0	0.0	0	14500	0.0	0	0	101	2	6	425418	0	0	****	70903	4212	
8/ 7/82	6600	0	0.0	0	2300	0.0	0	0	102	2	6	427718	0	0	****	71286	4193	
8/ 8/82	6600	0	0.0	0	2300	0.0	0	0	103	2		430018	0	0	****	71670	4174	
8/ 9/82	6600	0			0	0.0	0	0	104	2	6	430018	0	0	****	71670	4134	
8/10/82		0	0.0	0	2300	0.0	0	0	105	2	6	432318	0	0	****	72053	4117	
8/11/82		0	0.0		2600			0	106	2	6	434918				72486	4103	
8/12/82					1856			0	107	2		436774		0	****	72796	4082	
8/13/82		0	0.0		2800			0	108	2		439574				73262	4070	
8/14/82						0.0	0	0	109	2		446174		0	****	74362	4093	
*** REP	EATED I	RECOR	D ***	*														
8/14/82	6600	0	0.0	0	2500	0.0	0	0	109	2	6	448674	0	0	****	74779	4116	
8/15/82	6600	0	0.0	0	2500	0.0	0	٥	110	2	6	451174	0	0	****	75196	4101	
*** REP	EATED !	RECOR																
8/15/82	6600	0	0.0	. 0	2500	0.0	0	0	110	2	6	453674	0	0	****	75612	4124	
8/16/82	6600	0			0			0	111	2		453674	0	0	11111	75612	4087	
8/17/82					25 <b>0</b> 0			0		2		456174				76029	4072	
8/18/82					2500			0	113	2	6	458674	0	0	****	76446	4059	
8/19/82					2500			0		2	6	461174				76862	4045	
8/20/82						0.0		0		2		463274				77212	4028	
8/21/82			0.0			0.0		0		2		464974				77496	4008	
**** MI							-	•		_	-		•	•		, <b>.</b>		
8/24/82			0.0		0	0.0	0	0	119	2	6	464974	0	0	****	77496	3907	
		•		-	_	•	-	•		-	-		•	•				

#### REMARKS

#### \*\*\*\*\*\*\* 4/20/1982 \*\*\*\*\*\*\*

\* RIGGED UP AZTEC WELL SERVICE RIG \$89 TO PULL RODS & CHANGE OUT PUMP.
RU AZTEC WELL SERV RIG 89 TO PULL RODS & CHANGE OUT PUMP. PULLED
20,000 PSI. RODS PARAFFINED OFF. IDOT OILED ANNULUS W/40 BBL TO
FREE RODS. WORKED RODS TO FREE THEM. PUT 35 BBL HORE OIL DOWN
ANNULUS & RODS SEEMED FREE. PULLED 18,000 PSI ON RODS, BUT DID NOT
COME LOOSE. PUMPED HOT OIL IN TBG TO SEE IF PUMP WAS UNSEATED & IF
SO TO FREE UP RODS. PRESS UP TO 600 PSI. PRESS HELD. DECIDED TO
STRIP WELL. BACKED OFF ON RODS. PULLED 4 RODS. CALLED WIRELINE
SERVICE TO SET CHOKE IN DAKOTA STRING. SET CHOKE AT 1000'. BLEW
DOWN, PULLED WELLHEAD & PUT ON BOP. SDON.

#### \*\*\*\*\*\*\* 4/21/1982 \*\*\*\*\*\*\*\*

\* STRIPPING RODS.

STRIPPING RODS. 37 JTS 2-1/16° OUT OF HOLE & BACKING OFF ON RODS. TBG JUMPED, SUB PARTED. PULLED 2 JTS TBG. TOTAL 39 JTS 2-1/16° & 60 RODS OUT OF HOLE. SHUT DOWN AND PREPARED TO FISH TUBING SUB RODS. USED 12 BBLS OIL TO KEEP WELL DEAD.

#### \*\*\*\*\*\*\* 4/22/1982 \*\*\*\*\*\*\*

- \* REMOVED BLOWOUT PREVENTOR. PUT ON WELLHEAD TO PULL CHOKE FROM LONG
- \* STRING & SET BLANKING PLUG IN F NIPPLE. COULD NOT GET PLUG TO SET &
  - COULD NOT RETRIEVE IT. SHUT DOWN OVERNIGHT.

    REMOVED BOP. PUT ON WELLHEAD TO PULL CHOKE FROM LONG STRING & SET
    BLANKING PLUG IN F NIPPLE. COULD NOT GET PLUG TO SET & COULD NOT
    RETRIEVE IT. SET BAKER PLUG IN SLIDING SLEEVE & BLEW DOWN LONG STRING.
    PULLED WELLHEAD. COLDN'T UNSEAT DONUT. SDON. PUT WELLHEAD BACK ON.

#### \*\*\*\*\*\*\* 4/23/1982 \*\*\*\*\*\*\*

- \* REMOVED WELLHEAD. PULLED 42000 PSI ON LONG STRING. TENSION ON LONG
- \* STRING MADE IT IMPOSSIBLE TO REMOVE DONUT. CALLED HOMCO TO CUT LONG
- \* STRING. RU FISHING TOOLS TO FISH TUBING. WENT IN & GOT FISH AT
- \* AT 1776'. SHUT DOWN OVERNIGHT,
  REMOVED WELLHEAD. PULLED 42000 PSI ON LONG STRING. TENSION ON LONG
  STRING MADE IT IMPOSSIBLE TO REMOVE DONUT. CALLED HONCO TO CUT LONG
  STRING. PLANNED TO MAKE CUT AT 6000 BUT COULD ONLY GET TO 4564. LOAD
  TBG W/FLUID & CUT OFF AT 4564'. PULLED 4564 2-1/16" & STOOD IN
  DERRICK. DOTCO RU FISHING TOOLS TO FISH 2-1/16" TBG. WENT IN & GOT
  FISH AT 1776. PULLED 40000 PSI & DROPPED TO 24000 PSI. SDON.

#### \*\*\*\*\*\*\* 4/24/1982 \*\*\*\*\*\*\*

- \* PULLED OUT OF HOLE WITH FISH. LAYED DOWN 73 JTS TUBING. RIGGED UP
- \* TO GO IN TO GET RODS. SHUT DOWN OVERNIGHT.

  POH W/FISH. LD 73 JTS 2-1/16 TBG. NO RODS. RU TO GO IN TO GET

  RODS. GOT ON FISH & PULLED 32 RODS. WENT BACK IN & PULLED 16 RODS.

  SDON. PUMPED 57 BBLS OIL TO KILL WELL.

#### REMARKS

#### \*\*\*\*\*\*\*\* 4/26/1982 \*\*\*\*\*\*\*

- \* WENT IN HOLE WITH FISHING TOOL FOR RODS. PULLED 33 RODS & A PIECE.
- \* BODY BREAK. RIGGED UP FISHING TOOL TO CATCH TUBING. WENT IN HOLE
- **≭** BUT COULD NOT GET ON TUBING TO MUCH ROD ABOVE TUBING. SHUT DOWN
- \* OVERNIGHT.

\*\*\*\*\*\*\* 4/24/1982 \*\*\*\*\*\*\* (CONTINUED)

WIH W/FISHING TOOL FOR RODS. PULLED 33 RODS & A PIECE. BODY BREAK. RU FISHING TOOL TO CATCH TBG. WIH HOLE BUT COULDN'T GET ON TBG TO MUCH ROD ABOVE TBG. CAME OUT & CHANGED TOOLS TO GO IN & SWALLOW RODS & TRY TO GET ON TBG. SDON W/66 JTS 2-1/16" & APPROX 100 RODS IN HOLE. FISHING AT 4061' W/OVERSHOT.

#### \*\*\*\*\*\*\* 4/28/1982 \*\*\*\*\*\*\*\*

- \* TRIPPED OUT OF HOLE WITH WORK STRING & FISHING TOOLS. HAD SHORT
- \* COILED PIECE OF 8-5/8° ROD. TRIPPED BACK IN HOLE W/SAME FISHING
- \* TOOL. TAGGED TOP OF FISH AT 4043'. COULD NOT GET ON FISH. TRIPPED
- \* OUT OF HOLE. RAN IN HOLE W/IMPRESSION BLOCK, TRIPPED OUT WITH
- \* BLOCK & SHUT DOWN OVERNIGHT.

  TOOH W/WORK STRING & FISHING TOOLS. HAD SHORT COILED PIECE OF 8-5/8°

  ROD. TRIPPED BACK IN HOLE W/SAME FISHING TOOL. TAGGED TOP OF FISH

  AT 4043'. COULD NOT GET ON FISH. TOH, RIH W/IMPRESSION BLOCK. TOH

  W/BLOCK & SDON.

#### \*\*\*\*\*\*\*\*\* 4/29/1982 \*\*\*\*\*\*\*\*

- \* TRIPPED IN HOLE W/3 STANDS DRILL COLLARS, ACCELERATOR, & WORKING
- \* STRING. TAGGED FISH AT 4045'. TRIPPED OUT OF HOLE, NO FISH.

  TIH W/3-5/16' BOX TAP W/JARS, 3 STDS DC, ACCELERATOR, & WORKING

  STRING. TAGGED FISH AT 4045'. TOH, NO FISH. PUT ON ROTARY SHOE IN

  PLACE OF BOX TAP. TIH TO TRY TO MILL FISHING NECK ON FISH. GAINED

  2' HOLE. TOH, REPLACED ROTARY SHOE WITH QULO SOCKET W/7 JTS 2-3/8'

  SHOVE SOCKET IN WORK STRING. TIH & TRIED TO GET ON FISH. DID NOT

  SEEM TO PU ANY WI. SDON.

#### \*\*\*\*\*\*\* 4/30/1982 \*\*\*\*\*\*\*

- \* PUMPED 35 BBLS OIL IN TO KILL WELL. PULL OUT OF HOLE WITH NO FISH.
- \* LAYED DOWN CLULOW SOCKET & DRILL COLLARS. PICK UP BOX TAP, WENT IN
- \* SET DOWN ON FISH & TURNED TO PICK UP ON FISH. PULL OUT OF HOLE W/TAP
- \* RECOVERED SHORT PIECE BALLED ROD. LAYED DOWN SOCKET. PICK UP ROTARY
- \* SHOE 2/7' PIPE PUP & TRIPPED IN HOLE. TAGGED FISH AT 4050'. MILLED
- \* ON FISH. SHUT DOWN OVERNIGHT.

PMP 35 BBL OIL IN TO KILL WELL. POH W/NO FISH. LD CLULOW SOCKET & DC. PU BOX TAP, WENT IN, SET DOWN ON FISH & TURNED TO PU ON FISH. POH W/TAP. REC SHORT PIECE BALLED ROD. LD SOCKET. PU ROTARY SHOE W/7' PIPE PUP & TIH. TAGGED FISH 4050'. MILLED ON FISH. SDON.

#### \*\*\*\*\*\*\* 5/ 1/1982 \*\*\*\*\*\*\*

\* PULL OUT OF HOLE WITH ROTARY SHOE. HAD PIECES OF COILED ROD W/BOX.

#### REMARKS

-----

#### \*\*\*\*\*\*\* 5/ 1/1982 \*\*\*\*\*\*\* (CONTINUED)

\* TRIP IN HOLE & START MILLING OVER. MADE NO HOLE.
POH W/ROTARY SHOE. HAD PIECES OF COILED ROD W/BOX. TOTAL RODS OUT
132 + PIECE. LD TOOLS. PU OVERSHOT W/GRAPPLE. TIH, TAGGED FISH,
POH, NO FISH. LDRAPPLE. PU ROTARY SHOE & PIPE PUP. TIH & START
MILLING OVER. MILLED 3 HRS. MADE NO HOLE. SDON.

#### \*\*\*\*\*\*\* 5/ 2/1982 \*\*\*\*\*\*\*

- \* RAN MAGNET ON SAND LINE. CAUGH FISH ON 3 RUNS, 4TH NO FISH. PICKED
- UP CENTER SPEAR. TRIP IN, CAUGHT FISH. POH W/ROTARY SHOE. NO FISH. LD TOOL. RAN MAGNET ON SAND LINE. 3 RUNS EACH CAUGHT FISH. 4TH RUN, NO FISH. ROD PIECES OUT 23°. PU CENTER SPEAR. TIH, CAUGHT FISH. PULLED 3000 PSI DVER WT FOR 12' 1 LOST WEIGHT. TOOH. HAD 24' COILED ROD. TOP OF FISH 4062'. SDON.

#### \*\*\*\*\*\*\* 5/ 3/1982 \*\*\*\*\*\*\*\*

\* SHUT DOWN FOR SUNDAY. SD FOR SUNDAY.

#### \*\*\*\*\*\*\*\* 5/ 4/1982 \*\*\*\*\*\*\*

- # FISHING FOR PRODUCTION STRINGS & RODS. RECOVERED 1 COILED ROD.
- \* SHUT DOWN OVERNIGHT.

PU FISHING TOOLS, RIH, CAUGHT FISH, PULLED 7000# OVERWEIGHT, LOST NT POOH, CAUGHT 1 COILED ROD, CHANGE OUT TOOLS, RIH, POOH, NO FISH, CHANGED TOOLS, RIH, POOH, NO FISH, SDON.

#### \*\*\*\*\*\*\* 5/ 5/1982 \*\*\*\*\*\*\*

- \* FISHING FOR PRODUCTION STRINGS. RECOVERED 5' OF 1/2 ROD, NOW
- \* MILLING OVER. SHUT DOWN OVERNIGHT.

  PUMPED 25 BBL OIL TO KILL WELL, RIH W/CENTER SPEAR LATCH TOOL, CAUGHT
  FISH, PULLED 12000\* OVERWEIGHT, LOST WEIGHT. POOH, REC 5'-1/2 ROD
  MADE TRIP W/SAME TOOL, NO REC. LD TOOL, PU ROTARY SHOE, RIH & MILLED
  10'. SDON.

#### \*\*\*\*\*\*\* 5/ 6/1982 \*\*\*\*\*\*\*

- \* FISHING FOR PRODUCTION STRINGS, NO RECOVERY. SHUT DOWN TO PLAN
- \* FUTURE WORK.

POOH W/ROTARY SHOE, NO RECOVERY. SD TO PLAN FUTURE WORK.

#### \*\*\*\*\*\*\* 5/ 7/1982 \*\*\*\*\*\*\*\*

- \* FISHING FOR PRODUCTION STRINGS. RECOVERED APPROX 1 ROD. SHUT DOWN
- \* OVERNIGHT.

PU ROTARY SHOE, 2 JTS WO PIPE, DC, & JARS. RIH, TAG FISH @ 4074', MILLED 5 HRS MADE 59', POOH, REC APPROX 1 ROD TOP OF FISH 4133, SDON.

#### \*\*\*\*\*\*\* 5/ 8/1982 \*\*\*\*\*\*\*

\* FISHING FOR PRODUCTION STRINGS.
RIH W/SAME FISHING STRING, TRIP TO CHANGE SHOE & GRAPPLE, TRIP, NO

#### REMARKS

#### \*\*\*\*\*\* 5/ 8/1982 \*\*\*\*\*\*\* (CONTINUED)

RECOVERY. CHANGE TO CTR SPEAR, TRIP W/NO REC. RIH W/WASHPIPE, DRILL 2 HR, NO REC, SDON.

#### \*\*\*\*\*\*\* 5/ 9/1982 \*\*\*\*\*\*\*

- \* FISHING FOR PRODUCTION STRINGS, RECOVER 1 JT TUBING & 6 RODS. SHUT
- \* DOWN OVERNIGHT.

RIH W/NEW ROTARY SHOE, MILL 1-1/2 HR, MADE 67', POOH, REC PCS OF ROD, LD PIPE & RUN MAGNET, NO REC. RIH W/2-5/16" GRAPPLE & LIP GUIDE, TAG FISH @ 4138, PULL 26000# OVER WT, TRIP JARS, LOST WT. POOH & REC 1 JT 2-1/16 TBG & 6 RODS. TOP OF FISH 4170. SDON.

#### \*\*\*\*\*\*\*\* 5/10/1982 \*\*\*\*\*\*\*

\* SHUT DOWN FOR SUNDAY. SD FOR SUNDAY.

#### \*\*\*\*\*\*\*\*\* 5/11/1982 \*\*\*\*\*\*\*\*

FISHING FOR PRODUCTION STRINGS, RECOVER 13 JTS 2-1/16 TBG W/RODS. RIH W/FISHING STRING, CAUGHT FISH @ 4170, PULLED % JARRED ON FISH 8 HR. POOH. REC 13 JTS 2-1/16 TBG W/RODS.

#### \*\*\*\*\*\*\*\* 5/12/1982 \*\*\*\*\*\*\*

- \* FISHING FOR PRODUCTION STRINGS. RECOVER 52 JTS 2-1/16' TBG W/RODS
- AND PUMP. MILLING OVER DAKOTA STRING AT 4608. SHUT DOWN OVERNIGHT.

  POOH & LD 52 JTS 2-1/16" TBG W/RODS & PUMP. RIH W/OVERSHOT & GRAPPLE
  ON 2-3/8" TBG. TAG FISH @ 4572, COULD NOT GET OVER. POOH & PU WASHPIPE, RIH, TAGGED JUNK & MILLED OVER TO 4608. SDON.

#### \*\*\*\*\*\*\* 5/13/1982 \*\*\*\*\*\*\*\*

- \* FISHING PRODUCTION STRING, RECOVER 29 JTS 2-1/16 TUBING. SHUT DOWN
- \* OVERNIGHT.

TOOH W/WORK STRING & TOOLS. NO JUNK REC. TIH W/GRAPPLE & 2-3/8 TBG. GOT ON DAKOTA TBG & BACKED OFF. WELL STARTED KICKING W/52 STDS OUT HOLE. PMP 55 BBL 2% KCL WTR TO KILL WELL. TOH & LD 29 JT 2-1/16 TBG & PIECE. SDON.

#### \*\*\*\*\*\*\*\* 5/14/1982 \*\*\*\*\*\*\*\*

- **★** FISHING FOR DAKOTA PRODUCTION STRING. RECOVERED 2 JTS 2-1/16 TBG.
- \$ SHUT DOWN OVERNIGHT
  TIH W/GUIDE SHOE & GRAPPLE. GOT ON FISH & BACKED OFF 2-1/16 TBG. POH
  & LD 2 JT TBG. TIH & TRIED TO BACK OFF TBG. COULD NOT BACK OFF.
  PREP TO RUN STRING SHOT. SDON.

#### \*\*\*\*\*\*\*\* 5/15/1982 \*\*\*\*\*\*\*\*

- \* FISHING FOR DAKOTA PRODUCTION STRING. RECOVERED 33' 2-1/16" TBG.
- \* SHUT DOWN OVERNIGHT.

  RU GO WIRELINE & RAN FREE PT TO 6257'. TBG FREE, JET-CUT TBG @ 6245'.

  TOOH & LD 13', TBG CMT OFF & 20 JT 2-1/16 TBG. TIH W/CTR SPEAR.

  CAUGHT FISH, BUT COULD NOT HOLD. TOOH. SDON.

#### REMARKS

.....

\*\*\*\*\*\* 5/15/1982 \*\*\*\*\*\*\* (CONTINUED)

\*\*\*\*\*\*\* 5/16/1982 \*\*\*\*\*\*\*

\* FISHING DAKOTA PRODUCTION STRING, NO RECOVERY. SHUT DOWN FOR WKEND. RIH W/MILL SHOE, CUT LIP GUIDE, WASH PIPE W/CTR SPENT, DC, & JARS. TOOH, HAD 6 PIECE OF TBG, TIH & TOH W/SAME TOOLS. NO FISH. SHUT DOWN OVER WEEKEND.

\*\*\*\*\*\*\* 5/17/1982 \*\*\*\*\*\*\*

\* SHUT DOWN FOR SUNDAY. SD FOR SUNDAY.

\*\*\*\*\*\*\* 5/18/1982 \*\*\*\*\*\*\*

- \* TRIPPED IN & OUT OF HOLE TWICE. RECOVERED ONE SMALL PIECE OF ROD.
- \* FISHING AT 6062. SHUT DOWN OVERNIGHT.
  FISHING AT 6062 FOR DAKOTA PROD STRING, REC ONE SMALL PIECE OF ROD.

\*\*\*\*\*\*\* 5/19/1982 \*\*\*\*\*\*\*\*

\* FISHING FOR DAKOTA PRODUCTION STRING, RECOVER SMALL PIECE OF ROD. TIH W/CUT-LIP SHOE. NO CMT RIGHT ON SHOE. WORKED STRING & TOOL. TOOH. REC SMALL WADDED UP PIECE OF ROD. TIH W/MILL SHOE & 2 JT WASH PIPE TO MILL OVER FISH.

\*\*\*\*\*\*\*\* 5/20/1982 \*\*\*\*\*\*\*

\* MILLING OVER FISH.
MILLED OVER FISH FOR 8 HR. TOOH W/ROD PIECES TOTALLING ABOUT ONE ROD.
CHANGED ROTARY MILL SHOE. SDON.

\*\*\*\*\*\*\* 5/21/1982 \*\*\*\*\*\*\*

- \* MILLING OVER PRODUCTION STRING, RECOVERED SEVERAL PIECES OF RODS.
- \* SHUT DOWN OVERNIGHT.

  TIH & MILLED OVER FISH FOR 7 HR. TOOH W/SEVERAL PIECES OF RODS. CHG
  TO NEW MILL SHOE. SDON. FISHING AT 6150'.

\*\*\*\*\*\*\* 5/22/1982 \*\*\*\*\*\*\*\*

- # MILLING OVER DAKOTA PRODUCTION STRING. RECOVERED APPROX 10
- \* FEET OF ROD WITH BOX. SHUT DOWN OVERNIGHT.

  TIH & MILLED OVER FISH FOR 9 HR. TOOH W/PIECES OF ROD. HAD ABOUT 10' ROD W/ONE BOX. PUT ON NEW HILL SHOE & SDON.

\*\*\*\*\*\*\* 5/23/1982 \*\*\*\*\*\*\*

- \* MILLING OVER DAKOTA PRODUCTION STRING, RECOVERED APPROX 20' ROD
- \* PIECES. SHUT DOWN OVERNIGHT.
  TIH W/MILL SHOE, 2 JT WASHPIPE, JARS, % 2° WORK STRING. MILLED OVER
  FISH FOR 8 HR. MILLED TO 6342'. TOOH W/ABOUT 20' ROD PIECES. SDON.

\*\*\*\*\*\*\* 5/24/1982 \*\*\*\*\*\*\*\*

\* SHUT DOWN FOR SUNDAY. SD FOR SUNDAY.

\*\*\*\*\*\*\*\* 5/25/1982 \*\*\*\*\*\*\*\*

\* REPAIRED RIG, MILLED OVER PRODUCTION STRING 1-1/2'. SHUT DOWN OVER-

#### REMARKS

\_----

#### \*\*\*\*\*\* 5/25/1982 \*\*\*\*\*\*\* (CONTINUED)

\* NIGHT.

REPAIRS TO RIG. TIH & MILLED. MADE 1-1/2'. SDON.

#### \*\*\*\*\*\*\* 5/26/1982 \*\*\*\*\*\*\*

- \* MILLED 8 HRS WITH TRIP FOR NEW MILLING SHOE, MADE 3', SHUT DOWN
- \* OVERNIGHT.

MILLED 4 HR, POOH, CHG MILL SHOE, RIH, MILL 4 HR, SDON, MADE 3' HOLE.

#### \*\*\*\*\*\*\* 5/27/1982 \*\*\*\*\*\*\*\*

\* KILLED WELL & MILLED 6 HR. NO RECOVERY, SHUT DOWN OVERNIGHT. PUMP 75 BBL 2% KCL TO KILL WELL, MILLED OVER FISH 6 HR, SDON

#### \*\*\*\*\*\*\* 5/28/1982 \*\*\*\*\*\*\*

\* SET BRIDGE PLUG & SQUEEZE CASING HOLE.
RUN BLUE JET 5-1/2 GUAGE RING TO TOP OF FISH @ 6244, OK, SET PKR RBP
@ 5913, PU RTTS ON 2-3/8 TBG & RIH TO 5830. SET PKR & TEST RBP TO
2500 PSI, OK, SPOT 10 GAL 20/40 SD ON TOP PKR, POOH 16 STDS TO 4890.
SET PKR & INJ @ RATE 3 BPM @ 800 PSI. MIX & PUMP 150 SX CLASS B CHT
W/2% CACL2 & 150 SX CLASS B CMT W/0.4% HALAD 9. DISPLACE BELOW PKR &
SLOW PUMPS TO 1/4 BPM. DISPL TO 4850, SI W/400 PSI STANDING PRESS.
SION.

#### \*\*\*\*\*\*\* 5/29/1982 \*\*\*\*\*\*\*

\* DRILL CEMENT & CLEAN OUT HOLE TO 5533. SHUT DOWN OVERNIGHT.
RELEASE RTTS & POOH. RIH W/4-3/4 BIT & TAG CMT @ 5355. DRILL & CO
TO 5533, CIRC HOLE CLEAN & SDON.

#### \*\*\*\*\*\*\* 5/30/1982 \*\*\*\*\*\*\*

- \* DRILL OUT TO 5715, PRESSURE TEST CASING TO 2000 PSI FOR 15 MIN. NO
- \* LEAKS. PULL OUT OF HOLE TO 5380 % SHUT DOWN UNTIL TUESDAY A.M. DRILL CHT 5533-5715, CIRC HOLE CLEAN, PRESS TEST TO 2000 PSI FOR 15 MIN OK. POOH TO 5380 % SD FOR WKEND.

#### \*\*\*\*\*\*\*\* 5/31/1982 \*\*\*\*\*\*\*\*

\* SHUT DOWN FOR WEEKEND. SD FOR WKEND.

#### \*\*\*\*\*\*\*\* 6/ 1/1982 \*\*\*\*\*\*\*\*

\* SHUT DOWN FOR WEEKEND. SD FOR WKEND.

#### \*\*\*\*\*\*\*\* 6/ 2/1982 \*\*\*\*\*\*\*\*

- \* CLEAN OFF BRIDGE PLUG & RETRIEVE. RUN IN HOLE WITH WASHOVER PIPE TO
- \* 5000'. SHUT DOWN OVERNIGHT.
  RIH W/BIT TO 5885 % CLEAN SD OFF RBP @ 5913, POOH % PU RETREVING
  TOOL. RIH % RET RBP. PU MILLSHOE % WO PIPE % 2 DC. RIH TO 5000.
  SDON.

#### \*\*\*\*\*\*\* 6/ 3/1982 \*\*\*\*\*\*\*

FISHING FOR PRODUCTION STRING, MILLED 7 HR. RECOVER 1-1/2' 2-1/16\*

#### REMARKS

#### \*\*\*\*\*\*\* 6/ 3/1982 \*\*\*\*\*\*\*\* (CONTINUED)

\* TUBING. SHUT DOWN OVERNIGHT.

FIN RIH, MILL 7 HR, PODH, REC METAL CUTTING & APPROX 1-1/2' 2-1/16\*

TBG. PU NEW SHOE & RIH TO 2000, SDON.

#### \*\*\*\*\*\*\*\* 6/ 4/1982 \*\*\*\*\*\*\*

\* FISHING FOR PRODUCTION STRINGS.
HILL AND WASH 11 FT. IN 7 HRS (6251) POOH, RECOVER PART OF ROD. COULD
NOT GET FISH OUT OF WASHPIPE. SDON.

#### \*\*\*\*\*\*\* 6/ 5/1982 \*\*\*\*\*\*\*

\* FISHING FOR PRODUCTION STRINGS, NO RECOVERY. SHUT DOWN OVERNIGHT.
REC APPROX 21' ROB FROM WASHPIPE, RIH W/NEW MILL TO 6246. HILL & WASH
TO 6252. POOH, NO REC. SDON.

#### \*\*\*\*\*\*\*\*\* 6/ 6/1982 \*\*\*\*\*\*\*\*

\* FISHING FOR PRODUCTION STRING, NO RECOVERY. SHUT DOWN OVERNIGHT.
PU NEW HILL, RIH, MILL % WASH TO 6259 IN 7 HR. POOH, NO REC. SDON.

#### \*\*\*\*\*\*\* 6/ 7/1982 \*\*\*\*\*\*\*\*

\* SHUT DOWN FOR SUNDAY. SD FOR SUNDAY.

#### \*\*\*\*\*\*\*\* 6/ 8/1982 \*\*\*\*\*\*\*\*

- \* FISHING FOR PRODUCTION STRING, RECOVER 7' BALLED UP ROD W/ROD BOX.
  - SHUT DOWN OVERNIGHT.

    RIH W/NEW MILL SHOE, MILL & WASH TO 6260. POOH & REC 7' OF BALLED UP
    ROD & BOX. SDON.

#### \*\*\*\*\*\*\*\* 6/ 9/1982 \*\*\*\*\*\*\*\*

\* FISHING FOR PRODUCTION STRINGS, NO RECOVERY, SHUT DOWN OVERNIGHT.
RIH W/NEW SHOE, TAG FISH @ 6257, MILL % WASH TO 6261 IN 7.5 HR.
POOH W/NO RECOVERY. SDON.

#### \*\*\*\*\*\*\*\* 6/10/1982 \*\*\*\*\*\*\*\*

\* MILLING & WASHING OVER FISH. SHUT DOWN OVERNIGHT.
RIH W/NEW SHOE, TAG @ 6259, MILL & WASHOVER TO 6262 IN 7 HR. SDON.

#### \*\*\*\*\*\*\*\*\* 6/11/1982 \*\*\*\*\*\*\*\*

\* FISHING FOR PRODUCTION STRING, NO RECOVERY, SHUT DOWN OVERNIGHT.
RIH W/NEW SHOE, TAG FISH 6259', MILL 7 HRS. TO 6260', POOH, RIG BROKE DOWN, SDON.

#### \*\*\*\*\*\*\*\* 6/12/1982 \*\*\*\*\*\*\*\*

\* FISHING FOR PRODUCTION STRING, NO RECOVERY, SHUT DOWN OVERNIGHT.
FIN POOH, NO REC, RIH W/NEW SHOE, TAG FISH @ 6259, MILL 6-1/2 HRS.
POOH, NO REC. SDON.

#### \*\*\*\*\*\*\*\* 6/13/1982 \*\*\*\*\*\*\*\*

\* MILLING OVER FISH, MADE 1' IN 7 HRS. SHUT DOWN FOR WEEKEND. RIH W/NEW SHOE, TAG FISH @ 6257, MILL 7 HR, MADE 1'. POOH 3 STDS, SD FOR WKEND.

#### REMARKS

-----

\*\*\*\*\*\*\* 6/13/1982 \*\*\*\*\*\*\* (CONTINUED)

\*\*\*\*\*\*\* 6/14/1982 \*\*\*\*\*\*\*

\* SHUT DOWN FOR SUNDAY.

\*\*\*\*\*\*\*\* 6/15/1982 \*\*\*\*\*\*\*\*

★ MILLING ON FISH. SHUT DOWN OVERNIGHT. RIH W/3 STDS, TAG FISH @ 6258, MILL 4 HR, MADE 1/2'. TRIP FOR NEW SHOE, MILL ON LOOSE JUNK 4 HR TO 6259. SDON.

\*\*\*\*\*\*\*\* 6/16/1982 \*\*\*\*\*\*\*\*

\* MILLING OVER FISH, MADE 2'. SHUT DOWN OVERNIGHT.

RIH & TAG AT 6257. MILL 1' IN 3.5 HR, TRIP FOR NEW MILL, MILL 4.5 HR
TO 6259. SDON.

\*\*\*\*\*\*\* 6/17/1982 \*\*\*\*\*\*\*\*

\* FISHING & MILLING, RECOVER 1 PIECE OF ROD, SHUT DOWN OVERNIGHT.
RIH 3 STDS, TAG @ 6257, MILL 4.5 HR TO 6258, TRIP FOR NEW SHOE & MAGNET, MILL 2.5 HR, POOH & REC 1 PIECE ROD & CUTTINGS. SDON.

\*\*\*\*\*\*\*\* 6/18/1982 \*\*\*\*\*\*\*

- \* MILLING ON JUNK, RECOVER 2 PIECES METAL WITH MAGNET. SHUT DOWN
- \* OVERNIGHT.

  RIH W/MAGNET, HIT 2-3/8 COLLAR, POOH W/2 PIECES HETAL, RIH W/NEW
  MILL, TAG AT 6256, MILL 6.5 HR TO 6259. SDON.

\*\*\*\*\*\*\* 6/19/1982 \*\*\*\*\*\*\*

\* MILLING OVER FISH, RECOVER 2' OF ROD. SHUT DOWN OVERNIGHT.
RIH % TAG @ 6259, MILL 3.5 HR, POOH % REC 2' OF ROD. RIH, MILL 1/2'
IN 4 HR. SDON.

\*\*\*\*\*\*\*\* 6/20/1982 \*\*\*\*\*\*\*\*

- \* MILLING ON FISH, RECOVER 4 PIECES METAL & MAGNET FULL OF CUTTINGS.
- \* SHUT DOWN OVERNIGHT.

  RIH, MILL 3 HR TO 6260, RU BIGGER PUMP, MILL 2 HR TO 6260.5. POOH & REC 4 PCS METAL & MAGNET FULL OF CUTTINGS. SDON.

\*\*\*\*\*\*\* 6/21/1982 \*\*\*\*\*\*\*

\* SHUT DOWN FOR SUNDAY. SD FOR SUNDAY.

\*\*\*\*\*\*\* 6/22/1982 \*\*\*\*\*\*\*\*

- # MILLING ON FISH, RECOVER 29' ROD, 12' 2-1/16 TBG & MAGNET FULL OF
- \* CUTTINGS. SHUT DOWN OVERNIGHT.
  PU NEW HILL SHOE & RIH, TAG @ 6260. MIX GEL & MILL 7 HR TO 6261.
  POOH & REC 29' ROD, 12' 2-1/16 TBG W/LOTS OF METAL CUTTINGS. SDON.

\*\*\*\*\*\*\*\* 6/23/1982 \*\*\*\*\*\*\*\*

- # MILLING OVER FISH, RECOVER 2 SMALL METAL PIECES & MAGNET FULL OF
- \* CUTTINGS.
  RIH W/NEW MILL SHOE. TAG FILL @ 6260. MILL 6 HR TO 6262. POOH &
  REC 2 SMALL PIECES METAL, MAGNET FULL OF CUTTINGS.

#### REMARKS

\_\_\_\_\_

\*\*\*\*\*\*\* 6/23/1982 \*\*\*\*\*\*\*\* (CONTINUED)

\*\*\*\*\*\*\* 6/24/1982 \*\*\*\*\*\*\*\*

\* MILLING AT 6262', RECOVERED 8 PIECES OF METAL.
RU NEW MILL SHOE % TIH, TAG BTM AT 6262', MILL 8 HR, REC 8 PIECES
METAL % METAL CUTTINGS. PULL UP % SDON.

#### \*\*\*\*\*\*\* 6/25/1982 \*\*\*\*\*\*\*\*

- \* MILLING & FISHING FOR PRODUCTION STRINGS. RECOVERED SEVERAL PIECES
- \* OF ROD BOX.

RIH W/TBG, MILL 2 HR, POOH, PU NEW SHOE, RIH. TAG AT 6265, MILL 3.5 HR. REC SEVERAL PCS ROD BOX. SDON.

#### \*\*\*\*\*\*\* 6/26/1982 \*\*\*\*\*\*\*\*

- # MILLING OVER FISH TO 6267, LOST 30 BBLS WATER FROM PIT. SHUT DOWN
- \* OVERNIGHT.

  RIH W/TBG % TAG AT 6266', MILL FOR 3 HRS. POOH, CHG MILL SHOE, RIH

  MILL 3 HR TO 6267, LOST 30 BBLS WTR FROM PIT. POOH 1 JT, INSTALL

  VALVE, SDON.

#### \*\*\*\*\*\*\* 6/27/1982 \*\*\*\*\*\*\*

- \* FISHING FOR PRODUCTION STRING, RECOVER 7' 2-1/16" TBG WITH SLIDING
- \* SLEEVE. SHUT DOWN OVERNIGHT.

  OPEN VALVE, NO PRESS. RIH 1 JT, TAG AT 6267, NO FILL. POOH W/MILL
  RIH W/OVERSHOT, BUMPER SUB \* JARS. LATCH ONTO 2-1/16 SUB ON PKR,
  UNSEAT, POOH. REC 7' PIECE 2-1/16 TBG W/SLIDING SLEEVE. PU OVERSHOT
  FOR 2-3/8 TBG \* RIH. COULD NOT GET OVER RETRIEVING SUB DUE TO FILL.
  POOH 1 JT, INSTALL VALVE \* SDON.

#### \*\*\*\*\*\*\* 6/28/1982 \*\*\*\*\*\*\*

\* SHUT DOWN FOR SUNDAY. SD FOR SUNDAY.

#### \*\*\*\*\*\*\* 6/29/1982 \*\*\*\*\*\*\*

- \* FISHING FOR DAKOTA PROD STRING. REC 3-1/2' ROD % 1 SMALL PIECE
- \* METAL. SHUT DOWN OVERNIGHT.
  POOH W/OVERSHOT, REC 3-1/2' ROD. RU FLAT BOTTOM MAGNET, REC 1 SMALL
  PIECE METAL. RU SHOE & MAGNET. RIH & TAG AT 6264. MILL 4 HR. SDON.

#### \*\*\*\*\*\*\*\* 6/30/1982 \*\*\*\*\*\*\*\*

\* FISHING FOR DAKOTA PRODUCTION STRING, NO REC, SHUT DOWN OVERNIGHT.

POOH W/MILL, RUN IMPRESSION BLOCK, SHOWED RODS ON TOP RETRIEVING SOB.

RU SKIRTED FLAT BOTTOM MILL, RIH, SDON.

#### \*\*\*\*\*\*\*\* 7/ 1/1982 \*\*\*\*\*\*\*\*

\* MILLING ON DAKOTA PRODUCTION STRING. SHUT DOWN OVERNIGHT.
RIH W/SKIRTED; FLAT BOTTOM MILL; TAG @ 6263'. MILL 8 HR TO 6265.
POOH W/WORN OUT MILL SKIRT. SDON.

#### \*\*\*\*\*\*\*\* 7/ 2/1982 \*\*\*\*\*\*\*

\* HILL ON RODS AND HETAL TO 6267'.

#### REMARKS

-----

#### \*\*\*\*\*\*\* 7/ 2/1982 \*\*\*\*\*\*\*\* (CONTINUED)

TIH W/NEW MILL SKIRT & TAG AT 6265'. MILL FOR 7 HR TO 6267', REGAIN FULL CIRC. TOOH W/WORN OUT MILL SKIRT. FLAT BOTTOM MILL NOT AFFECTED. SDON.

#### \*\*\*\*\*\*\*\* 7/ 3/1982 \*\*\*\*\*\*\*\*

- \* TRIP IN HOLE WITH NEW MILL SKIRT AND TAG AT 6267'. MILL FOR 7 HOURS
- \* MILLING ON FISH, NO RECOVERY.
- \* TO 6269'. TRIP OUT OF HOLE WITH WORN-OUT MILL SKIRT. SHUT DOWN
- \* OVERNIGHT.

RIH W/NEW MILL: TAG @ 6267. MILL 7 HR TO 6269. POOH W/WORN OUT MILL SDON.

#### \*\*\*\*\*\*\* 7/ 4/1982 \*\*\*\*\*\*\*

- \* RIG UP NEW MILL SHOE WITH MAGNET, AND TRIP IN HOLE. TAG AT 6268'.
- \* MILL ON FISH, NO RECOVERY, SHUT DOWN FOR HOLIDAY.
- \* (LOST 1'). MILL FOR 5 HOURS. SHUT DOWN OVERNIGHT.
  RU NEW HILL W/MAGNET, RIH, TAG AT 6268, MILL 5 HR. SD FOR HOLIDAY.

#### **\*\*\*\*\*\*\*** 7/ 5/1982 **\*\*\*\*\***

- \* SHUT DOWN OVER WEEKEND.
- \* SHUT DOWN FOR SUNDAY. SD FOR SUNDAY.

#### \*\*\*\*\*\*\*\* 7/ 6/1982 \*\*\*\*\*\*\*

- \* SHUT DOWN OVER WEEKEND.
- SHUT DOWN FOR HOLIDAY, SD FOR HOLIDAY,

#### \*\*\*\*\*\*\*\* 7/ 7/1982 \*\*\*\*\*\*\*\*

\* HILLING ON PRODUCTION STRING, RECOVERED MAGNET FULL OF CUTTINGS.
RUN IN HOLE WITH HILL SHOE AND HILL FOR 3 HRS. TO 6270'. TOOH AND
REPLACE MILL SHOE (RECOVERED METAL CUTTINGS). TRIP IN HOLE WITH
NEW HILL SHOE AND MILL FOR 3 HRS. TO 6271'. SHUT DOWN OVERNIGHT.

#### \*\*\*\*\*\*\*\* 7/ 8/1982 \*\*\*\*\*\*\*

# MILLING ON PRODUCTIN STRING, RECOVERED PIECES OF ROD BOX AND ROD. RIH AND MILL FOR 3 HRS. TO 6271'. TOOH W/OLD MILL SHOE. (RECOVERED PIECES OF ROD BOX AND RODS). RU AND TIH W/NEW MILL SHOE. MILL FOR 3-1/2 HRS. TO 6272'. SDON.

#### \*\*\*\*\*\*\* 7/ 9/1982 \*\*\*\*\*\*\*\*

- \* MILLING ON PRODUCTION STRING RECOVERED MAGNET FULL OF CUTTINGS AND
- **\*** ONE ROD BOX.

RIH W/TBG. AND TAG AT 6272'. MILL FOR 3-1/2 HRS. TOOH W/WORN-OUT MILL SHOE. RECOVERED MAGNET FULL OF METAL. TIH W/NEW MILL SHOE AND MILL FOR 2-1/2 HRS. TO 6273'. SDON.

#### \*\*\*\*\*\*\*\* 7/10/1982 \*\*\*\*\*\*\*

\* MILL ON TOP SLIPS OF PACKER.

#### REMARKS

#### \*\*\*\*\*\* 7/10/1982 \*\*\*\*\*\*\*\* (CONTINUED)

- \* RUN IN WITH TUBING AND TAG AT 6315 FEET. MILL FOR 6 HOURS, RECOVERI
- \* NG LARGE AMOUNTS OF RUBBER.

  RUN IN HOLE WITH TUBING TO 6273', MILL FOR 3-1/2 HRS. TO 6274'.

  TRIP OUT OF HOLE WITH WORE OUT MILL SHOE. RECOVER PIECES OF METAL
  IN MAGNET AND PIECES OF RUBBER. TRIP IN HOLE WITH NEW MILL SHOE.

  SDON.

#### \*\*\*\*\*\*\*\* 7/11/1982 \*\*\*\*\*\*\*\*

\* MILLING ON PRODUCTION PACKER, RECOVER LARGE AMOUNT OF RUBBER.

#### \*\*\*\*\*\*\*\* 7/12/1982 \*\*\*\*\*\*\*

\* SHUT DOWN FOR SUNDAY.

#### \*\*\*\*\*\*\*\* 7/13/1982 \*\*\*\*\*\*\*\*

- \* MILLING ON PRODUCTION STRING. RECOVERED 4 1/2' OF ROD AND CUTTINGS.
- \* SHUT DOWN OVER NIGHT.

RUN IN HOLE WITH TUBING AND TAG AT 6315', MILL FOR 4 1/2 HRS. PACK ER FELL TO 6384'. MILL FOR 2 HRS. TRIP OUT OF HOLE WITH WORN OUT MILL SHOE, RECOVERED 4 1/2' OF ROD AND LARGE AMOUNT OF RUBBER CUTTINGS. TRIP IN HOLE WITH NEW MILL SHOE. SHUT DOWN OVER NIGHT.

#### \*\*\*\*\*\*\*\* 7/14/1982 \*\*\*\*\*\*\*\*

\* CONTINUE WILLING ON PACKER.

RIH W/TBG. AND TAG AT 6384'. HILL FOR 8 HRS. TO 6386' RECOVERED LARGE AMOUNTS OF METAL AND PIECES OF RODS. TOOH W/WORN-OUT HILL SHOE. MAGNET FULL OF CUTTINGS. TIH W/NEW HILL SHOE. S.D.O.N.

#### \*\*\*\*\*\*\*\* 7/15/1982 \*\*\*\*\*\*\*\*

\* MILLING ON SLIPS OF PACKER @ 6387'.

RUN IN HOLE WITH TUBING AND TAG AT 6385' (LOST 1'). MILL FOR 10 HRS
TO 6387'. RECOVERED PIECES OF METAL AND LARGE AMOUNTS OF RUBBER.

SHUT DOWN OVER NIGHT.

#### \*\*\*\*\*\*\*\* 7/16/1982 \*\*\*\*\*\*\*\*

MILLING ON SLIPS OF PACKER AT 6408 FEET.

RUN IN HOLE WITH TUBING AND TAG AT 6387'. MILL FOR 5 HOURS. TRIP
OUT OF HOLE WITH WORE OUT MILL SHOE. RECOVERED PIECES OF METAL IN
MAGNET. TRIP IN HOLE WITH NEW MILL SHOE. MILL FOR 2 HRS. PACKER
FELL TO 6408'. SHUT DOWN OVERNIGHT.

#### \*\*\*\*\*\*\*\* 7/17/1982 \*\*\*\*\*\*\*\*

\* MILLING ON PACKER AT 6408 FEET.

RUN IN HOLE WITH TUBING AND TAG AT 6408'. MILL 6 HRS. TO 6410'.

TRIP OUT OF HOLE WITH WORE OUT MILL SHOE. REPAIR RIG. RIG UP OVER SHOT, BUMPER SUB, AND JARS. TRIP IN HOLE. SHUT DOWN OVERNIGHT.

#### \*\*\*\*\*\*\*\* 7/18/1982 \*\*\*\*\*\*\*\*

# MILLING ON PAKCER AT 6404 FEET.
RUN IN HOLE WITH OVER SHOT. COULD NOT GET OVER RETRIEVING SUB ON

#### REMARKS

\*\*\*\*\*\* 7/18/1982 \*\*\*\*\*\* (CONTINUED)

PACKER. TRIP OUT OF HOLE WITH OVER SHOT. RIG UP SKIRTED FLAT BOTTOM MILL AND TRIP IN HOLE. TAG AT 6404' MILL FOR 2 HRS. SHUT DOWN OVERNIGHT.

\*\*\*\*\*\*\*\* 7/19/1982 \*\*\*\*\*\*\*\*

**\* SHUT DOWN OVER WEEKEND** 

\*\*\*\*\*\*\*\* 7/20/1982 \*\*\*\*\*\*\*

# MILL ON PACKER AT 6405 FEET.

RUN IN HOLE TO 6404'. MILL FOR 4 HRS. TO 6405'. TRIP OUT OF HOLE

WITH WORE OUT MILL. TRIP IN HOLE W/NEW SKIRTED MILL. MILL FOR 3 HRS.

SHUT DOWN OVERNIGHT.

#### \*\*\*\*\*\*\*\* 7/21/1982 \*\*\*\*\*\*\*

- \* MILL AND ATTEMPT TO FISH PACKER AT 6405 FEET, WILL ABANDON FISH AT
- \* 6405 FEET, FISH IS 9' BELOW BOTTOM DAKOTA PERFORATIONS.

  MILL ON RETRIEVING SUB AT 6405' FOR 3 HRS. % PULL OUT OF HOLE, HAD IMPRINT OF 2-3/8" COUPLING ON MILL. PICK UP OVER SHOT W/GRAPPLES AND GUIDE SHOE W/KUT-RITE INSIDE SHOE. GO IN HOLE TO TOP OF FISH AT 6405'. COULD NOT GET OVER FISH. SHUT DOWN OVERNIGHT.

#### \*\*\*\*\*\*\*\* 7/22/1982 \*\*\*\*\*\*\*\*

\* ATTEMPT TO FISH PACKER AT 6405'. RECOVERED NOTHING.
TRIP OUT HOLE W/OVER SHOT. RECOVERED NOTHING. LAY DOWN COLLARS &
FISHING EQUIP. & RELEASE DOTCO. TRIP IN HOLE W/2-1/16" TBG. & TRIP
OUT OF HOLE LAYING DOWN 2-1/16" TBG. CLEAN PIT AND MIX 160 BBLS.
2% KCL WATER AND PREPARE TO CLEAN WELL.

#### \*\*\*\*\*\*\*\* 7/23/1982 \*\*\*\*\*\*\*\*

\* SWAB WELL & PREPARE TO ACIDIZE.

RU HALLIBURTON "RTTS" PKR. TIH TO 6393. CIRC HOLE W/2% KCL WTR. PULL

UP TO 6235, SET PKR. RU SWAB REC WTR & MUD FROM WELL. RU HALLIBURTON

ACID. PUMP & PREP TO ACIDIZE WELL. SDON.

#### \*\*\*\*\*\*\* 7/24/1982 \*\*\*\*\*\*\*

\* ACIDIZE WELL TO CLEAN UP.

SIP OVERNIGHT 150 PSI, RU SWAB LINE. RIH, TAG FL @ 900'. RU HALLIBURTON TO TBG & PUMP 1000 GAL 7-1/2% MCA ACID AT 2 BPM & MAX PSI 1300
PSI. ISIP 950 PSI, FLOW BACK TO ACID TANK 250 GAL OF FL. PUMP BACK
IN WELL & OVER DISPLACE 500 GAL AT 2 BPM & 1050 PSI. ISIP 400 PSI,
WAIT 1 HR, RU SWAB LINE. SWAB WELL BACK REC HEAVY AMT GAS CUT ACID
& WTR. SDON.

#### \*\*\*\*\*\*\*\* 7/25/1982 \*\*\*\*\*\*\*

\* SWAB WELL TO PIT TO CLEAN UP.
SIP OVERNIGHT 150 PSI, RIH W/SWAB & TAG FL AT 5100', SWAB WELL TO PIT MAKING HVY AMT WIR. SDON.

#### \*\*\*\*\*\*\* 7/26/1982 \*\*\*\*\*\*\*\*

\* SHUT DOWN FOR SUNDAY.

#### REMARKS

\*\*\*\*\*\*\* 7/26/1982 \*\*\*\*\*\*\* (CONTINUED)

SD FOR SUNDAY.

#### \*\*\*\*\*\*\*\* 7/27/1982 \*\*\*\*\*\*\*\*\*

\* ACIDIZE WELL TO CLEAN UP.

SIP OVER WKEND 550 PSI. OPEN TO PIT. BLEW DOWN IN 30 MIN REC SMALL AMT WIR. RU & SWAB WELL DRY IN 2 RUNS. TAG FL @ 5200'. WAIT 1.5 HR & SWAB WELL DRY IN 3 RUNS, TAG FL @ 5200, RU HALLIBURTON & ACIDIZE WELL WITH 1000 GAL 15% MCA ACID & 600 SCF PER BARREL. NITROGEN & 50-7/8" BALL SEALERS MAX RATE 3.8 BPM, AVG RATE 3.5 BPM. MAX PRESS 2700 PSI, AVG PRESS 2500 PSI. ISIP 1600 PSI, SAW 200 PSI INCR WHEN BALLS GOT TO FM. SI FOR 2 HR & OPEN TO PIT. FLOW TO PIT FOR 1 HR, SDON.

#### \*\*\*\*\*\*\*\*\* 7/28/1982 **\*\*\***\*\*\*\*\*

\* SWAB WELL TO CLEAN UP.

SIP OVERNIGHT 500 PSI, RU SWAB & TAG FL @ 5100', SWAB WELL TO PIT TO CLEAN UP, WELL MAKING APPROX 4 BBL FL/HR W/SM SHOW OF GAS. RUN SWAB EACH HR. SDON.

#### **\*\*\*\*\*\*\*\*** 7/29/1982 **\*\*\*\*\*\***

\* SWAB WELL TO CLEAN UP.

SHUT IN PRESSURE OVER NIGHT - 580 PSI. RUN SWAB AND TAG FLUID AT 5600'. SWAB WELL TO PIT TO CLEAN UP. WELL MAKING APPROXIMATELY 1-1/2 BARRELS PER HOUR WITH SMALL SHOW OF GAS. RUN SWAB EACH HOUR. SHUT DOWN OVER NIGHT.

#### \*\*\*\*\*\*\*\*\* 7/30/1982 \*\*\*\*\*\*\*\*

\* ACIDIZE WELL TO CLEAN UP.

SHUT IN PRESSURE OVER NIGHT 750 PSI. OPEN WELL TO PIT AND FLOW BACK FOR 1-1/2 HRS. RUN SWAB IN HOLE, TAG NO FLUID. RIG HALLIBURTON TO ACIDIZE WELL. ACIDIZE WELL WITH 3000 GAL 7-1/2% HCL AND 700 SCF NITROGEN PER BARREL AND 50 BALL SEALERS. MAXIMUM RATE 7.4 BPM, MINIMUM RATE 4.3 BPM. AVERAGE RATE 4 BPM. MAXIMUM PRESSURE 3000 PSI, MINIMUM PRESSURE 500 PSI. AVERAGE PRESSURE 2450 PSI. ISIP = 250 PSI SAW 400 PSI WHEN BALL HIT FORMATION. OPEN WELL UP TO PIT AFTER SHUT IN FOR 1-1/2 HRS. FLOW WELL OVERNIGHT WITH WATCHMAN.

#### \*\*\*\*\*\*\*\* 7/31/1982 \*\*\*\*\*\*\*\*

\* SWAB WELL TO CLEAN UP.

RIG UP SWAB AND TAG FLUID AT 4000'. SWAB WELL TO PIT TO CLEAN UP. WELL MAKING 8 BBLS PER HR AND SMALL AMOUNT OF GAS.

#### \*\*\*\*\*\*\*\* 8/ 1/1982 \*\*\*\*\*\*\*\*

\* SWAB WELL TO PIT TO CLEAN UP.

SHUT IN PRESSURE OVER NIGHT 650 PSI. FLOW WELL TO PIT. RIG UP SWAB AND TAG FLUID AT 5100'. WELL MAKING 1-1/2 BBL FLUID PER HOUR & SMALL AMOUNT OF GAS. SHUT DOWN OVER NIGHT.

#### \*\*\*\*\*\*\*\* 8/ 2/1982 \*\*\*\*\*\*\*

\* SHUT DOWN OVER WEEKEND.

#### REMARKS

\*\*\*\*\*\* 8/ 2/1982 \*\*\*\*\*\*\* (CONTINUED)

\*\*\*\*\*\*\*\* 8/ 3/1982 \*\*\*\*\*\*\*\*

\* SWAB WELL TO FIT TO CLEAN UP.

SHUT IN PRESSURE OVER WEEKEND - 950 PSI. FLOW WELL TO PIT FOR 2-1/2

HRS. SWAB WELL TO PIT, MAKING HEAVY MIST OF WATER AND SMALL AMOUNT

OF GAS. SHUT DOWN OVER NIGHT.

#### \*\*\*\*\*\*\*\* 8/ 4/1982 \*\*\*\*\*\*\*\*

\* FLOW WELL TO PIT TO CLEAN UP.

SHUT-IN PRESSURE OVERNIGHT 860 PSI. OPEN WELL TO PIT AND FLOW BACK
FOR 2 HRS. - MAKING GAS AND APPROX. 20 BBL WATER. WELL UNLOADED
EVERY 3 HRS. MAKING APPROX. 6 BBL WATER AND LARGE AMOUNT OF GAS.

SDON.

#### \*\*\*\*\*\*\* 8/ 5/1982 \*\*\*\*\*\*\*

\* FLOW WELL TO PIT TO CLEAN UP.

SHUT IN PRESSURE OVER NIGHT 770 PSI. OPEN WELL AND FLOW TO PIT FOR 2

HRS. MAKING GAS & APPROXIMATELY 20 BBL WATER. WELL UNLOADED EVERY 3

HRS. MAKING GAS & APPROXIMATELY 3 BBL WATER. SHUT DOWN DVER NIGHT.

#### \*\*\*\*\*\*\* 8/ 6/1982 \*\*\*\*\*\*\*\*

\* PULL TUBING AND PACKER OUT OF HOLE AND STIMULATE DAKOTA ZONE.

RELEASE PACKER @ 6236' % MOVE PACKER DOWN HOLE TO 6400'. SPOT 500

GAL OF 15% HCL FROM 6400' TO 5900'. PODH W/PACKER % TBG. HAL
LIBURTON TREATED DAKOTA ZONE W/48,000 LBS OF 20-40 SND % 30,000 GALS

OF 30 LB X-LINKED GELLED 1% KCL WTR. MAX INJECTION RATE 34 BPM.

AVERAGE INJECTION RATE 25 BPM. HAX PRESSURE 1600 PSI. AVERAGE PRESSURE 1400 PSI. SAND CONCENTRATION 1,2, % 3 LBS PER GALLON. ISIP

1350 PSI, 15 MIN, 640 PSI. SHUT WELL IN OVERNIGHT.

#### \*\*\*\*\*\*\*\* 8/ 7/1982 \*\*\*\*\*\*\*\*

SWAB WELL TO PIT TO CLEAN UP.

SHUT-IN PRESSURE OVERNIGHT - O PSI. TIH WITH 2-3/8" TUBING TO 6380'.

RIG UP & SWAB WELL TO PIT. MAKING APPROX. 4 BBL. WATER PER RUN.

SDON.

#### \*\*\*\*\*\*\*\* 8/ 8/1982 \*\*\*\*\*\*\*\*\*

\* SWAB WELL TO PIT TO CLEAN UP.
SHUT IN PRESSURE OVER NIGHT CASING 50 PSI, TUBING 0 PSI, SWAB WELL
TO PIT MAKING APPROXIMATELY 2 BBL PER RUN. SHUT DOWN OVER NIGHT.

#### \*\*\*\*\*\*\*\* 8/ 9/1982 \*\*\*\*\*\*\*

\* SHUT DOWN OVER WEEKEND.

#### \*\*\*\*\*\*\* 8/10/1982 \*\*\*\*\*\*\*

\* SWAB WELL TO PIT TO CLEAN UP.
SHUT IN PRESSURE OVER NIGHT 150 PSI ON CASING AND O PSI ON TUBING.
SWAB WELL TO PIT. WELL MAKING APPROX. 2 BBLS. PER RUN. WELL MAKING
SMALL AMOUNT OF GAS, WATER AND SAND.

. 10.

#### REMARKS

\*\*\*\*\*\*\* 8/18/1982 \*\*\*\*\*\*\* (CONTINUED)

SEATING NIPPLE AT 6361'. TUBING HANGER DID NOT HOLD PRESSURE, NIPPLE BACK UP AND SDON.

#### \*\*\*\*\*\*\*\* 8/19/1982 \*\*\*\*\*\*\*

\* LAND TUBING AND FLOW WELL TO PIT TO CLEAN UP,
SHUT IN PRESSURE OVERNIGHT - 600 PSI ON CASING AND 375 PSI ON TUBING,
FLOW WELL TO PIT FOR 2 HRS. LAND TUBING IN GULF-CO WELL HEAD. RIG
UP SWAB AND TAG FLUID AT 6000'. RECOVERED 1 BBL WATER. WELL MAKING
GAS AND FINE MIST OF WATER. SDON.

#### \*\*\*\*\*\*\*\* 8/20/1982 \*\*\*\*\*\*\*

\* BLOW AND CLEAN TO PIT THROUGH CHOKE. SHUT IN CASING PRESSURE 670 PSI - TBG PRESSURE 375 PSI - OPEN TO PIT THROUGH 1/2" CHOKE. WELL LIFTING FLUID AFTER 1/2 HR AND CONTINUE THROUGH 7 HRS. CSG PRESSURE 290 PSI - REDUCED CHOKE TO 3/8" AND LEFT OPEN TO PIT OVERNIGHT.

#### \*\*\*\*\*\*\*\* 8/21/1982 \*\*\*\*\*\*\*\*

\* WELL SHUT IN TO PRESSURE UP.
NIPPLE UP WELLHEAD & OPEN THROUGH 3/8" CHOKE - RELEASE RIG AT 4:00
P.M. 8-20-82. SHUT WELL IN TO PRESSURE UP OVER WEEKEND.

#### \*\*\*\*\*\*\*\* 8/24/1982 \*\*\*\*\*\*\*\*

\* WELL SHUT IN TO PRESSURE UP.

#### \*\*\*\*\*\*\*\* 8/31/1982 \*\*\*\*\*\*\*

IN 4 HRS. ON 3/4" CHOKE, 30 PSI ON UNIT, FTP 77 PSI, GAS RATE 270

#### REMARKS

\*\*\*\*\*\*\* 8/10/1982 \*\*\*\*\*\*\* (CONTINUED)

\*\*\*\*\*\*\* 8/11/1982 \*\*\*\*\*\*

ŧ

\* SWAB WELL TO PIT TO CLEAN UP.
SHUT IN PRESSURE OVER NIGHT. 300 PSI ON CASING, 50 PSI ON TUBING.
SWAB WELL TO PIT. TAG FLUID AT 4200'. WELL MAKING APPROX. 4 BBLS.
WATER PER RUN. SHUT DOWN OVERNIGHT.

#### \*\*\*\*\*\*\*\* 8/12/1982 \*\*\*\*\*\*\*\*

SWABBING AND FLOWING TO PIT.

SHUT IN PRESSURE LOSING 650 PSI - TUBING PRESSURE 25 PSI. OPEN WELL AND SWAB TO PIT - WELL KICKED OFF @ 1:30 PM 8-11-82: FLOW FOR 1 HR AND DIED - RAN SWAB ONE TIME AND WELL FLOWED UNTIL 5:00 PM - MAKING HEAVY VOLUME SAND, WATER AND GAS - SHUT IN OVER NIGHT.

#### \*\*\*\*\*\*\*\* 8/13/1982 \*\*\*\*\*\*\*

\* SWAB WELL TO PIT TO CLEAN UP.

SHUT IN PRESSURE OVERNIGHT - 750 PSI ON CASING AND 100 PSI ON TUBING.

SWAB WELL DRY IN 3 RUNS. MAKING APPROX. 3 BBLS WATER PER RUN. WELL

MAKING WATER, TRACE OF SAND, AND GAS. SHUT DOWN OVERNIGHT.

#### \*\*\*\*\*\*\*\* 8/14/1982 \*\*\*\*\*\*\*

SWAB WELL TO PIT TO CLEAN UP.

SHUT IN PRESSURE OVER NIGHT - 800 PSI ON CASING AND 300 ON TUBING.

FLOW TO PIT FOR 2 HRS THEN LOGGED OFF. RIG UP, SWAB AND TAG FLUID AT 5000'. SWAB TUBING DRY IN 2 RUNS. WAITED 2 HRS AND RAN SWAB, BLOW APPROX 2 HRS BEFORE LOGGED OFF. MADE APPROX 3 BBLS WATER PER RUN. WELL MAKING SAND, GAS AND WATER. SHUT DOWN OVER NIGHT.

#### \*\*\*\*\*\*\*\* 8/15/1982 \*\*\*\*\*\*\*

SWAB WELL TO PIT TO CLEAN UP.

SHUT IN PRESSURE OVER NIGHT - 700 PSI ON CASING AND 250 ON TUBING.

FLOW WELL TO PIT FOR 2 HRS. MAKE SWAB RUN EVERY 2 HRS. MAKING

APPROX 3 BBLS WATER EVERY RUN. WELL MAKING SAND, GAS AND WATER.

WELL WILL BLOW APPROX 1 HOUR AFTER SWAB RUN. SHUT DOWN OVER NIGHT.

#### \*\*\*\*\*\*\*\* 8/16/1982 \*\*\*\*\*\*\*\*\*

\* SHUT DOWN FOR WEEKEND.

#### \*\*\*\*\*\*\*\* 8/17/1982 \*\*\*\*\*\*\*

SWAB AND FLOW WELL TO PIT TO CLEAN UP.

SHUT IN PRESSURE OVER WEEKEND - 800 PSI ON CASING AND 500 PSI ON TBG.

FLOW WELL TO PIT FOR 5 HRS, RIG UP SWAB AND TAG FLUID AT 5500'. SWAB

WELL BACK AND RECOVERED APROX 2 BBLS WATER. WELL MAKING GAS, WATER

AND SMALL AMOUNT OF SAND. SDON.

#### \*\*\*\*\*\*\*\* 8/18/1982 \*\*\*\*\*\*\*

\* FLOW WELL TO PIT TO TRY TO LAND TUBING.
SHUT IN PRESSURE OVERNIGHT. 700 PSI ON CASING AND 400 PSI ON TUBING.
FLOW TO WELL FOR 4 HRS TO PIT. PULL UP TO 6392' AND LAND TUBING.