

English & Harmon
Stagner No. 1
Schematic of Plugging Detail
Form C-108 Item VI

P & A: 10-28-40

Location: U-31-17-31

2 5x cement @
surface

Plug from 192' to
200' w 10 sx

TOC @ 470' by calc.

8 1/4" csq. cemented w 50 sx

8 1/4" csq. @ 670'

Hole filled w/ mud

Note: Ernest A. Hansen
attempted to re-enter
this well on 11-29-56.

Cleaned out to 295'
and encountered junk.

P & A 3-21-57 by filling
hole from 295' to surface
w/ mud and setting plug
from 40' to surface w/
15 sx.

Plug from 1578' to
1650' w 125 sx.

Shot 5 1/2" csq. @ 2460'
and pulled

Plug w/ rock, lead
wool, and steel
cuttings from
2460' to 4108'

8" hole

TOC @ 3950' by calc.

Cemented 5 1/2" csq. w/ 30 sx

5 1/2" csq. @ 4108'

5" hole

T.D. 4252'