

## United States Department of the Interior

## To the second

BUREAU OF LAND MANAGEMENT
Wyoming State Office Reservoir Management Group
2987 Prospector Drive
Casper, Wyoming 82604-2968

In Reply Refer to 3186 (3186.1) Poker Lake Unit NMNM71016X R-153

NOV 1 3 2017

Mr. Law Armstrong BOPCO, L.P. 810 Houston Street Fort Worth, Texas 76102-6203

Re:

Paying Well Determination

Poker Lake Unit CVX JV PC No. 13H

SHL: SE<sup>1</sup>/<sub>4</sub>SW<sup>1</sup>/<sub>4</sub>, Sec. 17, T.24S., R.30E. (Lease No. NMNM02860) BHL: NE<sup>1</sup>/<sub>4</sub>NW<sup>1</sup>/<sub>4</sub>, Sec. 17, T.24S., R.30E. (Lease No. NMNM02860)

Poker Lake Unit

Eddy County, New Mexico

## Dear Mr. Armstrong:

We have determined that under existing conditions the Poker Lake Unit CVX JV PC No. 13H well is **not** capable of producing unitized substances from the Upper Avalon Shale (a member of the Bone Spring Formation) in unit paying quantities. The well was completed in the Upper Avalon Shale on November 28, 2012. Production from the Upper Avalon Shale shall be handled and reported on a lease basis retroactive to the date of first production (July 11, 2014). The well is located on Lease No. NMNM02860.

If you have any questions, please call the undersigned at (307) 261-7685.

Sincerely,

/s/ J. David Chase

J. David Chase Chief, Reservoir Management Group cc: NMSO, James Glover
CFO, Chris Walls
ONRR, Glen Reese
New Mexico State Land Office, Anchor Holm
New Mexico Oil Conservation Division, William Jones