

RECEIVED

By OCD; Dr. Oberding at 11:06 am, Jun 04, 2015

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural ResourcesOil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505Form C-141
Revised October 10, 2003Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form**Release Notification and Corrective Action****OPERATOR**☐ Initial Report ☒ Final Report

Name of Company: Oxy Permian Ltd.	Contact: Austin Trammell	
Address: 1017 W Stanolind Road, Hobbs, NM 88240	Telephone No. (575)499-4919	
Facility Name West Dollarhide Devonian Unit 101	Facility Type: Well Location	
Surface Owner: BLM	Mineral Owner:	API No. 30-025-12335

LOCATION OF RELEASE

Unit Letter F	Section 33	Township 24S	Range 38E	Feet from the 1980	North/South Line North	Feet from the 779	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.175350° Longitude 103.0666°**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release 35Bbls	Volume Recovered 0
Source of Release: 2" riser on well head broke off	Date and Hour of Occurrence 09/24/13	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking NMOCD; Jennifer Van Curen BLM	
By Whom? Austin Trammell	Date and Hour 09/24/13 @2:31PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A 2 inch riser on the well head broke off causing 35 bbls of produced water to leak onto the ground. No fluids were recovered and the riser was repaired/replaced..

Describe Area Affected and Cleanup Action Taken.*

The affected area was excavated according to the NMOCD approved work plan. The contaminated soil was transported to Sundance, a NMOCD approved disposal facility. The excavated area was backfilled with caliche transported from off-site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Austin Trammell	Hydrologist Approved by District Supervisor: 	
Title: HSE Coordinator	Approval Date: 06/04/2015	Expiration Date: ///
E-mail Address: Austin_trammell@oxy.com	Conditions of Approval: ///	Attached <input type="checkbox"/> 1Rp-2966
Date: 05-15-2015	Phone: 575-499-4919	

* Attach Additional Sheets If Necessary

pSAD1327750394