District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NRM2009734927
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party: Cimarex Energy Co. of Colorado	OGRID: 162683
Contact Name: Laci Luig	Contact Telephone: 432.571.7800
Contact email: lluig@cimarex.com	Incident # (assigned by OCD)
Contact mailing address: 600 N Marienfeld Street, Ste. 600 Midland, TX 79701	

Location of Release Source

Latitude 32.339333_

(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Red Tank 4 Federal 1	Site Type: Battery
Date Release Discovered: 3/27/2020	API# (<i>if applicable</i>) 30-025-40534

Unit Letter	Section	Township	Range	County
D	4	23S	32E	Lea

Surface Owner: State Federal Tribal Private (Name:

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
Produced Water	Volume Released (bbls) 20 bbls	Volume Recovered (bbls) 20 bbls
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

A water hauler had pulled a load of water from the water tank and when he completed the job he forgot to disconnect his hose from the load line. When he drove off the load line pulled apart and the containment wall was damaged. The truck driver came back and recovered the 20 barrels of produced water from the lined containment. The trucking company had the line fixed, containment wall was repaired and containment cleaned. The cause of the spill was due to human error, 20 barrels of produced water were released and 20 barrels of produced water were recovered.

	Page 2 of
Incident ID	NRM2009734927
District RP	
Facility ID	
Application ID	

Was this a major	If YES, for what reason(s) does the responsible party consider this a major release?	
release as defined by		
19.15.29.7(A) NMAC?		
🗌 Yes 🖾 No		
If YES, was immediate no	ptice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?	
By: Gloria Garza		
Emailed: EMNRD OCD District 1 Spills and NM CFO Spill		

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

 \square The source of the release has been stopped.

The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Laci Luig	Title: Engineer Tech
Signature: <u>Ac</u>	Date: 4/2/2020
email: lluigcimarex.com	Telephone: (432) 571-7810
OCD Only	
Received by:Ramona Marcus	Date:4/6/2020

Page 2