

From: [Eads, Cristina, EMNRD](#)
To: "natalie@energystaffingllc.com"
Cc: [Mike EMNRD Bratcher \(mike.bratcher@state.nm.us\)](#); [Robert EMNRD Hamlet \(Robert.Hamlet@state.nm.us\)](#); [Victoria EMNRD Venegas \(Victoria.Venegas@state.nm.us\)](#)
Subject: NRH2002849703 HUBER FEDERAL #10 CTB @ 30-015-44848
Date: Friday, August 14, 2020 5:07:00 PM
Attachments: [image001.png](#)

NRH2002849703 HUBER FEDERAL #10 CTB @ 30-015-44848

Natalie,

The OCD has denied the submitted Closure Request C-141 for incident # NRH2002849703 for the following reason:

- Soil samples were not collected and analyzed at a lab where perforations in the liner were found. Because the liner was found to be compromised in several locations, additional investigation needs to take place to ensure soils have not been impacted.

Because the Huber Federal incident is located in a high karst potential area, soils will need to be remediated to the most stringent levels listed in Table 1 in 19.15.29 NMAC.

The Denied C-141 can be found in the online image file. Please review and make the required correction prior to resubmitting through the fee portal. If you have any questions or believe this denial is in error, please contact me prior to submitting an additional C-141.

Thank you,

Cristina Eads

Environmental Bureau

EMNRD – Oil Conservation Division

5200 Oakland Avenue NE, Suite 100

Albuquerque, New Mexico 87113

505.670-5601

email: Cristina.Eads@state.nm.us



OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.