Submit 1 Copy To Appropriate District State of New Mexico Form C-103 Office Energy, Minerals and Natural Resources Revised July 18, 2013 District I - (575) 393-6161 WELLAPINO. 1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 **30-015-**26575 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease District III - (505) 334-6178 1220 South St. Francis Dr. STATE 🖂 FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe. NM 87505 6. State Oil & Gas Lease No. District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM B-2071-28 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH GAINES WDW-3 8. Well Number: WDW-3 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator 9. OGRID Number: 15694 HOLLYFRONTIER NAVAJO REFINERY LLC 3. Address of Operator 10. Pool name or Wildcat P.O. Box 159, Artesia, NM 88210 **PENN 9691** 4. Well Location Unit Letter_N _____790 ____feet from the _____SOUTH_ line and 2250 _____feet from the _____WEST ___line Township 18S Range: 27E Section 1 County: EDDY 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3.609' GL 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A MULTIPLE COMPL PULL OR ALTER CASING CASING/CEMENT JOB DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. June 22, 2020; Day 1: Begin constant-rate injection (+/- 10%) into GAINES WDW-3 as well as the three (3) offset wells for at least 30 hours prior to shut-in of WDW-3 for falloff testing. Target rate for WDW-3 is approximately 160 gpm. Wellhead pressure will not exceed 1,400 psig. Plant personnel will record rate, volume and pressure during the constant-rate injection period to ensure steady flow for analysis. Samples of the injectate will be collected approximately every 10 hours and analyzed for pH and specific gravity. June 23, 2020; Day 2: Continue constant-rate injection into all four (4) wells. June 24, 2020; Day 3: While injection continues, run dual downhole memory gauges to test depth making flowing gradient stopes every 1,000 feet. Collect pressure data at test depth for at least 1 hour while in jecting at constant rate. Shut in WDW-3 and collect falloff data for a minimum of 30 hours. WDW-1, WDW-2 and WDW-4 will continue injection at constant rate until downhole memory gauges are pulled from WDW-3. June 25, 2020; Day 4: WDW-3 will remain shut-in while collecting falloff pressure data using downhole memory gauges. June 26, 2020; Day 5: After a minimum of 30 hours of falloff data collection, remove gauges from the well making 5-minute gradient stops every 1,000 feet. Note the top of fill will be tagged either with gauges prior to pulling from the well, or on a second run with sinker bars after gauges are removed (TBD). Conduct MIT for 30 min. minimum. Rig down wireline and return well to service. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE_Env. Spec. DATE 6/16/2020

Coll J. Chares TITLE Environmental Engineer DATE Conditions of Approval (if any): Contact Artesia DO for witnessing of bot. hole gauge install and MIT.

L.R. Dade E-mail address: _Lewis.Dade@hollyfrontier.com PHONE: 575-746-5281

6/16/2020

Type or print name

For State Use Only

APPROVEDBY: