

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	7. Unit Agreement Name
2. Name of Operator Bennett Petroleum Corp.	8. Farm or Lease Name Phelps-Dodge
3. Address of Operator Suite 630, 1580 Lincoln St., Denver, CO 80203	9. Well No. 3-Y
4. Location of Well UNIT LETTER I , 1,645 FEET FROM THE South LINE AND 4,216 FEET FROM THE West LINE, SECTION 9 TOWNSHIP 28 N RANGE 21 E N.M.P.M.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 6573' GR, 6586 KB	12. County Colfax


16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data


NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER _____ <input type="checkbox"/>	OTHER _____ <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On or about 4/15/85, move in and rig up completion unit. Run open-ended tubing to 1900'. Circulate well with 9.2 lb/gal mud from 1900' to 810'. Set 25-sack plug from 810' to 680'. Fill well with 9.2 lb/gal mud from 680' to surface. Set 10-sack cement plug with dry-hole marker at surface. Squeeze 10 sacks cement in 10 3/4" x 7" annulus. Clean up surface. Remove rig anchors. Arrange for inspection by a representative of the Commission.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED  TITLE **President** DATE **3/26/85**

APPROVED BY  TITLE **DISTRICT ADVISOR** DATE **3-29-85**

CONDITIONS OF APPROVAL IF ANY: