

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-85

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator McClellan Oil Corporation	8. Farm or Lease Name Burner Fee
3. Address of Operator P.O. Drawer 730, Roswell, NM 88202	9. Well No. 3
4. Location of Well UNIT LETTER <u>F</u> <u>2310</u> FEET FROM THE <u>North</u> LINE AND <u>2310</u> FEET FROM THE <u>West</u> LINE, SECTION <u>19</u> TOWNSHIP <u>11-N</u> RANGE <u>22-E</u> NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4904' G.L.	12. County Guadalupe

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

7/8/85: Rigged up unit.
7/9/85: Perf from 3008' - 3012' with 2 JSPF, 10 holes. Acidized with 1000 gal. 7-1/2 HCL plus additives. Swab acid to pit.
7/10/85: Swab well, no gas, no oil. Set CIBP at 2900'. Dumped 20 sx cement on top with bailer. Perf from 2692' - 2715' with .38" holes. Acidized zone with 1500 gals. 7-1/2% Claymaster. Swab back acid load - formation salt water.
7/11/85: Swab well, no hydrocarbons present. Pulled tubing, ran in hole with CIBP. Set at 2680'. Dumped 20 sx cement on top. Perf new zone at 2616' - 2622' and 2650' - 2658', 6 holes, .38". Acidized down tubing with 1200 gals. 7-1/2% Claymaster. Could not swab below 900' from surface. Salt water.
7/12/85: Swabbing, no oil or gas.
7/16/85: Pulled tubing, packer and RBP out of hole. Temporarily abandoned.

AUTHORIZATION FOR MAINTENANCE IN SHUT-IN OR TEMPORARY ABANDONMENT STATUS EXPIRES 7-26-86

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Production Engineer DATE 7/22/85
APPROVED BY [Signature] TITLE DISTRICT SUPERVISOR DATE 7-26-85
CONDITIONS OF APPROVAL, IF ANY: