

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O.Box 2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

Santa Fe, New Mexico 87504-2088

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

30-021-20235

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well

OIL
WELL ☐

GAS
WELL ☐

OTHER

CO2 Well

2. Name of Operator

Amoco Production Company

8. Well No.

191G

3. Address of operator

P.O. Box 606, Clayton New Mexico 88415

9. Pool name or Wildcat

Tubb

4. Well Location

Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line

Section 19 Township 20N Range 33E NMPM Harding County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

5050

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

Move in rig up service unit 8/11/94. Casing pressure 340 psig. Bleed down to 0 psi. Nipple up BOP. Run 2.375" tubing open ended to 2387 feet. Displace casing with gelled fluid. Run tubing, tag PBTD @ 2538 feet. Spot 40 sacks of Class "C" cement. Estimated cement top @ 1927 feet. Pull tubing, tubing landed @ 764 feet. Spot 7 sacks of Class "C" cement. Pull tubing tubing landed @ 40 feet. Circulate cement to surface with 3 sacks Class "C" cement. Nipple down BOP. Rig down move out service unit 8/12/94. Cut off well head and install PXA marker, cut off service unit anchors, clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Billy E. Prichard

TITLE

Field Foreman

DATE 08-23-94

TYPE OR PRINT NAME

Billy E. Prichard

TELEPHONE NO. (505) 374-3053

(This space for State Use)

APPROVED BY

Ry E. Prichard

TITLE

DISTRICT SUPERVISOR

DATE

9-1-94

CONDITIONS OF APPROVAL, IF ANY: