

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals, and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-021-20243

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well

OIL WELL ☐

GAS
WELL ☐

OTHER C02

2. Name of Operator

AMOCO PRODUCTION COMPANY

3. Address of Operator

P.O. Box 303, AMISTAD, NEW MEXICO 88410

7. Lease Name or Unit Agreement Name

BRAVO DOME C02 GAS UNIT

8. Well No.

2033-211G

9. Pool name or Wildcat

BRAVO DOME C02 GAS UNIT

4. Well Location

Unit Letter G : 1980 Feet From The NORTH Line and 1980 Feet From The EAST Line
Section 21 Township 20N Range 33E NMPM HARDING County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
5022

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations

SEE RULE 1103.

(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)

4/11/98

Move in, rig up service unit. Kill well with fresh water. Nipple up BOP. Run 2-3/8" workstring to 2500'. Spot 15 sacks of class C cement @ 2500'.

4/12/98

Tag top of cement at 2340'. Circulate well with mud laden fluid with inhibitor. Pressure test 4-1/2" fiberglass to 500 psi. Spot 10 sacks class C cement @ 1953' - 1806'. Spot 5 sacks of class C cement @ 30' - 3'. Cut off wellhead 3' below ground level. Dug up anchors. Cap well with steel plate. Install dry hole marker. Rig down, move out service unit. Clean and level location.

OK-8-4-98

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

[Signature]

TITLE

Field Team Leader

DATE

4/16/98

TYPE OR PRINT NAME

D. J. Holcomb

TELEPHONE NO.

(505) 374-3010

(This space for State Use)

APPROVED BY

[Signature]

TITLE

DISTRICT SUPERVISOR

DATE

8/10/98

CONDITIONS OF APPROVAL, IF ANY: