

Memo

8/15/80

From
CARL ULVOG

To John Smith

It seems as though not only won't this well (your #5) stay plugged, it won't even stay in the same place!

If you will just nail it down and tell me where that is, I'll approve the last plugging job. It is a little frustrating to keep 3 different files for the same hole - at least I hope there is only one #5.

C.U.

8/10/81 : By telephone - Smith decides that his 1980' FN+E location is wrong. Change to 990' as on C-105 but change C-105 to R-29-E.

C.U