

NEW MEXICO OIL CONSERVATION COMMISSION

SANTA FE, NEW MEXICO

MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of notice by checking below:

NOTICE OF INTENTION TO TEST CASING SHUT-OFF		NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL	
NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING	
NOTICE OF INTENTION TO REPAIR WELL		NOTICE OF INTENTION TO PLUG WELL	*
NOTICE OF INTENTION TO DEEPEN WELL			

Springer, New Mexico, Nov. 14, 1951.

Place

Date

OIL CONSERVATION COMMISSION,
Santa Fe, New Mexico.

Gentlemen:

Following is a notice of intention to do certain work as described below at the Neill Oil and Gas(CO₂)
Company Smith and Niera Well No. 1 in SWSW
Company or Operator Lease
 of Sec. 1, T. 20 E., R. 30 E., N. M. P. M., Bueyerous Gas Field.
Harding County.

FULL DETAILS OF PROPOSED PLAN OF WORK

FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS OF THE COMMISSION

Plug gas sand 30 feet above CO₂ sand with cement*. Pull casing and fill with mud. Place marker and abandon.

Surrounding leases belong to Clyde B. Neill.

* Cement 30' interval above gas sand as shown on log, approximately 800' +. Fill hole with heavy mud above cement plug to 15' below surface. Set 4' x 4" marker in 15' cement at surface.

Approved 1951, 19____
except as follows:

OIL CONSERVATION COMMISSION,

By [Signature]
Title geologist

Neill Oil and Gas(CO₂) Company,
Company or Operator

By [Signature]
Position President

Send communications regarding well to

Name Clyde B. Neill.Address Drawer # 668.Springer, New Mexico.