

Received 12/3/2014

NMOCD Artesia

Form C-141

Revised October 10, 2003

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural ResourcesOil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form**Release Notification and Corrective Action****OPERATOR**☐

Initial Report

☒


Final Report

Name of Company: Bopco, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, NM 88220	Telephone No.: (575) 887-7329
Facility Name: Poker Lake Unit 78 Tank Battery	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No.: 30-015-27536	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	25	24S	30E	660	North	660	East	Eddy

Latitude: N 32° 11' 39.37" **Longitude:** W 103° 49' 40.14"**NATURE OF RELEASE**

Type of Release: crude oil and produced water	Volume of Release: 6 bbl crude oil and 57 bbls PW	Volume Recovered: 4 bbls crude oil 6 bbls PW
Source of Release: heater treater	Date and Hour of Occurrence: 7/4/14 time unknown	Date and Hour of Discovery: 7/4/14 @ 7:40 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher NMOCD and Jim Amos BLM	
By Whom? Tony Savoie	Date and Hour: 7/4/14 @ 7:52 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
Depth to Water. ~360 ft bgs		
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* The heater treater pressured up and blew out the gasket on the bottom man-way hatch. The crews switched the production stream out of the heater treater and replaced the failed gasket.		
Describe Area Affected and Cleanup Action Taken.* The spill impacted approximately 4,516 sq. ft. of caliche pad with oil saturation ranging from 10 to 12 inches in depth. The release misted an area measuring approximately 15,400 sq. ft. in a previous remediated area that had just recently been re-seeded. The misted area averaged approximately 2" in saturation depth. All of the free standing fluid was recovered. The contaminated soil has been excavated and hauled to a state approved disposal facility and the excavation has been backfilled in accordance to the NMOCD and BLM remediation guidelines.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Brad Blevins	Approved by District Supervisor:	
Title: EHS Asst. Remediation Foreman	Approval Date: 12/10/2014	Expiration Date: NA
E-mail Address: bblevins@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10-2-14 Phone: (432) 214-3704	FINAL	

* Attach Additional Sheets If Necessary

2RP-2372