

Received 12/3/2014
NMOCD Artesia

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Bopco, L.P.	Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, NM 88220	Telephone No.: (575) 887-7329	
Facility Name: PLU-387H Tank Battery	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No.: 30-015-41185

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	18	25S	31E	526	North	418	West	Eddy

Latitude: N 32.136122 **Longitude:** W 103.824399

NATURE OF RELEASE

Type of Release: crude oil and produced water	Volume of Release: 29 bbls of crude oil and 6 bbls produced water	Volume Recovered: 20 bbls crude oil and 5 bbls water
Source of Release: flare line vent	Date and Hour of Occurrence: 1/5/14 @ 7:00 am	Date and Hour of Discovery: 1/4/14 @ 7:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Delayed report to Mike Bratcher NMOCD BLM on 1/5/14 @ 12:30 pm	
By Whom? Tony Savoie	Date and Hour: 1/7/14 @ 11:36 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	


Depth to Water. ~375 ft bgs

If a Watercourse was Impacted, Describe Fully.* Not Applicable

Describe Cause of Problem and Remedial Action Taken.* The valves on the process valves were misaligned and the flare scrubber dump failed to operate properly. The system over pressured and fluid went out the flare line vent. The system was restored to normal operations.

Describe Area Affected and Cleanup Action Taken.* Approximately 247,860 sq. ft. of pasture area was lightly misted by the release; fluid was visible on the vegetation but not on ground surface. Approximately 23,726 sq. ft. of pasture was more heavily impacted by the release; the vegetation was covered with 1-6 inches of saturation on the soil. A berm around the flare system that contained some of the fluid; approximately 25 bbls total fluid was recovered from the bermed area. The heavily impacted vegetation was washed down with soap, water and micro-blaze mixture. The area of saturated soil was excavated approximately 2 ft bgs and remediated on site using Micro-Blaze and clean soil. The excavation was backfilled with the remediated soil, treated with Micro-Blaze again, reseeded and watered. The spill will be remediated in accordance to the NMOCD and BLM recommended guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Brad Blevins	Approved by District Supervisor:	
Title: EHS Asst. Remediation Foreman	Approval Date: 12/10/2014	Expiration Date: NA
E-mail Address: bblevins@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11-26-14 Phone: (432) 214-3704	FINAL	

* Attach Additional Sheets If Necessary

2RP-2164