

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

XX Initial Report ☐ Final Report

Name of Company Key Energy Services LLC	Contact Mike Slaughter or Wayne Price-Price LLC
Address 1807 E Buckley St Brownfield Tx 79316	Telephone No. 505-715-2809
Facility Name BKE	Facility Type SWD

Surface Owner Private	Mineral Owner	API No. 30-015-23493
-----------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter H	Section 13	Township 23S	Range 27E	Feet from the 2310	North/South Line N	Feet from the 860	East/West Line E	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	-----------------------	----------------------	---------------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE


Type of Release- Produced Water & Small Amount of Skim Oil	Volume of Release: Raw Estimate 250-296***	Volume Recovered- 250 bbl's
Source of Release: Injection Pump Suction Tank	Date and Hour of Occurrence Nov 9 or 10, 2014 Night Time	Date and Hour of Discovery Nov 10, 2014, Morning Hours
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD-Artesia	
By Whom? Wayne Price-Price LLC	Date and Hour Nov 10 E-mail	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse. NA	

If a Watercourse was Impacted, Describe Fully.* NA

Describe Cause of Problem and Remedial Action Taken. Tank overflowed, possible stuck check valve, ran produced water and skim oil into berm area. It appears a small amount ran over the berm on the west side, where berm was eroded due to recent heavy rains in area. There is a visual salt stain on backside of battery. See Photos.

Describe Area Affected and Cleanup Action Taken. Key vacuum trucks picked up fluids and put back in other tanks on-site. Inside berm area has some oily & salt stain. See Photos. Note: *** The level of the spill measured about 6-8 inches and it pooled mostly on the west side inside of the berm area. Calculating the worst-case volume using 8" would be 296 barrels. So a good estimate of the release is 250-296 bbls.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
		Approved by Environmental Specialist:	
Printed Name: Wayne Price-Price LLC			
Title: NM Agent/Consultant		Approval Date:	Expiration Date:
E-mail Address: wayneprice77@Earthlink.net		Conditions of Approval:	Attached <input type="checkbox"/>
Date: Nov 19, 2014 Phone: 505-715-2809			

- Attach Additional Sheets If Necessary-Photos Attached