Report Date: October 28, 2015 Work Order: 15102201 Page Number: 1 of 1

Summary Report

Bill Dougherty Nadel & Gussman Permian LLC 601 N. Marienfeld Suite 508 Midland, TX 79701

Report Date: October 28, 2015

Work Order: 15102201

Project Location: Sec 13-18S-31E Eddy Co. NM
Project Name: South Taylor 13 Fed #1/5 St

Project Number: Heater Treater Overspray

406809	HT Westside	soil	2015-10-20	09:00	2015-10-22
Sample	Description	Matrix	Taken	Taken	Received
			Date	Time	Date

	BTEX			MTBE	TPH DRO	TPH GRO	
	Benzene	Toluene	Ethylbenzene	Xylene	MTBE	DRO	GRO
Sample - Field Code	(mg/Kg)	(mg/Kg)	(mg/Kg)	(mg/Kg)	(mg/Kg)	(mg/Kg)	(mg/Kg)
406809 - HT Westside	< 0.0200	< 0.0200	< 0.0200	< 0.0200		<50.0 Qr	<4.00 в

Sample: 406809 - HT Westside

Param	Flag	Result	Units	RL
Chloride		<250	m mg/Kg	50