

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

Initial Report  Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU 347	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-38668
------------------------	------------------------	----------------------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	<u>North</u> /South Line	Feet from the	East/ <u>West</u> Line	County
C	11	25S	30E	540		1440		Eddy

Latitude: 32.15100 Longitude: 103.85560

#### NATURE OF RELEASE

Type of Release: Crude oil and Produced Water	Volume of Release: 65 barrels crude oil and 12 barrels PW	Volume Recovered: 5 barrels crude oil and 2 barrels PW
Source of Release: 2 inch hammer union on wellhead	Date and Hour of Occurrence: 9-20-14 time unknown	Date and Hour of Discovery: 9-20-14 @ 10:50am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? First reported to EHS at 11:56am as 5 barrels crude oil floating on rain water on location. Could not access until 8:00am on 9-22-14 due to heavy flooding rains. Reported correction and release amounts to Heather in person 8:00am on 9-22-14 Tony S.	
By Whom? Tony Savoie	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
A hammer union leaked on wellhead, connection was re tightened.

Describe Area Affected and Cleanup Action Taken.\*  
The release impacted approximately 27,200 sq feet of the caliche pad and lease road, 53,700 sq feet of pasture area that was flooded with a combination of rain water and crude oil. The entire impacted area was sampled on 9-24-14. The crude oil impacted areas was treated twice with micro blace on 9-26-14. The chloride impacted area on pad was excavated and hauled to a state approved facility. A 20 mil liner was place in the floor of the excavation and backfilled with clean topsoil and caliche.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Bradley Blevins	Approved by Environmental Specialist:	
Title: Assistant Remediation Foreman	Approval Date: 2/16/2016	Expiration Date: N/A
E-mail Address: bblevins@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2-5-2016 Phone: 432-214-3704	FINAL	