

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 7/13/2016  
NMOCD Artesia

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

**OPERATOR**  Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Sterling Silver 3 Federal #6 CTB	Facility Type	Battery

Surface Owner	BLM	Mineral Owner		API No.	30-01527638
---------------	-----	---------------	--	---------	-------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	3	24S	31E					Eddy

Latitude N 32.24813° Longitude W 103.76643°

### NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	30 bbls oil, 170 bbls produced water	Volume Recovered	20 bbls oil
Source of Release	Water transfer pump malfunction caused tank spill	Date and Hour of Occurrence	03/04/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD; Sol Hughes-BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	03/05/2015		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Malfunction of a water transfer pump caused a tank to spill 30 bbls of oil and 170 bbls of produced water onto the ground. A vacuum truck recovered 20 bbls of oil and the pump was repaired/reset.

Describe Area Affected and Cleanup Action Taken.\*  
The affected area is approximately 50' x 50' on location within the containment area. Remediation was completed in accordance with a remediation plan approved by Mike Bratcher of NMOCD via email on 8/19/2015 and by Shelly Tucker of the BLM via email on 08/19/2015.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Casey Summers	Approved by District Supervisor:		
Title: NM Environmental Advisor	Approval Date: 7/14/2016	Expiration Date: N/A	
E-mail Address: Casey_Summers@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 7-11-16	Phone: (575) 513-8289	FINAL	

\* Attach Additional Sheets If Necessary