

August 17, 2016

Mike Bratcher New Mexico Energy, Minerals & Natural Resources Oil Conservation Division, Environmental Bureau - District 2 811 S. First St. Artesia. NM 882L0

RE: Closure Report Burnett Oil Co., Inc. - Stevens A Tank Battery UL/H sec. 14 T17S R30E

Mr. Bratcher

The above location is located approximately 2 miles northeast of Loco Hills, New Mexico at UL/M sec. 13 T17S R30E. The site is located in an area of no known groundwater.

On February 3, 2016 a release was discovered of 3 barrels of crude oil and 437 barrels of produced water. We were able to recover approximately 400 barrels of total fluid. The release occurred when a loss of power occurred at the location, which caused the tanks to overflow. The release impacted a 60' x80' area within the firewall of the facility. The BLM and the NMOCD were both notified of the release on February 3, 2016 with the initial C-141 being filed on the same day.

Corrective Action Plan

On February 9, 2016 Burnett Oil Co., Inc. enlisted Trinity Oilfield services to excavate the surface of the impacted area to a depth of approximately 6'' - 1'. The impacted material was hauled to Lea Land Disposal. To remediate the impacted soil, Burnett Oil Co., Inc. enlisted the services of Aspen Grow LLC. to apply Probiotic compounds to the impacted area. The probiotics were applied with fresh water to the impacted area once a week for four weeks. In that time the probiotics and the fresh water was able to begin remediating the chlorides and hydrocarbons in the impacted area, with the exception of SP-3. The area of SP-3 was the lowest spot in the facility, and was excavated to a depth of 1' before the application of the probiotics.



August 17, 2016

Closure Report

As per our conversation on August 3, 2016, Burnett Oil Co., Inc. request to defer the remaining remediation until abandonment of the location. Further excavation of the impacted area could result in a negative effect on the integrity and stability of the facility and it's components.

Following the approval of the plan, Burnett Oil Co., Inc. will submit all the proper documentation to the NMOCD and the BLM in accordance to the State and Federal guidelines set forth.

Please feel free to contact me with any questions concerning this remediation plan request.

Sincerely,

Johnny Titsworth HSE Coordinator Burnett Oil Co., Inc. P.O. Box 188 / CR 220 North Loco Hills, NM 88255 (432)-425-2891 Email: jtitsworth@burnettoil.com

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

API No. 30-015-38373

Release Notification and Corrective Action

OPERATOR	Initial Report	Х	Final Report
Contact: Johnny Titsworth		-	
Telephone No. (432) 425-2891			
Facility Type: Tank Battery			
	Contact: Johnny Titsworth Telephone No. (432) 425-2891	Contact: Johnny Titsworth Telephone No. (432) 425-2891	Contact: Johnny Titsworth Telephone No. (432) 425-2891

Surface Owner: BLM	Surface	Owner:	BLM
--------------------	---------	--------	-----

LOCATION OF RELEASE

Mineral Owner: BLM


Unit LetterSectionTownshipRangeFeet from theNorth/South LineFeet from theEast/West LineCountyM1317S30E1219South54WestEddy					LUCI		
	Unit LetterSecM13	3	1	Range 30E		Feet from the 54	5

Latitude: <u>32.82253</u> Longitude: <u>-103.93016</u>

NATURE OF RELEASE

Type of Release: Oil/Water	Volume of Release: 3/437 bbls		covered: 400 bbls water							
Source of Release: power loss / tank overflow	Date and Hour of Occurrence:	our of Discovery:								
	2/3/16	2/3/16								
Was Immediate Notice Given?	If YES, To Whom?									
X Yes 🗌 No 🗌 Not Required	BLM – S. Tucker & OCD – H. Pat	terson								
By Whom? Leslie Garvis	Date and Hour: 2/3/16 @ 12:00 pn									
Was a Watercourse Reached?	If YES, Volume Impacting the Wat	tercourse.								
Yes X No										
If a Watercourse was Impacted, Describe Fully.*										
N/A										
N/A										
Describe Cause of Problem and Remedial Action Taken.*										
Loss of power at facility caused tanks to overflow										
Loss of power at facility caused tanks to overflow										
Describe Area Affected and Cleanup Action Taken.*										
60' x 80' area within the firewall. All standing fluid has been recovered.	Area will be sampled and remediated									
I hereby certify that the information given above is true and complete to t	he best of my knowledge and understa	and that pursu	ant to NMOCD rules and							
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger										
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability										
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health										
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other										
federal, state, or local laws and/or regulations.										
OIL CONSERVATION DIVISION										
Signature:										
Approved by Environmental Specialist:										
Printed Name: Johnny Titsworth	rippioted by Entrionmental Special									
		Dentire the D								
Title: HSE Coordinator	Approval Date:	Expiration D	ate:							
E-mail Address: jtitsworth@burnettoil.com	Conditions of Approval:									
	Attached									
Date: Phone: (432) 425-2891										

* Attach Additional Sheets If Necessary



Rite in the Rain.

2

GGGGGG BURNETT OIL CO, INC.

Location: Stevens A Tank Battery

Ч

page

Table 1 - Analytical Results

Sample ID	Depth	Chloride	TPH - GRO TPH - DRO	TPH - DRO	Benzene	Toluene	Toluene Ethylbenzen	Xylene	BTEX
	0-1'	2000	783	3210	-				
	1'-1.5'	453							
	2'-2.5'	79							
	3'-3.5'	128							
	4'-4.5'	235							
	0-1'	916	1090	8450					
	1'-1.5'	1030	871	3740	18				
	2'-2.5'	1350	348	976					
	3'-3.5'	1020							
	4'-4.5'	1110							
	0-1'	7710	QN	QN	QN	QN	QN	QN	QN
	1'-1.5'	13400		×					

			_									
~	1		ВТЕХ				ND					
DARP) 0 3		Xylene				QN					
			Ethylbenzene				ŊŊ					
k Batterv			Toluene				DN					
Stevens A Tank Batterv		sults	Benzene		2		DN				5	
l ocation:		tical Re	TPH - DRO				190			e.		
		1 - Analytical Results	TPH - GRO				ND	8				
		Table 1	Chloride	12400	12600	9670	970	209	751	1100		
			Depth	2'-2.5'	3'-3.5'	4'-4.5'	0-1'	1'-1.5'	2'-2.5'	3'-3.5'		
GGGGGG			Sample ID	SP-3		e e	SP-4					
3			Date	4/28/2016	4/28/2016	4/28/2016	4/28/2016	4/28/2016	4/28/2016	4/28/2016		