

Bratcher, Mike, EMNRD

From: Blaney, Karolina <Karolina.Blaney@wpxenergy.com>
Sent: Friday, December 23, 2016 11:58 AM
To: Weaver, Crystal, EMNRD
Cc: Bratcher, Mike, EMNRD; Tucker, Shelly (stucker@blm.gov)
Subject: RE: WPX RDU 11 - C-141
Attachments: RDU 11 Characterization Plan.pdf

Good morning Crystal,
Attached is the characterization plan for the RDU 11 spill.
Please let me know if you have any questions or suggestions.
Thank you and have a great Christmas!!!

Karolina Blaney
Environmental Specialist
WPX Energy
Office: (575) 885-7514
Cell: (970) 589-0743
karolina.blaney@wpxenergy.com

From: Patterson, Heather, EMNRD [mailto:Heather.Patterson@state.nm.us]
Sent: Thursday, December 01, 2016 1:24 PM
To: Blaney, Karolina <Karolina.Blaney@wpxenergy.com>
Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Tucker, Shelly (stucker@blm.gov) <stucker@blm.gov>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>
Subject: RE: WPX RDU 11 - C-141

RE: WPX * RDU #11 * 30-015-24307 * 2RP-4001

Karolina,

Attached are the Conditions of Approval for this C-141 Remediation Permit. The OCD tracking number for this event is 2RP-4001.

Thank you,

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

From: Blaney, Karolina [mailto:Karolina.Blaney@wpxenergy.com]
Sent: Thursday, November 17, 2016 2:26 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; 'stucker@blm.gov'
Subject: RE: WPX RDU 11 - C-141

Attached is C-141 for the RDU 11 spill.
Thank you and have a great afternoon,

Karolina Blaney

Environmental Specialist

WPX Energy

Office: (575) 885-7514

Cell: (970) 589-0743

karolina.blaney@wpxenergy.com

From: Blaney, Karolina

Sent: Sunday, November 06, 2016 11:09 AM

To: 'Patterson, Heather, EMNRD' <Heather.Patterson@state.nm.us>; 'Bratcher, Mike, EMNRD' <mike.bratcher@state.nm.us>; 'stucker@blm.gov' <stucker@blm.gov>

Subject: WPX RDU 11 - spill notification

Good morning,

Yesterday, 11/5/16, WPX had a spill at the RDU 11 well pad, API # 30-015-24307; T26S R30E S22. The cause of this spill is equipment failure. A pump air locked causing tank to overfill. 66 bbls of oil was recovered from a dirt SPCC containment berm; none of the fluids have left the containment. The C-141 report will be submitted within 15 days from the incident. Please let me know if you have any questions or concerns.

Thank you and have a great Sunday.

Karolina Blaney

Environmental Specialist

WPX Energy

Cell: (970) 589-0743

karolina.blaney@wpxenergy.com