

From: Patterson, Heather, EMNRD
To: "adriann@pegasusplace.com"; [Sanchez, Daniel J., EMNRD](#)
Cc: [Bayliss, Randolph, EMNRD](#); [Bratcher, Mike, EMNRD](#); [Griswold, Jim, EMNRD](#); agroves@slo.state.nm.us; "[Kasuboski, Robert](#)"
Subject: FW: Ledbetter well
Date: Wednesday, August 10, 2016 10:51:00 AM
Attachments: ATT00001.txt
ATT00002.txt
ATT00003.txt
ATT00004.txt
ATT00005.txt

Ms. Ragsdale,

I appreciate you talking with me this morning. Please see the attached photos of the Leonard State #2 well (30-015-03543). The tank on location has been leaking, and according to witnesses, production has resumed at this location. It also appears as though a cleanup is underway, but the OCD has not received a spill report.

Also noted in the complaint are three old tanks that have been dumped to the east of this location. The assumption is these are associated with the Jim Pierce wells and have been placed there by Buddy DeLong.

Several other Jim Pierce Wells have environmental concerns, both historic and recent as wells are being readied to go back into production by Mr. DeLong.

Thanks,

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

-----Original Message-----

From: Kasuboski, Robert [<mailto:rkasuboski@slo.state.nm.us>]
Sent: Monday, August 08, 2016 11:44 AM
To: Groves, Amber
Cc: Patterson, Heather, EMNRD
Subject: Ledbetter well

Howdy.

Ranch foreman stopped me for this one. SESW sec 1 19s 29e. Started pumping old well in last couple weeks. Tank leaking at inspection hatch. Also 3 old tanks dropped on old pad a couple hundred yards to the east of here.

Robert

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>
