

Bratcher, Mike, EMNRD

From: Price, Henryetta <hprice@blm.gov>
Sent: Wednesday, May 10, 2017 1:53 PM
To: Christine Alderman
Cc: Billings, Bradford, EMNRD; Weaver, Crystal, EMNRD; Bratcher, Mike, EMNRD; James Amos
Subject: Re: Pintail 23 Fed #8

Good Afternoon Christine,

Due to the length of time that the contaminants have been left on location, I am going to require a confirmation sample 2 ft. below the excavation to ensure that migration did not occur. In addition to that, the proposed amount of soils to be removed/remediated will be excavated in 14 days. For this location, I was mostly waiting on feedback from NMOCD and in the future will probably request to have contaminated soils picked up within 30 days if no work plan is in place and/ or remediation not completed within 45 days.

Please let me know if you have any issues or concerns. Thank you.

Henryetta Price

Environmental Protection Specialist
Bureau Of Land Management
Hprice@blm.gov
Phone 575-234-5951
Cell 575-706-2780
Fax 575-234-5927

*Please remember that Lesser Prairie Chicken timing stipulations are in effect 01 Mar- 15 June Annually

On Wed, May 10, 2017 at 12:56 PM, Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us> wrote:

RE: Cimarex Energy * Pintail 23 Fed Com 8H * 30-015-38657 * 2RP-4006 * DOR: 11/20/16

Christine,

After further review of the above referenced release site, and the proposed soil washing procedure for remediation of the impacted material, OCD does **not** approve the soil washing method in this instance. Given the potential for encountering ground water at less than 50', the site is also situated in a BLM mapped "High Karst Potential" area. OCD would encourage submittal of a similar proposal for a release occurrence at a more suitable location for this method of remediation. At this time, please submit an alternative remediation method for this release.

Thank you,

Mike Bratcher

NMOCD District 2

811 South First Street

Artesia NM 88210

575-748-1283 Ext 108

mike.bratcher@state.nm.us

From: Bratcher, Mike, EMNRD

Sent: Wednesday, May 3, 2017 1:26 PM

To: 'Christine Alderman' <calderman@cimarex.com>

Cc: Price, Henryetta <hprice@blm.gov>; Billings, Bradford, EMNRD <Bradford.Billings@state.nm.us>;
Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>

Subject: RE: Pintail 23 Fed #8

RE: 2RP-4006

Christine,

OCD is reviewing several soil washing proposals, and this is one of them. I do have some questions on this one in particular and will get those to you as soon as I get some more input from our group.

Thanks,

Mike Bratcher

NMOCD District 2

811 South First Street

Artesia NM 88210

575-748-1283 Ext 108

mike.bratcher@state.nm.us

From: Christine Alderman [<mailto:calderman@cimarex.com>]

Sent: Wednesday, May 3, 2017 10:21 AM

To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>

Cc: Price, Henryetta <hprice@blm.gov>

Subject: FW: Pintail 23 Fed #8

Mr. Bratcher,

I was wondering if you have had a chance to review the attached workplan.

Thank you!

Christine Alderman

Cimarex Energy Co.



ESH Supervisor – Permian Basin

Midland TX

Cell – 432.853.7059

From: Christine Alderman
Sent: Friday, April 14, 2017 10:54 AM
To: mike.bratcher@state.nm.us
Cc: Price, Henryetta <hprice@blm.gov>
Subject: Pintail 23 Fed #8

Mr. Bratcher,

Please find attached the revised workplan for the Pintail location. We have included the requested leak detection portion.

Thank you, and please let me know if you have any further concerns.

Christine Alderman

Cimarex Energy Co.



ESH Supervisor – Permian Basin

Midland TX

Cell – 432.853.7059