

Bratcher, Mike, EMNRD

From: Baker, Larry <Larry.Baker@apachecorp.com>
Sent: Tuesday, May 30, 2017 9:59 AM
To: 'rpair@blm.gov'; Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD
Subject: Lab Analysis for 2RP-3749
Attachments: H701143R EPI.pdf; H701151 EPI.pdf

All,

Apache has completed the 4 foot excavation around sample point 2 in accordance with the approved corrected action plan. Attached is the confirmation lab analysis for the excavation. The lab consists of two lab reports the samples collected on 4/28/2017 are confusing due to sample technician labeled the sidewalls in numerical order instead of north, west, and south wall. Sample point 2 is the west wall, sample point 3 is the north wall and we were collecting samples as we performed the excavation on the south wall to ensure the contamination was remove so sample point 8 is the south wall. The second lab report reflects samples collected on 5/1/2017 for the bottom of the excavation and the east wall. Upon your review and approval Apache Corporation request permission to backfill the excavation and seed the location to complete remediation activities. Once site is backfilled and seeded a termination report and final C-141 will be submitted. Please let me know if you have any questions or wish to discuss. Thanks and have a good day.

Bruce Baker
Apache Corporation
Environmental Technician
Northwest District
Email: larry.baker@apachecorp.com
Mobile: 432-631-6982