

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nMLB0610137549

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street	Telephone No. 505-748-1471	
Facility Name State D SWD #1	API Number 30-015-21572	Facility Type Battery-SWD Site
Surface Owner State	Mineral Owner State	Lease No. V-2531


LOCATION OF RELEASE

Unit Letter N	Section 16	Township 20S	Range 24E	Feet from the 660	North/South Line South	Feet from the 1980	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.56807 Longitude 104.59483

NATURE OF RELEASE

Type of Release Crude Oil and Produced Water/Iron Sulfide	Volume of Release 15 B/O & 5 B/PW	Volume Recovered 0 B/O & 0 B/PW
Source of Release Gun Barrel	Date and Hour of Occurrence 3/12/2006 PM	Date and Hour of Discovery 3/12/2006 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Power failure caused by high winds resulted in controller on motor to malfunction which subsequently caused gun barrel to run over. Controller replaced and put back into service.		
Describe Area Affected and Cleanup Action Taken.* Water containing iron sulfide and oil sprayed tanks and a large area on location and surrounding pasture. No Pooling occurred. Depth to Ground Water: >100', Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Requested Work Plan: Wash tanks with a solution of Microblaze and water and vacuum up solution as washing occurs. Microblaze areas contacted by oil/iron sulfide mist.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Final was not approved at time of submittal	
Title: Environmental Regulatory Agent	Approved by District Supervisor:	
E-mail Address: boba@ypcnm.com	Approval Date:	Expiration Date:
Date: Thursday, September 21, 2006	Conditions of Approval:	Attached <input type="checkbox"/>
Phone: 505-748-1471		

* Attach Additional Sheets If Necessary

2RP-79