District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 OCD Rec'd: 09/05/18

Form C-141 Revised April 3, 2017

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

## **Release Notification and Corrective Action**

				(	<b>OPERAT</b>	OR		Initia	l Report	$\boxtimes$	Final Report		
Name of Company OXY USA INC						Contact WADE DITTRICH							
Address 1017 W. Stanolind, Hobbs, NM 88240						Telephone No. 575-390-2828							
Facility Name CEDAR CANYON 21-22 FED COM 33H						acility Typ	e WELL						
Surface Owner FEDERAL Mineral Owner						FEDERAL API No. 30-015-44133							
				LOCAT	ION	OF REI	EASE						
Unit Letter	Section	Township	Range	Feet from the N	North/S	South Line						У	
L	21	24S	29E	1754	SO	UTH	374	N	/EST	EDDY			
Latitude_32.200600_ Longitude103.996693_ NAD83													
					RE (	OF RELI							
Type of Release OIL & PRODUCED WATER						Volume of Release 10 BBLS OIL Volume Ro 40 BBLS PRODUCED WATER 30 BBLS I				ecovered PRODUCED WATER			
Source of Release 4" POLY FLOWLINE FAILURE						Date and Hour of Occurrence Date and F 11/10/2017 11/11/201				Hour of Discovery			
Was Immediate Notice Given?						If YES, To Whom?							
✓ Yes ☐ No ☐ Not Required						MIKE BRATCHER-NMOCD; MARIA PRUITT-NMOCD; SHELLY TUCKER-BLM							
By Whom? WADE DITTRICH						Date and Hour 11/11/2017 @ 6:39 PM							
Was a Watercourse Reached?  ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.							
If a Watercou	rse was Im	nacted Descri	he Eully 4	<b>t</b>									
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	, , , , , , , , , , , , , , , , , , , ,											
Describe Cause of Problem and Remedial Action Taken.*													
The release w	as caused b	ov a 4 inch po	olv flow l	ine failure-leak is	60 ft f	from wellhe	ead-leak left loc	ation.	Polv line w	as fixed and	d return	ed to service.	
	The release was caused by a 4 inch poly flow line failure-leak is 60 ft from wellhead-leak left location. Poly line was fixed and returned to service.												
Describe Are	a Affected a	and Cleanup A	Action Tak	en.*									
The affected	l area was	10v1006 (m	eacurem	ents are subject to	chana	a with GDS	tracking) Dan	nadintic	an will be	nompleted	in acc	ordance	
											III acci	ordance	
with a remediation plan approved by the NMOCD and the BLM. REMEDIATION COMPLETED – 2RP-4489													
I hereby certi	fy that the i	nformation gi	ven above	is true and complete	e to the	e best of my	knowledge and u	ndersta	nd that purs	uant to NM	OCD n	ales and	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger													
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
				tance of a C-141 rep									
federal, state,	or local lay	ws and/or regu	lations.										
Signature: WADE DITTRICH						OIL CONSERVATION DIVISION							
						11111							
						Approved by Environmental Specialist:							
						Approval Date: 09/10/18 Expiration Date: N/A							
Title: ENVIROMENTAL COORDINATOR						Approval Date: 09/10/18 Expiration			Date: IN/A				
E-mail Addre	E-mail Address: wade_dittrich@oxy.com					Conditions of Approval:			Attached				
	8/27/2018	. 70 57	_	none: 575-390-282	28	Like App	oroval BLM						
Attach Addi A#:pAB173	Attach Additional Sheets If Necessary A#:pAB1732448348												