District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAB1914841996
District RP	2RP-5448
Facility ID	
Application ID	pAB1914841760

## **Release Notification**

## **Responsible Party**

Responsible Party XTO Energy				OGRID 5380		
Contact Name Kyle Littrell				Contact Telephone 432-221-7331		
Contact email Kyle_Littrell@xtoenergy.com				Incident #	(assigned by OCD) NAB1914841996	
Contact mailing address 522 W. Mermod, Carlsbad, NM 88220						
Location of Release Source						
Latitude 232.336089 Longitude 1-103.831974 [NAD 83 in decimal degrees to 5 decimal places]						
Site Name James Ranch Unit #36 Battery			-	Site Type DCP gas line at Bulk Storage and Separation Facility		
Date Release Discovered 5/10/2019				API# (if applicable) 30-015-27686 (JRU 36)		
Unit Letter Section	Township	Range	,	Coun	ity.	
G 1	238	30E		Eddy		
0 1	255	301			y	
Surface Owner:   State   I	Federal 🗌 Tri	bal Private (N	/ame: _	BLM	)	
Nature and Volume of Release						
Material(s) R	Released (Select all		calculation	ns or specific	justification for the volumes provided below)	
	olume Released	3.07			Volume Recovered (bbls) 2.50	
Produced Water Vo	Volume Released (bbls) 33.24				Volume Recovered (bbls) 22.50	
Is the concentration of total dissolved sol in the produced water >10,000 mg/l?				ls (TDS)	☐ Yes ☐ No	
	Volume Released (bbls)				Volume Recovered (bbls)	
☐ Natural Gas Vo	ral Gas Volume Released (Mcf)				Volume Recovered (Mcf)	
Other (describe)	Volume/Weight Released (provide units)				Volume/Weight Recovered (provide units)	
Cause of Release						
A contract excavator struck an unmarked buried low pressure DCP poly gas line while performing work for XTO. Fluids were released to the well pad and lease roads. DCP was previously unaware of their line in this area and crimped the line in order to stop the leak until repair can be made. A vacuum truck recovered free fluids. Additional third party resources have been retained to assist with remediation.						

## State of New Mexico Oil Conservation Division

Incident ID	NAB1914841996	
District RP	2RP-5448	
Facility ID		
Application ID	pAB1914841760	

Was this a major	If YES, for what reason(s) does the response	onsible party consider this a major release?					
release as defined by		'					
19.15.29.7(A) NMAC?	An unauthorized release of a volume of 2	5 barrels or more					
☐ Yes ☐ No							
********							
		hom? When and by what means (phone, email, etc)?					
Notice provided by Bryan Foust to Mike Bratcher, Rob Hamlet, Victoria Venegas, and Jim Griswold (NMOCD), Jim Amos, Crystal							
Weaver, and Deborah McKinney (BLM) on 5/10/2019 by email							
<del></del>							
	Initial R	esponse					
The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury							
★ The source of the rele	ase has heen stopped						
li'	s been secured to protect human health and	I the environment					
	•	dikes, absorbent pads, or other containment devices.					
		•					
	coverable materials have been removed an						
	above have <u>not</u> been undertaken, explain	why:					
N/A							
Dog 10 15 20 9 D (4) ND 4	A C 4l-	La Caracteria Caracter					
		remediation immediately after discovery of a release. If remediation efforts have been successfully completed or if the release occurred					
within a lined containment	t area (see 19.15.29.11(A)(5)(a) NMAC),	blease attach all information needed for closure evaluation.					
		best of my knowledge and understand that pursuant to OCD rules and					
		fications and perform corrective actions for releases which may endanger					
public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have							
failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws							
and/or regulations.	a C-141 report does not reneve the operator of	responsibility for compliance with any other rederal, state, or local laws					
Printed Name: Kyle Littre	ıı 🗾	Title: SH&E Supervisor					
Printed Name:	-1-	Title:					
Signature	thereof	Date: 5/24/2019					
. Kyle Littrell@xtoe	energy com						
email:	JERTON . SVAA	Telephone: 432-221-7331					
OCD Only							
Received by:	Amplio Detamento	Date: 5/28/2019					
received by.	filming fixensusive	Date					