

Liner Integrity Inspection - Photos attached	
Date: 1/27/2020  Facility: 6NDER WIGGINS FED Com 26 1H 2H 3  48-Hour Notification Given On: 1/23/2020	3H CTB
Responsible party has Visually inspected the liner	Ø/N
Liner Remains Intact	Ø/N
Liner had the ability to contain the leak in question	$\left( \widehat{Y} \right) N$
Notes:  16 photos attoched.  1 area for repair - DOES NOT COMPROMIZE LINER ABILITY TO CONTAIN LARGE SPILLS On East Containment wall, Starts I feat from liner buse, along liner Seam.  upon additional inspection, the failure mentioned above was not as failure as when repairs were attempted - there was a portion of siding that overlaps behind where the two sheets are bolted together	
Company Representative (s)  Shape Ham VESTER  Shull Hall The Company Representative (s)	_



(218) 724-1322 (701) 225-7847 wescominc.com

## **Liner Inspection Photos – Ender Wiggins Fed Com 25 CTB**













(218) 724-1322 (701) 225-7847 wescominc.com







(218) 724-1322 (701) 225-7847 wescominc.com







(218) 724-1322 (701) 225-7847 wescominc.com








(218) 724-1322 (701) 225-7847 wescominc.com











Safely serving the best companies with unmatched quality and service









