

Venegas, Victoria, EMNRD

From: Hamlet, Robert, EMNRD
Sent: Monday, August 24, 2020 2:01 PM
To: Gloria Garza; Bratcher, Mike, EMNRD; Venegas, Victoria, EMNRD; BLM SPILL (blm_nm_cfo_spill@blm.gov)
Cc: Laci Luig
Subject: RE: Cimarex Reportable Spill - Hayduke 34 Federal 1 - 3.26.2020

Gloria,

If Cimarex has demonstrated liner integrity after the affected material has been removed and the affected area of the liner is exposed, you are welcome to back fill. Please include liner integrity report and pictures in final closure submission.

Thank you,

Robert J Hamlet
State of New Mexico
Energy, Minerals, and Natural Resources
Oil Conservation Division
811 S. First St., Artesia NM 88210
(575) 748-1283
Robert.Hamlet@state.nm.us

From: Gloria Garza <ggarza@cimarex.com>
Sent: Monday, August 24, 2020 11:33 AM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>; BLM SPILL (blm_nm_cfo_spill@blm.gov) <blm_nm_cfo_spill@blm.gov>
Cc: Laci Luig <lluig@cimarex.com>
Subject: [EXT] RE: Cimarex Reportable Spill - Hayduke 34 Federal 1 - 3.26.2020

All,

We have removed the gravel in the area where the spill occurred and exposed the liner for inspection. We are requesting a field visit to inspect the liner and give permission to back fill. Attached are pictures showing the exposed liner and that the liner is intact.

Gloria Garza
432.234.3204

From: Gloria Garza
Sent: Friday, March 27, 2020 4:56 PM
To: 'mike.bratcher@state.nm.us' <mike.bratcher@state.nm.us>; Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>; BLM SPILL (blm_nm_cfo_spill@blm.gov) <blm_nm_cfo_spill@blm.gov>

Cc: 'Griswold, Jim, EMNRD' <Jim.Griswold@state.nm.us>

Subject: Cimarex Reportable Spill - Hayduke 34 Federal 1 - 3.26.2020

All,

We had a release at the Hayduke 34 Federal 1H last night. The 2" ball valve right before the water transfer pump washed out from the inside due to corrosion, spilling 32 bbls of produced water in the gravel lined containment. We recovered 30 barrels of produced water and the valve has been replaced. We will remove gravel to inspect the liner, make sure the liner is intact and request an inspection from the NMOCD and BLM before replacing the gravel.

Well Details

API: 30-015-36601

Well Name: HAYDUKE 34 FEDERAL #001

Operator: CIMAREX ENERGY CO. OF COLORA

Pools: [96890] SAGE DRAW;WOLFCAMP, E

ULSTR: A-34-25S-26E

Footages: 800 FNL & 660 FEL

A C-141 will be submitted online for the OCD and submitted by email for the BLM.

Please call if you have any questions.

Thank you,

Gloria Garza
432.234.3204

From: XEC Apps <DONOTREPLY_DEVAPPS@cimarex.com>

Subject: New Incident Created

New Incident Created 24181

PDF Report

Incident Type: Spill

Sub Type: N/A

Severity Level: Level 2

District: Permian Basin-Northwest

Department: Production

Property Name: HAYDUKE 34 FEDERAL 1H

Reported By: Mario Reyes

Reported By Phone Number: 5759883738

Incident Time: 3/26/2020 10:30 PM

Completed By: Lonnie Hernandez on 03/27/2020

Contractor Involved: No

Operation

Normal

Cause of Spill: Corrosion

Material: Produced Water

Spilled: 32 Barrels (bbls)

Recovered: 30 Barrels (bbls)

Was Spill Contained: Yes

Is Containment Lined: Yes

Description

2" ball valve right before the water transfer pump washed out from the inside due to corrosion, spilling 32 bbls of pw in the gravel lined containment.

Comment

Leak has been picked up and valve has been replaced. Water transfer pump is back in service.

Automated Message Sent By Radar: <https://apps.cimarex.com/Radar/usersetup>