

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

|   |
|---|
| WELL API NO.<br><b>30-015-29930</b>   |
| Indicate Type of Lease<br>STATE <input type="checkbox"/> FEE <input type="checkbox"/> |
| State Oil & Gas Lease No.   |
| Lease Name or Unit Agreement Name<br><b>Coyote 21</b>                                 |
| Well No.<br><b>1</b>  |
| Pool name or Wildcat<br><b>Cedar Canyon Delaware</b>                                  |

|  |   |
|--|---|
| <b>SUNDRY NOTICES AND REPORTS ON WELLS</b><br>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)        |   |
| Type of Well:<br>OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>   | <b>RECEIVED</b><br><b>MAR 19 2004</b><br><b>OCD-ARTESIA</b> |
| Name of Operator<br><b>Pogo Producing Company</b>  |   |
| Address of Operator<br><b>P. O. Box 10340, Midland, TX 79702-7340</b>  |   |
| Well Location<br>Unit Letter <b>K</b> : <b>2310</b> Feet From The <b>South</b> Line and <b>2310</b> Feet From The <b>West</b> Line<br>Section <b>21</b> Township <b>24S</b> Range <b>29E</b> NMPM <b>Eddy</b> County |   |
| Elevation (Show whether DF, RKB, RT, GR, etc.)   |   |

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: **Add Perfs** ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

02/20/04 POOH w/ rods, pump & tbg. Set CIBP @ 5197'. Perf Delaware 5006-16 w/ 2 spf. Test CIBP to 3000# ok.  
02/23/04 Acdz w/ 1000 gals 7-1/2% acid. Swab.  
02/25/04 Perf Delaware 4876-98 w/ 2 spf. TIH w/ RBP & set @ 4940'. Test to 3000# ok. Acdz w/ 1100 gals 7-1/2% acid. Swab.  
03/02/04 Frac 4876-98 w/ 23,550# 16/30 SLC. Swab.  
03/05/04 Return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Cathy Wright TITLE Sr. Operation Tech DATE 03/17/04  
TYPE OR PRINT NAME Cathy Wright 432-685-8100 TELEPHONE NO.

(This space for State Use)

**MAR 29 2004**

APPROVED BY FOR RECORDS ONLY TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: