

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1940, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-005-63301
5. Lease Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 26827
7. Lease Name or Unit Agreement Name Willow Springs "16" State
8. Well No. 1
9. Pool name or Wildcat 149441

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input checked="" type="checkbox"/>	RECEIVED
2. Name of Operator Reliance Energy, Inc.	DEC 1 5 2003
3. Address of Operator 6 Desta Drive, Suite 5500, Midland, TX 79705	OCD-ARTESIA
4. Well Location Unit Letter N : 660 Feet From The South Line and 1980 Feet From The West Line Section 16 Township 4S Range 25 E NMPM Chaves County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3864' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1101.

11/19/03 Set 5-1/2" CIBP @ 3688' run dumpbailer and cap w/ 35' of cmt. TOC @ 3653'.
11/19/03 Circulate hole w/ 10# mud.
11/19/03 Spot 30 sx cmt. from 2000' to 1704' WOC & tag TOC @ 1685'.
11/19/03 Spot 30 sx cmt. from 1673' to 1377'.
11/20/03 Shot 5-1/2" csg. @ 960', could not pull csg. Pressure up to 1000 PSI on csg. cut and held. Spot 25 sx cmt. from 1012' to 762' WOC & tag TOC @ 757'.
11/20/03 Cut and pull 5-1/2" csg. from 529'.
11/20/03 Spot 30 sx cmt. from 582' to 435' WOC & tag TOC @ 442'.
11/21/03 Spot 25 sx cmt. from 60' to surface WOC & tag TOC @ surface.
11/21/03 Cut off wellhead and install dry hole marker, clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R. Massey TITLE Agent DATE 11-25-03
TYPE OR PRINT NAME Roger Massey TELEPHONE NO. 432-530-0907

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep ID DATE APR 5 2004

CONDITIONS OF APPROVAL, IF ANY:



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop
Cabinet Secretary

Lori Wrotenberg
Director
Oil Conservation Division

15 December 2003

Reliance Energy, Inc.
6 Desta Drive, Suite 5500
Midland, Texas 79705

*P/A
OK To Release
3/29/04*
RECEIVED

FEB 23 2004

OCD-ARTESIA

Form C-103 Report of Plugging for your Willow Springs "16" State # 1 N-16-4-25 30-005-63301
Cannot be approved until an NMOCN representative has made an inspection of the location and found it to
be cleared to comply with OCD rules and regulations. Please check each item in the space provided to
indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in
concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name,
well number and location including quarter/quarter section or unit letter, section, township, range and API
well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been
cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been
leveled and cleared of all junk & equipment.
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for
plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and
returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and
approval.

[Signature]
Name

James R. Berryman

Operations Supervisor
Title

[Signature]

Van Barton
Field Rep. II