		P. C. C. COPY	ı	مر م	<i>y~</i> ,
Form 9-331 (May 1963)	TED STATES  DEPARTMENT OF THE I	SUBMIT IN TI	OR TE-	Form approve Budget Burea  5. LEASE DESIGNATION	u No. 42-R142
	GEOLOGICAL SUR	VEY		NM-04540	
SUN (Do not use this	NDRY NOTICES AND REPORT FOR PERMIT—"	ORTS ON WELLS or plug back to a different reservoir. for such propossis.)	1	O. IF INDIAN, ALLOTTEE	OR TRIBE NAM
OIL GAS WELL WELL	X OTHER	RECEIVE	-	7. UNIT AGBERMENT NA	N B
2. NAME OF OPERATOR Union Oil 3. ADDRESS OF OPERATO	Company of California	SEP 2 1 1973		8. FARM OR LEASE NAM Wersell Fede 9. Well NO.	
	71 - Midland, Texas 7970	01		1	
4. LOCATION OF WELL (Report location clearly and in accordance See also space 17 below.) At surface		th any State requirements.  ARTESIA, OFFICE		10. FIELD AND POOL, OR WILDCAT Undesignated Morrow Ga	
810° FNL	& 1980' FWL			11. SEC., T., B., M., OR BI SURVEY OR AREA	
14. PERMIT NO.	15. ELEVATIONS (Show	whether DF, RT, GR, etc.)		Sec. 4, T-225,	
	3218' GR			Eddy	N.M.
16.	Check Appropriate Box To Inc	dicate Nature of Notice, Repor	t, or Otl	ner Data	
	NOTICE OF INTENTION TO:	1	BUBBEQUE	T REPORT OF:	
TEST WATER SHUT-	OFF PULL OR ALTER CASING	WATER SHUT-OFF		BEPAIRING W	ELL
PRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	r	ALTERING CA	BING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZI	asing	ABANDONMEN'	
REPAIR WELL (Other)	CHANGE PLANS	(Other)		multiple completion o on Report and Log for	n Well
	•			cluding estimated date depths for all markers	and zones peri
9-13-73; R	" hole to 5262'. an and cemented 5236' 9-5 ulated to surface. Waite	5/8", 40#, N-80 casing	at 520	52' with 2400	sacks.
9-13-73: R	" hole to 5262'. an and cemented 5236' 9-5	5/8", 40#, N-80 casing	at 520	52' with 2400	sacks.
9-13-73: R	" hole to 5262'. an and cemented 5236' 9-5 ulated to surface. Waite	5/8", 40#, N-80 casing	at 520	52' with 2400	sacks.
9-13-73: R	" hole to 5262'. an and cemented 5236' 9-5 ulated to surface. Waite	5/8", 40#, N-80 casing	at 520	52' with 2400	sacks.
9-13-73: R	" hole to 5262'. an and cemented 5236' 9-5 ulated to surface. Waite	5/8", 40#, N-80 casing	at 520	S2' with 2400 Tested casing	sacks.
9-13-73: R	" hole to 5262'. an and cemented 5236' 9-5 ulated to surface. Waite	5/8", 40#, N-80 casing	at 520	RECEIVE SEP181973	sacks. to
9-13-73: R. Cement circ. 1500 psi fo	" hole to 5262'.  an and cemented 5236' 9-5 ulated to surface. Waite r 30 minutes. OK.	5/8", 40#, N-80 casing	at 520	rested casing  RECEIVE	sacks. to
9-13-73: R. Cement circ. 1500 psi for	" hole to 5262'.  an and cemented 5236' 9-5 ulated to surface. Waite r 30 minutes. OK.	5/8", 40#, N-80 casing	at 520	RECEIVE SEP 181973 S. GEOLOGICAL SARTESIA, NEW MI	sacks. to

\*See Instructions on Reverse Side