

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised May 08, 2003

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-015-22302
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. NM229
7. Lease Name or Unit Agreement Name VILLA
8. Well Number 1-Y
9. OGRID Number 3292
10. Pool name or Wildcat DELAWARE

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	RECEIVED MAR 29 2004 OCD-ARTESIA
2. Name of Operator C E LaRUE & B N MUNCY JR.	
3. Address of Operator P O BOX 1370 ARTESIA, NM 88211-1370	
4. Well Location Unit Letter <u>D</u> : <u>990</u> feet from the <u>NORTH</u> line and <u>380</u> feet from the <u>WEST</u> line Section <u>8</u> Township <u>23S</u> Range <u>28E</u> NMPM EDDY County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3031 GL	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

RE-PLUGGED VILLA 1-Y

03/25/04: DRILL TOP PLUG AND DRESSED OFF PLUG IN 8 5/8" CASING TO 320'. SET CAST IRON BRIDGE PLUG @ 316' AND FILLED CASING FROM 316' TO SURFICE w/100 SKS CLASS C CEMENT. INSTALL DRY HOLE MARKER. CLEAN LOCATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C E LaRUE TITLE OWNER DATE 3/26/04

Type or print name C E LaRUE Telephone No. (505) 746-2401  
(This space for State use)

APPROVED BY [Signature] TITLE Wild Sep ID DATE   
Conditions of approval



# Rotary Wire Line SERVICE, INC.

## *"Specializing in Pipe Recovery"*

P.O. Box 2735 • Phone (505) 397-6302  
HOBBS, NEW MEXICO 88241

## WORK ORDER

ME 14694

DATE 3-25-2004

P. O. NO. \_\_\_\_\_

ORDERED BY \_\_\_\_\_

WELL NAME & NO. 100-100-100

CUSTOMER E. L. LARVE, JR.

ADDRESS \_\_\_\_\_

COUNTY Edo STATE NH

[illegible]

Thank you

SUB-TOTAL

TAX

TOTAL

SERVICED BY Wade J. Krueger

WIRE LINE UNIT NO. 109

DATE COMPLETED 5-25-2004

CUSTOMER 2. Lakure oil

AUTHORIZED BY \_\_\_\_\_

**COMPANY REPRESENTATIVE**



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**

Governor

**Joanna Prukop**  
Cabinet Secretary

**Lori Wrotenbery**

Director

**Oil Conservation Division**

RECEIVED

APR 08 2004

OCD-ARTESIA

5 April 2004

C. E. Larue & B. M. Muncy Jr.  
P. O. Box 1370  
Artesia, New Mexico 88211-1370

4/14/04  
OK for  
Release  
MB

Form C-103 Report of Plugging for your Villa 1-Y D-8-23-28 API 30-015-22302  
Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Name

Title

Van Barton  
Field Rep. II