District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV

Date: March 8, 2004

* Attach Additional Sheets If Necessary

Phone: (432) 682-6324

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 2040 South Pacheco Santa Fe, NM 87505 Form C-141 Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

2040 South Pa	icheco, Santa	Fe, NM 87505										de of form	
30.015.31052			Release Notification and Corrective Action										
			OPERATOR					☐ Ini	☐ Initial Report ☐ Final Report				
Name of Company Clayton Williams Energy, Inc.							Contact□ Matt Swierc, Production Supt.						
Address Six Desta Drive, #3000, Midland, TX 79705							Telephone No. □ (432) 682-6324						
Facility Name STATE 20B #7 Facility Type□ pumping oil well													
Surface Owner State of New Mexico Mineral Owner						State of I		Lease No. □ B6846					
				LOCAT	ΓΙΟΝ (OF RELI	EASE						
						South Line Feet from the East/West Line County Edd					v		
В	20	17S	29E	330	North		2310	East		 		· J	
	NATURE OF RELEASE												
Type of Release Oil & water						Volume of Release 3-5 bbls.			Volume Recovered□				
Source of Release stuffing box leak						Date and Hour of Occurrence			Date and Hour of Discovery				
						02/23/04; 12:00 p.m.							
W. J. J. J. A. M. Alice Change							ICATEG T. HIL				02/23/04; 2:00 p.m.		
Was Immediate Notice Given? ✓ Yes No Not Required							If YES, To Whom? Mr. Jerry Guy, NM OCD Field Representative						
·													
By Whom? Phillip Creech, Production Foreman Was a Watercourse Reached?							Date and Hour 02/23/24; 2:02 p.m. If YES, Volume Impacting the Watercourse.						
was a watercourse Reacned? Yes No							A 220, Totalio impacing air Transforms.						
If a Watercourse was Impacted, Describe Fully.*													
MAR ~ 9 7004													
	Describe Cause of Problem and Remedial Action Taken.*												
Stuffing Box leaked. Repair & replace rubbers on stuffing box.													
Describe Are								**					
				l, approx. 6' L		_						İ	
							o spread soil or				lown to	clean	
soil, and turn to remediate soil so that contaminates are within guideline levels. Operation complete 3/8/04													
							knowledge and u						
							ons and perform o						
endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator													
of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for													
compliance with any other federal, state, or local laws and/or regulations.													
							OIL CONSERVATION DIVISION						
Signature: Matt Lucie / Le						TIM W. GUM							
Signature:	- gymer	e/ll	-							, 1			
Printed Name: Matt Swierc						Approved by District Part of The Prison							
						, <u>-</u>		.,. T.					
Title: Production Supt.						Approval Date: 4/28/2014 Expiration Date:							
D.4 36		TO!	(422)	(00 (004	1	One distance	-6 A			Att	tached		

Conditions of Approval: