

District I - (505) 393-6161  
P.O. Box 1980  
Hobbs, NM 88241-1980  
District II - (505) 748-1283  
811 South First  
Artesia, NM 88210  
District III - (505) 334-617  
1000 Rio Brazos Road  
Aztec, NM 87410  
District IV - (505) 827-7131

State of New Mexico  
Energy Minerals and Natural Resources Department  
Oil Conservation Division  
2040 South Pacheco Street  
Santa Fe, New Mexico 87505  
(505) 827-7131

Form C-141  
Originated 2/13/97

Submit 2 copies to  
Appropriate District  
Office in accordance  
with Rule 116 on  
back side of form.

30-015-31314

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name	Contact
OXY USA WTP Limited Partnership	Rick Kerby
Address	Telephone No.
P.O. Box 4294 Houston, TX 77210-4294	505-393-2174
Facility Name	Facility Type
Sweet and Sour #1	Battery

Surface Owner	Mineral Owner	Lease No.
State	NMOCD	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	24	17S	27E	1310	south	660	east	Eddy

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Produced Water	56	56
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Produced water tank	UNK	3:30 PM 4-4-04
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
	Van Barton	
By Whom?	Date and Hour	
Rick Kerby	4-4-04 9:05 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets if Necessary)

APR 21 2004

000-ARTESIA

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets if Necessary)

Lightning strike in vicinity of tank battery destroying fiberglass 300 bbl water tank. All water with no oil and was contained inside of tank dike. No fluid outside of tank dike.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets if Necessary)

All fluid was contained inside dike and picked up by vacuum truck. According to gauges, all fluid was picked up and hauled to disposal. With the produced fluid being contained inside dike, no testing of soil for chlorides was conducted and no further cleanup is planned. The damaged tank was removed, replaced, and battery was rebuilt.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rick Kerby</i>	OIL CONSERVATION DIVISION	
Printed Name: Rick Kerby	Approved by	TIM W. GUM
Title: HESTech	District Supervisor:	DISTRICT I SUPERVISOR - N.S.
Date: 2-3-03	Approval Date: 4/30/2004	Expiration Date:
Phone: 505-393-2174	Conditions of Approval:	Attached <input type="checkbox"/>