

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised June 10, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO 30-005-63051
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-2982
7. Lease Name or Unit Agreement Name Quincy AMQ State
8. Well Number 8
9. OGRID Number 025575
10. Pool name or Wildcat Acme San Andres SE

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Yates Petroleum Corporation

3. Address of Operator
105 S. 4th Street, Artesia, NM 88210

RECEIVED

APR 09 2004

OCD-ARTESIA

4. Well Location

Unit Letter F : 2,310' feet from the North line and 2,310' feet from the West line

Section 12 Township 8S Range 27E NMPM Chaves County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

3/23/04 – RU. POH w/ 84 3/4" rods and pump. ND wellhead and NU BOP. RU floor and 2-3/8" tubing equipment. POOH w/ 66 joints 2-3/8" tubing & close in well. SD.

3/24/04 – Drilled cement from 1,600' to 1,700'. Fell out of cement. Washed & drilled from 1,706' to 2,715'. Tagged cement. Drilled cement from 2,715' – 2,725'. Fell out of cement. Circulated from 2,725'–2,768'. Circulated clean. Pulled up into casing w/ bit. SI. SD.

3/25/04 – Hooked up JWS to pump. Pumped 20 bbls fresh water. Spotted 25 sacks cement at 2,214'. POOH w/ 30 joints and WOC. TIH w/ tubing. Tagged cement at 1,927'. Laid down 1 joint. Circulated salt gel mud. POOH & laid down tubing to 528'. Spotted 25 sacks cement. Calc TOC at 275'. POOH. ND BOP. TIH w/ 3 joints to 75'. Circulated cement to surface. Laid down tubing. Fill casing to top. RD. Install regulation abandonment marker as per regulations. Plugged and Abandoned on 3/25/04. **PLUGGED AND ABANDONED – FINAL REPORT.**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE: Su'Ann Rogers TITLE: Regulatory Tech. DATE: 4/8/04

Type or print name Su'Ann Rogers E-mail address: Telephone No. 505-748-1471

(This space for State use)

APPROVED BY: [Signature] TITLE: Field Rep ID DATE: JUN 4 2004

Conditions of approval, if any.



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

JK-Eng
SM-prod
3 29-04

GARY E. JOHNSON
Governor
Betty Rivera
Cabinet Secretary

6/3/04 -
OK for Release
MB

Lori Wrotenberg
Director
Oil Conservation Division

RECEIVED
MAY 25 2004
OCC-ARTESIA

Yates Petroleum Corporation
105 South 4th Street
Artesia, New Mexico 88210

Form C-103 Report of Plugging for your Quincy AMQ St. #8. Sec 12-T8S-R27E-30-005-63051
Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- ☐ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Jim King
Name

date
5-17-04

Van Barton
Field Rep. II

DELG Superintendent
Title