Submit 3 Copies To Appropriate District Office <u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	State o Energy, Mineral			WELL API NO.	Form C-1 March 4, 20
District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 Sou	OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505		30-015-28418 5. Indicate Type STATE	of Lease X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa I	Fe, NM 87.	505	6. State Oil & G LG-6459	as Lease No.
		EPEN OR PLU		7. Lease Name of Agave AAJ State	or Unit Agreement Name
PROPOSALS.)  1. Type of Well:  Oil Well X Gas Well	_	·	CEIVED	8. Well Number 3	
2. Name of Operator	<u> </u>	JUN	1 2 2 2004	9. OGRID Numl	ber
Yates Petroleum Corporation			ARTEGIA	025575	337'1 1
<ol> <li>Address of Operator</li> <li>South Fourth Street, Artesia, 1</li> </ol>	VM 88210	Gas Good and		10. Pool name of Siegrest Draw Al	
4. Well Location Unit Letter E : 1  Section 32	980 feet from the	North 19S Ran	_	60 feet from t	the West lin
Section 32	11. Elevation (Show v		RKB, RT, GR, etc.		dy County
Pit or Below-grade Tank Application (Fo	r pit or below-grade tank clo			<u>ed)</u>	
Pit Location: ULSectTwp	Rng Pit type	De <sub>l</sub>	oth to Groundwater_	Distance from n	earest fresh water well
Distance from nearest surface water	Below-grade Tank L	ocation UL	SectTwp	Rng;	i
feet from theline and	feet from the	line			
	Appropriate Box to I	Indicate Na		SEQUENT RE	
12. Check A NOTICE OF IN	Appropriate Box to I	Indicate Na	SUB REMEDIAL WOR	SEQUENT RE	PORT OF: ALTERING CASING [
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON	Appropriate Box to I TENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE	Indicate Na	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI	SEQUENT RE	PORT OF: ALTERING CASING [ PLUG AND
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON TO PULL OR ALTER CASING	Appropriate Box to ITENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION	Indicate Na	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: ertinent details, and	SEQUENT RE  K  ILLING OPNS.  ND  d give pertinent dat	PORT OF: ALTERING CASING [ PLUG AND [ ABANDONMENT
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  Yates Petroleum Corporation plans to the standard of the standa	Appropriate Box to ITENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION  Reted operations. (Clear ork). SEE RULE 1103.  To plug and abandon this ment on top.	Indicate Na	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AT CEMENT JOB OTHER: ertinent details, and completions: At	SEQUENT RE  K  ILLING OPNS.  ND  d give pertinent dat	PORT OF: ALTERING CASING [ PLUG AND [ ABANDONMENT
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  Yates Petroleum Corporation plans t Rig up all safety equipment.  Set 7" CIBP at 3936' with 35' cer Circulate hole with 9.5# mud.  Set 100' cement plug at +/-3171'.  Set 100' cement plug at +/-1435'.  Squeeze perfs at 415'.  Screw in 7" casing swedge and ci Cut off wellhead and install mark	Appropriate Box to ITENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION  letted operations. (Clear ork). SEE RULE 1103. to plug and abandon this ment on top.  Tag plug.  reculate cement to surfaceer.	Indicate Na	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: extinent details, and completions: At	SEQUENT RE  K  ILLING OPNS.  ND  d give pertinent dat	PORT OF: ALTERING CASING [ PLUG AND [ ABANDONMENT
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  Yates Petroleum Corporation plans t I. Rig up all safety equipment. I. Set 7" CIBP at 3936' with 35' cet I. Circulate hole with 9.5# mud. I. Set 100' cement plug at +/-3171' I. Set 100' cement plug at +/-1435' I. Squeeze perfs at 415' I. Screw in 7" casing swedge and ci	Appropriate Box to ITENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION  leted operations. (Clear ork). SEE RULE 1103. to plug and abandon this ment on top.  Tag plug. Tag plug. Trulate cement to surfacer. In will use steel pits and above is true and completosed according to NMOCI	Indicate Na  N X  Cly state all period of the state all period of the state all period of the state of the best of the best of guidelines of the state of the best of guidelines of the state of the sta	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: extinent details, and exterminent	SEQUENT RE  K  LLING OPNS.  ND  d give pertinent dat tach wellbore diagr	PORT OF: ALTERING CASING [ PLUG AND ABANDONMENT  Tes, including estimated of the proposed completed and the proposed completed an
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  Yates Petroleum Corporation plans t  Rig up all safety equipment.  Set 7" CIBP at 3936' with 35' cer  Circulate hole with 9.5# mud.  Set 100' cement plug at +/-3171'.  Set 100' cement plug at +/-1435'.  Serew in 7" casing swedge and ci  Cut off wellhead and install mark  NOTE: Yates Petroleum Corporation hereby certify that the information rade tank has been/will be constructed or	Appropriate Box to ITENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION  leted operations. (Clear ork). SEE RULE 1103. o plug and abandon this ment on top.  Tag plug.  reulate cement to surface er.  n will use steel pits and above is true and completosed according to NMOCI	Indicate Na  N X  In X	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: ertinent details, and completions: At wws:	SEQUENT RE  K	PORT OF: ALTERING CASING [ PLUG AND ABANDONMENT  Tes, including estimated or arm of proposed complete arm of proposed complete or certify that any pit or belonative OCD-approved plan [ ATE: June 21, 2004
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  Yates Petroleum Corporation plans t Rig up all safety equipment. Set 100' cement plug at +/-3171' Set 100' cement plug at +/-1435'. Squeeze perfs at 415'. Screw in 7" casing swedge and ci Cut off wellhead and install mark NOTE: Yates Petroleum Corporation hereby certify that the information rade tank has been/will be constructed or SIGNATURE:  Type or print name  Tina Huert	Appropriate Box to ITENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION  leted operations. (Clear ork). SEE RULE 1103. o plug and abandon this ment on top.  Tag plug.  reulate cement to surface er.  n will use steel pits and above is true and completosed according to NMOCI	Indicate Na  N X  Cly state all period of the state all period of the state all period of the state of the best of the best of guidelines of the state of the best of guidelines of the state of the sta	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: ertinent details, and completions: At wws:	SEQUENT RE  K	PORT OF: ALTERING CASING [ PLUG AND ABANDONMENT  res, including estimated or ram of proposed complete or certify that any pit or belonative OCD-approved plan [
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  Yates Petroleum Corporation plans t  Rig up all safety equipment.  Set 7" CIBP at 3936' with 35' cer  Circulate hole with 9.5# mud.  Set 100' cement plug at +/-3171'.  Set 100' cement plug at +/-1435'.  Serew in 7" casing swedge and ci  Cut off wellhead and install mark  NOTE: Yates Petroleum Corporation hereby certify that the information rade tank has been/will be constructed or	Appropriate Box to ITENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION  leted operations. (Clear ork). SEE RULE 1103. o plug and abandon this ment on top.  Tag plug.  reulate cement to surface er.  n will use steel pits and above is true and completosed according to NMOCI	Indicate Na  N X  In X	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AI CEMENT JOB OTHER: extinent details, and exterminent	SEQUENT RE  K	PORT OF: ALTERING CASING [ PLUG AND ABANDONMENT  Tes, including estimated or arm of proposed complete arm of proposed complete or certify that any pit or belonative OCD-approved plan [ ATE: June 21, 2004

WELL NAME: Agave "AAJ" St #3 Field: Siegrest Draw ABO LOCATION: Unit E, Sec 32, T19S-R24E 1980' FNL & 660' FWL **Eddy County ZERO**: 9' **KB**: 3823' **GL**: 3814 9 5/8" 36# 8R J-55 1385' **SPUD DATE**: 4/3/95 **COMPLETION DATE: 6/9/95** 7" 23# J-55 ST&C 4239' COMMENTS:\_\_\_ **AFTER** San Andres plug @ 415' Circ to surface in & out of casing 14 3/4" hole **TOC 800' CBL TOPS** 100' casing shoe plug 365' San Andres 3 5/8" @ 1385' w/2050 sx set @ 1435' Tag @ -Glorieta 1685' and 30 yrd (circ) 1335 3121' Tubb Abo Shale 3770' Abo Dolomite 3892' 8 3/4" hole 100' Tubb plug set @3171' 7" CIBP set @ 3936' with 35' cement dumped on top Perf's: 3986'-4090" w/81 .52" holes Acidize: 13500 g 20% nefe, 180'000 g gel w/ 700,000# 20/40 PBTD 4190'

7" @ 4239' w/400 sx cmt

WELL NAME: Agave "AAJ" St #3 Field: Siegrest Draw ABO LOCATION: Unit E, Sec 32, T19S-R24E 1980' FNL & 660' FWL Eddy County 9, **KB**: 3823' **GL**: 3814 ZERO: 1385' 9 5/8" 36# 8R J-55 **SPUD DATE**: 4/3/95 **COMPLETION DATE**: 6/9/95 7" 23# J-55 ST&C 4239' COMMENTS: **BEFORE** 14 3/4" hole TOC 800' CBL **TOPS** San Andres 365' 9 5/8" @ 1385' w/2050 sx 1685' Glorieta and 30 yrd (circ) Tubb 3121' Abo Shale 3770' Abo Dolomite 3892' 8 3/4" hole 2 7/8" Tbg @ 4068' Perf's: 3986'-4090" w/81 .52" holes Acidize: 13500 g 20% nefe, 180'000 g gel w/ 700,000# 20/40 PBTD 4190' 7" @ 4239' w/400 sx cmt

TD 4240'