Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103	
Office District I	ergy, Minerals and Natural Resources	Revised June 10, 2003	
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210	IL CONSERVATION DIVISION	30-015-00692	
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM		o. State of the Gas Dease No.	
87505 SUNDRY NOTICES AN	D REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		<b>3</b>	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		StateB	
1. Type of Well:	İ	8. Well Number	
Oil Well Gas Well Other X	RECEIVED	1	
2. Name of Operator		9. OGRID Number	
SDX Resources, Inc.	11 10 11 / /114 1	020451	
3. Address of Operator	OCO:ARTESIA	10. Pool name or Wildcat	
PO Box 5061, Midland, TX 79704		Red Lake, QN-GB-SA	
4. Well Location			
Unit Letter B: 980 feet from the North line and 2300 feet from the East line			
	T. 120 P. 27F	NA (T) ( )	
Section 36	Township 17S Range 27E vation (Show whether DR, RKB, RT, GR, etc.)	NMPM Eddy County	
11. Lievanion (onlow whether Dr., 1915, 11, Org every			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG	AND ABANDON   REMEDIAL WORK	☐ ALTERING CASING ☐	
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ PLUG AND X			
		ABANDONMENT	
PULL OR ALTER CASING MULTIPLE CASING TEST AND COMPLETION CEMENT JOB			
OTHER:	□ OTHER:	П	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
8" mudded to 875' (pulled)			
7" csg @ 1415' w/50 sx			
OH 1415' – 1744'			
4/25/04: P&A Procedure: Set CIBP @ 1370'. Circ hole w/mud laden fluid & spot 10 sx plug on CIBP. Perf csg @ 600', 400' & 60'.			
TIH w/pkr & pump 60 sx plug in & out of 7" csg 500' – 600'. TOH. WOC			
TIH w/pkr & pump 80 sx plug in & out of 7" csg 300' - 400'. TOH. WOC. Tag plug 126'. Pump 40 sx plug 60' to surf.			
WOC 24 hrs. TOC @ surf.			
RDMO.			
Verbal approval & witnessed by Phil Hawkin, NMOCD - Artesia.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
Ra . A A			
SIGNATURE DATE 6/3/04			
Type or print name Bonnie Atwater	E-mail address: batwater@sdxresources.com	n_ Telephone No. 432/685-1761	
(This space for State use)			
ADDDDOVED DV	7999 5		
APPPROVED BY Conditions of annroval if any	TITLE	DATE	