

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised May 08, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30.015.00835
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Empire Abo Unit 'O'
Well No. 6
8. GRID Number 000778
9. Pool name or Wildcat Empire Abo
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3532' DF

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
BP America Production Company

3. Address of Operator
P.O. Box 1089 Eunice NM 88231

4. Well Location
Unit Letter **K** : **1980** feet from the **S** line and **1980** feet from the **W** line
Section **09** Township **18S** Range **27E** NMPM County **EDDY**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3532' DF

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

TD: 5717' PED: 5686' PERFS: 5600-5628'

MIRUPU. POH W/RODS & PMP. NDWH. NUBOP. POH W/TBG
RIH W/BIT & SCRAPER TO 5686'. POH. RIH W/RBP & TBG. SET @ 5590'
RUWL. RUN TDT LOGS F/5590-5200'. SELECT PERFS FROM LOGS & PERF.
TEST TBG IN HOLE TO 5,000# BELOW SLIPS
RUN EMULSION TEST & ACIDIZE WELL
SWAB WELL FOR TEST & EVAL FOR SAND FRAC
RUWH TO FRAC WELL. FRAC AND FLOW BACK
RIH W/TBG & RETRIEVING HEAD TO RETRIEVE BP
RIH W/TBG. HANG ON BELOW BTM PERF. NDBOP. NUWH.
RIH W/PMP & RODS. HANG WELL ON.
RTP

Fax: EAU
06.30.04

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Staff Support DATE 06.30.04

Type or print name Kellie D. Murrish Telephone No. 505.394.1649

(This space for State use)
APPROVED BY Jim W. Gunn TITLE District Supervisor DATE JUN 08 2004
Conditions of approval, if any: