

Submit 3 Copies
to Appropriate
District Office

DISTRICT I
P.O. Box 1940, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DO, Artesia, NM 88210


DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89




SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> WIW	6. State Oil & Gas Lease No. K67721
2. Name of Operator Saga Petroleum, LLC	7. Lease Name or Unit Agreement Name Double L Queen Tract 21
3. Address of Operator 415 W. Wall, Suite 1900, Midland, TX 79701	8. Well No. 1
4. Well Location Unit Letter M : 660 Feet From The South Line and 660 Feet From The West Line Section 24 Township 14S Range 29E NMPM Chaves County	9. Pool name or Wildcat Double L Queen
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-29-01 Set 5-1/2" CIBP @ 1833' cap w/ 35' cmt. w/ dumpbailer.
3-29-01 Mix mud & circ.
3-29-01 Perf 4 holes @1300', set pkr @ 1050', sqz 35 sx cmt., tag plug @1160'.
3-29-01 Perf 4 holes @ 377', set pkr @ 60', sqz 35 sx cmt.
3-30-01 Tag plug @ 250'.
3-30-01 Perf @ 50', circ. cmt. to Surface out of 8-5/8" csg. Leave 5-1/2" csg. full of cmt.
3-30-01 Install dry hole marker.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Agent DATE 04/05/01

TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep ID DATE JUL 07 2004

CONDITIONS OF APPROVAL, IF ANY: _____



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON
Governor
Jennifer A. Salisbury
Cabinet Secretary

Lori Wrotenbery
Director
Oil Conservation Division

Saga Pet LLC
415 W Wall STE 1900
Midland TX 79701

Tipton Oil & Gas
P.O. Box 1234
Lovington, NM 88260



Re: Plugging Reports

Form C-103 Report of Plugging for your Double L Queen Tract 21 #1 M-24 14-29-30-005-60154
Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above mentioned lease is ready for OCD inspection and approval.

Debra McKelvey
Name
Agent for Ryan Tipton, Principal
Title

6/28/04
well plugged
3/30/2001

OK
To Release.

Copy
Field Rep
Well P/A
7/9/04
[Signature]