

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised June 10, 2003

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-005-63298
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <b>P&amp;A</b>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Yates Petroleum Corporation		6. State Oil & Gas Lease No. VO-5523
3. Address of Operator 105 S. 4 <sup>th</sup> Street, Artesia, NM 88210		7. Lease Name or Unit Agreement Name Vista AVS State
4. Well Location  Unit Letter <u>A</u> : <u>330</u> feet from the <u>North</u> line and <u>330</u> feet from the <u>East</u> line Section <u>21</u> Township <u>9S</u> Range <u>26E</u> NMPM <u>Chaves</u> County		8. Well Number 5
		9. OGRID Number 025575
		10. Pool name or Wildcat Wildcat San Andres
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3760' GR		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

4/1/04 - Moved rig to location. Nipped up BOP. POOH with tubing and packer.  
4/2-4/04 - Mixed and spotted 25 sx cement at 1640'. WOC 4 hrs. No tag. Reversed out. No cement. Mixed and spotted 25 sx cement.  
4/7/04 - Tagged cement at 1225'. PUH to 982'. Mixed and spotted 25 sx cement. TIH to 60'. Mixed and circulated 15 sx to surface.  
Filled casing to top. WOC 3 hrs. Cement set up. Stayed at surface. Rigged down rig and P&A equipment.

**WELL IS PLUGGED AND ABANDONED. FINAL REPORT.**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE: Tina Huerta TITLE: Regulatory Compliance Supervisor DATE: April 14, 2004

Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471

(This space for State use)

APPROVED BY: [Signature] TITLE: Field Rep DATE: AUG 12 2004

Conditions of approval, if any:



NEW MEXICO ENERGY, MINERALS and  
NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON

Governor  
Betty Rivera  
Cabinet Secretary

Lori Wrotenberg

Director  
Oil Conservation Division

RECEIVED

AUG 02 2004

OCB-ARTESIA

Yates Petroleum Corporation  
105 South 4<sup>th</sup> Street  
Artesia, New Mexico 88210

Form C-103 Report of Plugging for your *Vista AVS ST. #5 Sec 21-T9S-R26E-30-005-63298*  
Cannot be approved until an NMOCDD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

*Jim K*  
Name

*date*  
*7-28-04*

\_\_\_\_\_  
Van Barton  
Field Rep. II

*Relg Supp.*  
Title