

\*Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised May 08, 2003

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <b>30.015.22628</b>
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator <b>BP America Production Company</b>		6. State Oil & Gas Lease No. <b>E-7116</b>
3. Address of Operator <b>P.O. Box 1089 Emice NM 88231</b>		7. Lease Name or Unit Agreement Name: <b>Empire Abo Unit 'F'</b>
4. Well Location Unit Letter <b>G</b> : <b>1330</b> feet from the <b>N</b> line and <b>1980</b> feet from the <b>E</b> line Section <b>34</b> Township <b>17S</b> Range <b>28E</b> NMPM County <b>EDDY</b>		8. Well No. <b>352</b>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <b>3670.3' GR</b>		9. OGRID Number <b>000778</b>
		10. Pool name or Wildcat <b>Empire Abo</b>

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

TD: 6285' PBD: 5987' (CIBP W/25' CMT) CIBP: 6012' W/25' CMT PERFS: 5860-5924'

06.09.04: MIRUPU. BLEED WELL DOWN. RIG UP SWAB. RIH TO SN @ 5907L. POH. DROP SV.

06.10.04: PU PMP TRUCK & TEST CSG TO 500# PSI FOR 15 MINS. HELD GOOD. ROWL. RU HOT OIL PMP TRUCK ON TBG. PMP 16 BBL OIL. RD. RIH W/PERF GUNS & PERF TBG @ 5880'. POH. SWAB & TAG FL @ 4000'

06.11.04: NDWH. NUBOP. UNSET PKR & POH W/TBG & SN. RIH W/BIT & SCRAPER. TAG BOTTOM.

06.14.04: POH. RIH W/LOGGING TOOLS & LOG BOTTOM OF HOLE FOR PERFORATING.

06.15.04: RIH W/DUMP BAILER. DUMP CMT ON TOP OF PLUG @ 6012'. POH. RIH W/PERF GUNS & PERF F/5860-5924', 2 JSPF, 63 HOLES.

06.16.04: RU TESTERS & TEST TBG GOING IN HOLE W/PKR & SN. 96 STANDS. & 1 SINGLE. RD TESTERS. PUH ABOVE PERFS & LEAK PKR SWINGING AT 5780'. WAIT F/FAC TRUCKS.

06.17.04: RU PUMP TRUCKS AND ACIDIZE WELL N2 FOAMED ACID 4000 GALS & 15% HCL. (OVER)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Staff Support DATE 08.09.04

Type or print name Kellie D. Murrish

Telephone No. 505.394.1649

(This space for State use)

APPROVED BY FOR RECORDS ONLY TITLE DATE AUG 11 2004  
Conditions of approval, if any:

06.17.04: FLOW BACK TO TEST TANK. RU SWAB.

06.18-22.04: SWAB WELL

06.23.04: RUWL & RIH W/PERF TOOL. PERF TBG @ 5775'. POH. SWAB & TAG  
FL @ 4400'

06.24.04: UNSET PKR & POH W/TBG & SN. RIH W/PROD ASSY. 2-3/8" TBG  
SET @ 5923'. SN @ 5934'. NDBOP. SET TAC. NUWH.

07.01.04: RTP. IN 24 HRS PMP'D 116 MCF, 35 BO, 19 BW.