Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

SEP 0 3 2004

FORM APPROVED OMB No. 1004-0135 Expires January 31, 2004

HTESIA 5. Lease Serial No

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

NMLC029395A

6. If Indian, Allottee or Tribe Name

apandoned well. Use Form 3100-3 (AFD) for such proposals.				
SUBMIT IN TRIPLICATE - Other instructions on reverse side	7. If Unit or CA/Agreement, Name and/or No.			
Type of Well Oil Well Gas Well Other	8. Well Name and No.			
Name of Operator MARBOB ENERGY CORPORATION	TONY FEDERAL #1 9. API Well No.			
A. Address 3b. Phone No. (include area code) PO BOX 227, ARTESIA, NM 88211-0227 (505) 748-3303	30-015-30381 10. Field and Pool, or Exploratory Area			
Location of Well (Footage, Sec., T., R., M., or Survey Description)	CEDAR LAKE; YESO 11. County or Parish, State			
330 FSL 2056 FWL, SEC. 18-T17S-R31E, UNIT N	EDDY CO., NM			

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

T	YPE OF SUBMISSION		TYPE OF ACTION					
			Acidize		Deepen	Production (Start/Resume)	Water Shut-Off	
u	Notice of Intent	Ö	Alter Casing		Fracture Treat	Reclamation	Well Integrity	
X	Subsequent Report	⊠	Casing Repair		New Construction	Recomplete	Other	
_	Subsequent respect		Change Plans		Plug and Abandon	Temporarily Abandon		
	Final Abandonment Notice		Convert to Injection		Plug Back	Water Disposal		

- 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)
 - 1. SWEDGED AND ROLLED OUT TIGHT SPOTS IN 5 1/2" CSG FROM 2770' 3096'.
 - 2. SET CIBP @ 4595'
 - 3. SET CMT RETAINER @ 2719'.
 - 4. PUMP 500 SX CLASS "C" CMT.
 - 5. DRILLED OUT RETAINER & CMT. RIH TO 4595'. TAG CIBP.
 - 6. RAN & SET 4"/10.46/J55/ULT-FJ LINER FROM SURFACE TO 4060'. CEMENTED TO SURFACE W/ 200 SX CLASS "C" CMT (CIRC 38 SX).
 - 7. DRILLED CIBP. PUSH CIBP TO 5068'.
 - 8. PUT WELL BACK ON PUMP & RETURNED TO PRODUCTION.

14. I hereby certify that the foregoing is true and correct							
Name (Printed/Typed)	i						
DIANA J. CANNON	Title	PRODUCTION ANAL	YST				
Signature MAN	Date	9/2/04					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by	Т	itle	Date				
Conditions of approval, if any, are attached. Approval of this notice does not wan certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.	rant or t lease	office					

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.