	State of New Mexico	Form C-103
Office District I Energy,	Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CO	ONSERVATION DIVISION	30-015-28639
	20 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa 1 0, 14141 07303	6. State Off & Gas Lease No.
87505		
SUNDRY NOTICES AND REI		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL O DIFFERENT RESERVOIR. USE "APPLICATION FOR PER		Harroun 22
PROPOSALS.)	RECEIVED	
1. Type of Well: Oil Well Gas Well	Other	8. Well Number 1
2. Name of Operator	OCT 1 2 2004	9. OGRID Number
Pogo Producing Company	- ORD:ARTESIA	017891
3. Address of Operator		10. Pool name or Wildcat
P. O. Box 10340, Midland, TX 797	UZ-734U	Cedar Canyon Delaware
4. Well Location    Unit Letter   D   660   fact from the North   line and   660   fact from the West   line		
		neet mom theme
	wnship 24S Range 29E	NMPM Eddy County
11. Elevation	a (Show whether DR, RKB, RT, GR, etc.	
Pit or Below-grade Tank Application or Closure		
Pit typeDepth to GroundwaterDista	nce from nearest fresh water well Dis	tance from nearest surface water
Pit Liner Thickness: mil Below-Grad	le Tank: Volumebbls; Co	onstruction Material
12. Check Appropriate I	Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND A	ABANDON 🔲 📗 REMEDIAL WOF	RK. ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A		
PULL OR ALTER CASING MULTIPLE C	COMPL CASING/CEMEN	TJOB
OTHER	C OTHER:	Add Perfs (X)
OTHER:  13. Describe proposed or completed operation	OTHER:	Add Perfs X
13. Describe proposed or completed operation	s. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
13. Describe proposed or completed operation	s. (Clearly state all pertinent details, an	
13. Describe proposed or completed operation of starting any proposed work). SEE RUL	s. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.	s. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
<ol> <li>Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.</li> <li>O9/21/04 TOH w/ rods, pump &amp; tbg.</li> </ol>	s. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.</li> <li>09/21/04 TOH w/ rods, pump &amp; tbg.</li> <li>09/22/04 Set CIBP @ 5190'. Test to 3000# ok.</li> </ul>	is. (Clearly state all pertinent details, an LE 1103. For Multiple Completions: A	d give pertinent dates, including estimated date
<ul> <li>13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.</li> <li>09/21/04 TOH w/ rods, pump &amp; tbg.</li> <li>09/22/04 Set CIBP @ 5190'. Test to 3000# ok.</li> <li>09/23/04 Perf Delaware 4898-4930 w/ 1 spf. Ac</li> </ul>	is. (Clearly state all pertinent details, an LE 1103. For Multiple Completions: A	d give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  09/21/04 TOH w/ rods, pump & tbg. 09/22/04 Set CIBP @ 5190'. Test to 3000# ok. 09/23/04 Perf Delaware 4898-4930 w/ 1 spf. Ac 09/30/04 Frac w/ 72,000# 20/40 sand.	is. (Clearly state all pertinent details, an LE 1103. For Multiple Completions: A	d give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  09/21/04 TOH w/ rods, pump & tbg. 09/22/04 Set CIBP @ 5190'. Test to 3000# ok. 09/23/04 Perf Delaware 4898-4930 w/ 1 spf. Ac 09/30/04 Frac w/ 72,000# 20/40 sand. 10/05/04 DO CIBP @ 5190'.	is. (Clearly state all pertinent details, an LE 1103. For Multiple Completions: A	d give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  09/21/04 TOH w/ rods, pump & tbg. 09/22/04 Set CIBP @ 5190'. Test to 3000# ok. 09/23/04 Perf Delaware 4898-4930 w/ 1 spf. Ac 09/30/04 Frac w/ 72,000# 20/40 sand.	is. (Clearly state all pertinent details, an LE 1103. For Multiple Completions: A	d give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  09/21/04 TOH w/ rods, pump & tbg. 09/22/04 Set CIBP @ 5190'. Test to 3000# ok. 09/23/04 Perf Delaware 4898-4930 w/ 1 spf. Ac 09/30/04 Frac w/ 72,000# 20/40 sand. 10/05/04 DO CIBP @ 5190'.	is. (Clearly state all pertinent details, an LE 1103. For Multiple Completions: A	d give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  09/21/04 TOH w/ rods, pump & tbg. 09/22/04 Set CIBP @ 5190'. Test to 3000# ok. 09/23/04 Perf Delaware 4898-4930 w/ 1 spf. Ac 09/30/04 Frac w/ 72,000# 20/40 sand. 10/05/04 DO CIBP @ 5190'.	is. (Clearly state all pertinent details, an LE 1103. For Multiple Completions: A	d give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  09/21/04 TOH w/ rods, pump & tbg. 09/22/04 Set CIBP @ 5190'. Test to 3000# ok. 09/23/04 Perf Delaware 4898-4930 w/ 1 spf. Ac 09/30/04 Frac w/ 72,000# 20/40 sand. 10/05/04 DO CIBP @ 5190'.	is. (Clearly state all pertinent details, an LE 1103. For Multiple Completions: A	d give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  09/21/04 TOH w/ rods, pump & tbg. 09/22/04 Set CIBP @ 5190'. Test to 3000# ok. 09/23/04 Perf Delaware 4898-4930 w/ 1 spf. Ac 09/30/04 Frac w/ 72,000# 20/40 sand. 10/05/04 DO CIBP @ 5190'.	is. (Clearly state all pertinent details, an LE 1103. For Multiple Completions: A	d give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  09/21/04 TOH w/ rods, pump & tbg. 09/22/04 Set CIBP @ 5190'. Test to 3000# ok. 09/23/04 Perf Delaware 4898-4930 w/ 1 spf. Ac 09/30/04 Frac w/ 72,000# 20/40 sand. 10/05/04 DO CIBP @ 5190'.	is. (Clearly state all pertinent details, an LE 1103. For Multiple Completions: A	d give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  09/21/04 TOH w/ rods, pump & tbg. 09/22/04 Set CIBP @ 5190'. Test to 3000# ok. 09/23/04 Perf Delaware 4898-4930 w/ 1 spf. Ac 09/30/04 Frac w/ 72,000# 20/40 sand. 10/05/04 DO CIBP @ 5190'.	is. (Clearly state all pertinent details, an LE 1103. For Multiple Completions: A	d give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  09/21/04 TOH w/ rods, pump & tbg. 09/22/04 Set CIBP @ 5190'. Test to 3000# ok. 09/23/04 Perf Delaware 4898-4930 w/ 1 spf. Ac 09/30/04 Frac w/ 72,000# 20/40 sand. 10/05/04 DO CIBP @ 5190'.	is. (Clearly state all pertinent details, an JE 1103. For Multiple Completions: A details. A detail	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  09/21/04 TOH w/ rods, pump & tbg. 09/22/04 Set CIBP @ 5190'. Test to 3000# ok. 09/23/04 Perf Delaware 4898-4930 w/ 1 spf. Ac 09/30/04 Frac w/ 72,000# 20/40 sand. 10/05/04 DO CIBP @ 5190'. 10/06/04 Well returned to production.	is. (Clearly state all pertinent details, an JE 1103. For Multiple Completions: A cdz w/ 1900 gals 7-1/2% acid. Swab.	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  09/21/04 TOH w/ rods, pump & tbg. 09/22/04 Set CIBP @ 5190'. Test to 3000# ok. 09/23/04 Perf Delaware 4898-4930 w/ 1 spf. Ac 09/30/04 Frac w/ 72,000# 20/40 sand. 10/05/04 DO CIBP @ 5190'.	is. (Clearly state all pertinent details, an JE 1103. For Multiple Completions: A cdz w/ 1900 gals 7-1/2% acid. Swab.	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  09/21/04 TOH w/ rods, pump & tbg. 09/22/04 Set CIBP @ 5190'. Test to 3000# ok. 09/23/04 Perf Delaware 4898-4930 w/ 1 spf. Ac 09/30/04 Frac w/ 72,000# 20/40 sand. 10/05/04 DO CIBP @ 5190'. 10/06/04 Well returned to production.	is. (Clearly state all pertinent details, an LE 1103. For Multiple Completions: A cdz w/ 1900 gals 7-1/2% acid. Swab.  Indicomplete to the best of my knowledge to NMOCD guidelines , a general permit	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion ge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  09/21/04 TOH w/ rods, pump & tbg. 09/22/04 Set CIBP @ 5190'. Test to 3000# ok. 09/23/04 Perf Delaware 4898-4930 w/ 1 spf. Ac 09/30/04 Frac w/ 72,000# 20/40 sand. 10/05/04 DO CIBP @ 5190'. 10/06/04 Well returned to production.	is. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: A cdz w/ 1900 gals 7-1/2% acid. Swab.  Indicated the complete to the best of my knowledge to NMOCD guidelines , a general permit   TITLE Sr. Eng. Tec	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion ge and belief. I further certify that any pit or below-lor an (attached) alternative OCD-approved plan
13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  09/21/04 TOH w/ rods, pump & tbg. 09/22/04 Set CIBP @ 5190'. Test to 3000# ok. 09/23/04 Perf Delaware 4898-4930 w/ 1 spf. Ac 09/30/04 Frac w/ 72,000# 20/40 sand. 10/05/04 DO CIBP @ 5190'. 10/06/04 Well returned to production.	is. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: A cdz w/ 1900 gals 7-1/2% acid. Swab.  Indicate to the best of my knowledge to NMOCD guidelines , a general permit   TITLE Sr. Eng. Tec wrightc@pogoprod	ge and belief. I further certify that any pit or below- for an (attached) alternative OCD-approved plan .  h  DATE 10/07/04  ucing.com 432-685-8100
13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  09/21/04 TOH w/ rods, pump & tbg. 09/22/04 Set CIBP @ 5190'. Test to 3000# ok. 09/23/04 Perf Delaware 4898-4930 w/ 1 spf. Ac 09/30/04 Frac w/ 72,000# 20/40 sand. 10/05/04 DO CIBP @ 5190'. 10/06/04 Well returned to production.  I hereby certify that the information above is true a grade tank has been/will be constructed or closed according.  SIGNATURE Add Wright  Type or print name Cathy Wright	is. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: A cdz w/ 1900 gals 7-1/2% acid. Swab.  Indicated the complete to the best of my knowledge to NMOCD guidelines , a general permit   TITLE Sr. Eng. Tec	ge and belief. I further certify that any pit or belowder an any fit or an (attached) alternative OCD-approved plan DATE 10/07/04 ucing.com  DATE 10/07/04 Telephone No.
13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  09/21/04 TOH w/ rods, pump & tbg. 09/22/04 Set CIBP @ 5190'. Test to 3000# ok. 09/23/04 Perf Delaware 4898-4930 w/ 1 spf. Ac 09/30/04 Frac w/ 72,000# 20/40 sand. 10/05/04 DO CIBP @ 5190'. 10/06/04 Well returned to production.  I hereby certify that the information above is true a grade tank has been/will be constructed or closed according.  SIGNATURE Add Wright Type or print name Cathy Wright For State Use Only	is. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: A cdz w/ 1900 gals 7-1/2% acid. Swab.  Indicated to the best of my knowledge to NMOCD guidelines , a general permit   TITLE Sr. Eng. Teccuric wrightc@pogoprod E-mail address:	ge and belief. I further certify that any pit or below- for an (attached) alternative OCD-approved plan .  h  DATE 10/07/04  ucing.com 432-685-8100
13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  09/21/04 TOH w/ rods, pump & tbg. 09/22/04 Set CIBP @ 5190'. Test to 3000# ok. 09/23/04 Perf Delaware 4898-4930 w/ 1 spf. Ac 09/30/04 Frac w/ 72,000# 20/40 sand. 10/05/04 DO CIBP @ 5190'. 10/06/04 Well returned to production.  I hereby certify that the information above is true a grade tank has been/will be constructed or closed according.  SIGNATURE Add Wright Type or print name Cathy Wright For State Use Only	is. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: A cdz w/ 1900 gals 7-1/2% acid. Swab.  Indicate to the best of my knowledge to NMOCD guidelines , a general permit   TITLE Sr. Eng. Tec wrightc@pogoprod	ge and belief. I further certify that any pit or belowder an any fit or an (attached) alternative OCD-approved plan DATE 10/07/04 ucing.com  DATE 10/07/04 Telephone No.