## N.M. Oil Cons. DIV-Dist. 2

Temporarily Abandon

Water Disposal

✓ Plug and Abandon

Plug Back

Form 3160-5 (April 2004)

1. Type of Well

3a Address

2. Name of Operator

UNITED STACO 1 W. Grand Avenue DEPARTMENT OF THE INTERIOR NIM 88210 -

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter O, 625 FSL, 1709 FEL Section 22, Township 17-S, Range 31-E

TYPE OF SUBMISSION

Final Abandonment Notice

Notice of Intent

Subsequent Report

L	DEFARTMENT OF THE	ANDOMAN SAME	2021A -	Expires. Maich 51, 2007	
E	BUREAU OF LAND MAN	5. Lease Serial No.			
SUNDRY	NOTICES AND REF	PORTS ON WELLS	;	LC-029419A	
Do not use th	is form for proposals t	o drill or to re-enter	r an	6. If Indian, Allottee or Tribe Name	
IBMIT IN TRI	IPLICATE- Other insti	7. If Unit or CA/Agreement, Name and/or No.  Skelly Unit			
Oil Well Gas Well Other					
ator Chevron U	USA Inc				
		2h Dhona No (include mea	- andal	30-015-29461	
5 Smith Rd, Midland, TX, 79705		432-561-8600		10 Field and Pool or Exploratory Area	
<u></u>	T., R., M., or Survey Description)			E. Cedarlake - Abo	
, ,				11 County or Parish. State	
r O, 625 FSL, 170 , Township 17-S,		6. If Indian, Allottee or Tribe Name  7. If Unit or CA/Agreement, Name and/or No.  Skelly Unit  8. Well Name and No.  904  9. API Well No.  30-015-29461  10. Field and Pool, or Exploratory Area			
, 10wnsmp 17-3,	Kange 31-E			Eddy, New Mexico	
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NATURE C	OF NOTICE, R	EPORT, OR OTHER DATA	
SUBMISSION		ТҮРЕ О			
	Acidize	Deepen	Production (St	art/Resume) Water Shut-Off	
Intent	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
nt Report	Casing Repair	New Construction	Recomplete	Other	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

1. Notified Duncan with NM BLM 24 hrs prior to MI and RU.

Change Plans

Convert to Injection

- 2. Set 5 1/2" CIBP at 7260, spot 25sx, plug from 7260-7007.
- 3. Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL.
- 4. Spot 25sx, plug from 5241-4988 (Paddock) WOC Tag at 4965.
- 5. Spot 25sx, plug from 4904-4651 (8 5/8 Shoe) WOC Tag at 4684.
- 6. Cut csg at 3165, no pull, press up to 1500 psi, spot 25sx, plug from 3218-2965.
- 7. Cut csg at 2470, no pull, press up to 1500 psi, spot 25sx, plug from 2550-2297.
- 8. Perf at 1600, sqz 60sx from 1600-1400, WOC Tag at 1364.
- 9. Circ 70sx cmt from 650-Surf.
- 10. Install dry hole marker.

P&A Complete 11-4-04

APPROVED

NOV 15 2004

(ORIG. SGD.) ALEXIS C. SWOBODA

ALEXIS C. SWOBODA PETROLEUM ENGINEER

4. I hereby certify that the foregoing is true and correct Name (Printed/Typed)		_		RECEIVED
Jimmy Bagley	Title	F	ield Supervisor	
Signature	Date	11/04/2004		NOV 1 7 2004
THIS SPACE FOR FEL	ERAL OR	STATE OFFIC	E USE	OOD ADTE
pproved by		Title	Date	
onditions of approval, if any, are attached. Approval of this notice does entify that the applicant holds legal or equitable title to those rights in the hich would entitle the applicant to conduct operations thereon.	Office			

(Instructions on page 2)