orm 3169-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB NO. 1004-0135

Expires: November 30, 2000

Lease Serial No. NMLC061701

	T	

UNITED STATES	
DEPARTMENT OF THE INTERIOR	
BUREAU OF LAND MANAGEMENT 02021222	32
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.	12 15 15 12 15 12 15 12 15 12 15 15 15 15 15 15 15 15 15 15 15 15 15
110	-

	72 230 2000	
SUBMIT IN TRIPLICATE - Other ins	structions on reverse side CEIVED	7. If Unit or CA/Agreement, Name and/or No. NMNM105334
1. Type of Well Gas Well Other	£140. 59/	8. Well Name and No. POCO LOCO 8 FED COM 1
2. Name of Operator HARVEY E YATES COMPANY Conta	E-Mail: jatkinson@neycoogs 7 & 7	9. API Well No. 30-015-31228-00-X1
3a. Address P. O. BOX 1933 ROSWELL, NM 88202	3b. Phone No. (include area code) Ph: 505.623.6601 Ext: 1219 Fx: 505.624.5321	10. Field and Pool, or Exploratory S EMPIRE
4. Location of Well (Footage, Sec., T., R., M., or Survey Descr.	iption)	11. County or Parish, and State
Sec 8 T18S R29E SESW 860FSL 1980FWL		EDDY COUNTY, NM
UT.N		
12 CHECK APPROPRIATE ROY(ES	TO INDICATE NATURE OF NOTICE R	FPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☐ Notice of Intent Subsequent Report Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Fracture Treat ☐ New Construction ☑ Plug and Abandon ☐ Plug Back	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☐ Temporarily Abandon ☐ Water Disposal	□ Water Shut-Off □ Well Integrity □ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

3/05/03 MI & RU SMITH & MARRS. ND WH & NU BOP. SDFN.

3/06/03 POOH W/108 JTS 2 3/8" TBG. SI, SDFN.

3/07/03 FINISH POOH W/2 3/8" TBG. RU WIRELINE TRUCK & GIH W/ 5 1/2" CIBP, SET @ 10,200' & TOP W/40' CMT. GIH W/2 3/8" TBG & LOAD HOLE W/9# MUD.

 $3/08/03\,$ POOH W/TBG. ND BOP. WELD ON CSG STUB TO 5 1/2" CSG. RU CSG JACKS. RU W/L TRUCK. GIH TO 9150', CUT OFF CSG, POOH. RD W/L TRUCK. PULLED ON CSG, CSG NOT FREE.

 $3/11/03\,$ GIH W/2 3/8" TBG TO 9201'. SPOT 25 SX CMT. POOH W/TBG. RU WIRELINE TRUCK, CSG CUTTER TO 8150'. CUT CSG - CSG NOT FREE. RD WIRELINE TRUCK.

14. Thereby certify	For HA	ission #19615 verified by the BLM Well Information System RVEY E YATES COMPANY, sent to the Carlsbad S for processing by Linda Askwig on 03/19/2003 (03AL0004SE)	
Name (Printed/I	Typed) JEN ATKINSON	Title AUTHORIZED SIGNATURE	
Signature	(Electronic Submission)	Date 03/19/2003	
	THIS SPA	CE FOR FEDERAL OR STATE OFFICE USE	
Approved By LES	S BABYAK	TitlePETROLEUM ENGINEER	Date 03/19/20
certify that the applic	val, if any, are attached. Approval of this is and holds legal or equitable title to this e riche applicant to conduct operations thereon		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #19615 that would not fit on the form

32. Additional remarks, continued

 $3/12/03\,$ GIH W/2 3/8" TBG TO 8201' & SPOT 25 SX CMT. PULLED UP TO 6160' & SPOT 25 SX CMT. POOH W/TBG. RU. GIH W/SLICK LINE TO 4277' & CUT OFF CSG. POOH W/34 JTS 5 1/2" CSG.

 $3/13/03\,$ FINISH POOH, LAYING DOWN 5 1/2" CSG (95 JTS TOTAL). GIH W/2 3/8" TBG TO 4341' & SPOT 40 SX CMT & WOC. GIH W/WIRELINE & TAG TOC AT 4244' (17' TOO DEEP PER BLM). GBIH W/2 3/8" TBG TO TOC & SPOT 30 MORE SX CMT. POOH W/TBG.

 $3/14/03\,$ GIH W/WIRELINE & TAG TOC AT 4157'. PULL UP TO 3278' & SPOT 40 SX CMT. WOC. GIH & TAG TOC @ 3136'. PULL UP TO 356'. SPOT 40 SX CMT. PULL TBG OUT OF HOLE. SPOT 15 SX CMT FOR SURFACE PLUG. INSTALL DRY HOLE MARKER. RIG DOWN & CLEAN LOCATION.