Form 3160-5 (August 2007)

UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO 1004-0135 Expires July 31, 2010

OCD- Artesia

	5 Lease Serial No
SUNDRY NOTICES AND REPORTS ON WELLS	NMLC029395B
not use this form for proposals to drill or to re-enter an	
1 11 11 1 0100 0 (177)	6 If Indian Allottee or Tribe Name

Do not use this form for proposals to drill or to re-enter an			7 101 P 11 11				
abandoned well. Use form 3160-3 (APD) for such proposals.				6 If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7 If Unit or CA/Agreement, Name and/or No			
I Type of Well		·····			8 Well Name and No		
🗖 Oıl Well 🔲 Gas Well 🛛 Oth		TURNER B 55					
2 Name of Operator Contact NANCY FITZWATER LINN OPERATING INCORPORATED E-Mail nfitzwater@linnenergy.com					9 API Well No 30-015-05444-00-S1		
3a Address 600 TRAVIS STREET SUITE HOUSTON, TX 77002	3b Phone No Ph: 281-84 Fx: 281-840			10 Field and Pool, or Exploratory GRAYBURG			
4 Location of Well (Footage, Sec., T			11 County or Parish, and State				
Sec 29 T17S R31E SENE 1980FNL 660FEL				-	EDDY COUNTY, NM		
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE	NATURE OF	NOTICE, RI	EPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
	☐ Acidize	Deepen				☐ Water Shut-Off	
□ Notice of Intent	Alter Casing	Fracture Treat		☐ Reclam		☐ Well Integrity	
Subsequent Report ■	Cook as a sound Down and		Construction	☐ Recomp		Other	
☐ Final Abandonment Notice	Change Plans	_	and Abandon	_	arily Abandon	_ canor	
	Convert to Injection	_		☐ Water I			
Redelivery Sundry: 5-10-11 Rig to loc. Wait on ar well, open up press 900 psi. S flange for wellhead. S/I well. S 5-11-11 Crew to loc, bled well that were bad. NOTE**All tbg LD. RU testers, PU bit & scralater date, possibly turn into a Unload new string of 2 3/8 JO	Start flowing well down. W SDFN. I down. ND WH. NU BOP in well was 2 7/8 J055 ba pper, tested all tbg in der work string. RD testers,	Vell unloaded The unset AD-1 pare steel tbg. Trick bk in hole PU 30 jts of 2	okr, POOH w/3 Fallied all tbg, s We will use th 7/8 tbg to tag v per above perfs	on different 9 stands, LD stood bk and his tbg at a with. S. SDFN. record - NN	29 jts	100 13 2011 D	
14 I hereby certify that the foregoing is	s true and correct			-22-11		<u>\$/</u>	
Comm	Electronic Submission # For LINN OPERA	TING INCORP	DRATED, sent t	o the Carlsba	d [*]	•	
Committed to AFMSS for processing by DEBONAME (Printed/Typed) TAMMY SCARBOROUGH				ADMIN III	· (11DEWI0817SE)		
Signature (Electronic S	Submission)		Date 06/01/	2011			
· · · · ·	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE		
Approved By ACCEPTED			JAMES A TitleSUPERV	\"00D ED0		Date 06/04/201	
Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon			Office Carlsba	ad			
Fitle 18 U S C Section 1001 and Title 43 States any false, fictitious or fraudulent	USC. Section 1212, make it statements or representations a	a crime for any post to any matter w	erson knowingly authin its jurisdiction	nd willfully to n	nake to any department o	r agency of the United	

Additional data for EC transaction #109416 that would not fit on the form

32. Additional remarks, continued

- 5-12-11 Crew to loc Open well up RIH w/tbg & PU 7 more jts to tag @ 3322' Tally out of hole, LD bit & scrapper, PU bit & sub. RIH to 3222'. RU swivel & clean out from 3222' to 3630 Circ hole clean, rig down swivel, pull 10 stands. Close in well. SDFN
- 5-13-11 Crew to loc POOH w/tbg, LD bit & sub. TIH w/treating pkr w/92 jts & wait for acid crew to arrive RU acid truck, do acid job. Left well shut in for 3 hrs. Open well up, it 1000 psi on tbg Flowed well back to frac tank for 30 min. Well flowed bk 38 bbls. S/I well SDFN.
- 5-16-11 Tbg 700 psi, flowback well until after lunch Release pkr TOOH, LD 92 jts & pkr TIH w/13 stands out of derrick. TOOH with 26 jts. Was going to replace top bowl so we shut down to find WH, plus packer hand had put 1.87 profile on packer that won't with 2 3/8 tbg
- 5-17-11 Bleed down well, PU 5 1/2 Hornet pkr w/1 50 profile nipple T@ on/off tool PU 92 jts new 2 3/8 IPC RD floor & tongs NDBOP land tbg Circ 60 bbls pkr fluid set pkr @ 2989' pressure test mock MIT to 500 psi for 30 min, lost 21 psi. It was to windy to rig down.

5-18-11 RDWSU move off.