

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☐ Final Report

Name of Company Devon Energy	Contact Tracy Kidd
Address PO Box 250 Artesia, NM 88211	Telephone No. 575.513.0628
Facility Name Cotton Draw Unit 114	Facility Type Oil Well

Surface Owner Federal	Mineral Owner	API No. 30-015-37410 2RP-962
------------------------------	---------------	-------------------------------------

LOCATION OF RELEASE

Unit Letter B	Section 34	Township 24S	Range 31E	Feet from the 330	North/South Line North	Feet from the 1980	East/West Line East	County Eddy
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------

Latitude: 32.180117040773 _____ Longitude: 103.763554613439 _____

NATURE OF RELEASE

Type of Release Spill Oil	Volume of Release 60bbbls	Volume Recovered 50bbbls
Source of Release mechanical failure blown gasket on a heater treater	Date and Hour of Occurrence 11/11/2011	Date and Hour of Discovery 11/11/2011, 9:00 am
Was Immediate Notice Given? ☒ Yes ☐ No ☐ Not Required	If YES, To Whom? Jim Amos BLM & Mike Bratcher NMOCD	
By Whom? Chris McCullough	Date and Hour 11/11/2011 @ 11:40 am BLM & 11:50 am OCD	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Gasket rupture on fire tube in heater treater caused oil spray. RW Trucking recovered 50bbbls of oil and soil samples will be taken. Gasket was replaced on heater treater. Oil spill remained on location. RW Trucking recovered 50bbbls and soil sampling will be done.

Describe Area Affected and Cleanup Action Taken.* Talon/LPE had been contracted to perform the remedial actions. The impacted areas in the vicinity of sample locations S-1 and S-2, under the separators, heater treaters, were hand-excavated to the best extent as reasonable, feasible and as safely as possible. The current and historical areas were then treated with microblaze as a bioremediation agent. The impacted area in the vicinity of sample location S-3 was excavated to a depth of 1.5-feet deep. A confirmation sample was taken and the results were within the RRAL's. The impacted soil was transported to Lea Land, LLC. The excavated area at S-3 was backfilled using new material from a local borrow pit and re-contoured to match the surrounding location. No further action is required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sandra Farley	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Sandra Farley	Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: 8/29/2014	Expiration Date: NA
E-mail Address: Sandra.Farley@dmn.com	Conditions of Approval: Final	Attached ☐
Date: 8/27/2014 Phone: 575.746.5587		

* Attach Additional Sheets If Necessary