

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Harroun 15 #15 CTB	Facility Type	Battery

Surface Owner	Mineral Owner	API No.
---------------	---------------	---------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	15	24S	29E					Eddy County, NM

Latitude N 32.21975° Longitude W 103.97809°

**NATURE OF RELEASE**

Type of Release	Oil and Produced water	Volume of Release	10 bbls of oil, 10 bbls of produced water	Volume Recovered	15 bbls
Source of Release	Separator failed to dump causing skim tank to spill over	Date and Hour of Occurrence	03/03/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, NMOCD and Jennifer Van Curen, BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	03/03/2014 @ 4:32 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
The separator failed to dump causing the skim tank to spill 10 bbls of oil and 10 bbls of produced water inside the containment on the ground. A vacuum truck recovered a total of 15bbls and the issue with the separator was resolved.

Describe Area Affected and Cleanup Action Taken.\*  
The affected area is approximately 20' x 20' on location inside the containment around the skim tank. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 06/30/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Chris Jones Digitally signed by Chris Jones DN: cn=Chris Jones, o, ou, email=ckjones88@yahoo.com, c=US Date: 2015.04.30 12:59:23 -0500'	<b>OIL CONSERVATION DIVISION</b>	
Signature: Jones	Approved by Environmental Specialist:	
Printed Name: Christopher Jones	Approval Date: 5/8/2015	Expiration Date: N/A
Title: HES Specialist	Conditions of Approval: <b>FINAL</b>	Attached <input type="checkbox"/>
E-mail Address: Christopher.Jones@oxy.com		
Date:	Phone: (575) 628-4121	

\* Attach Additional Sheets If Necessary