

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 6/24/2015

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Occidental Permian	Contact	Charles F. Bullard Jr.
Address	6 Desta Drive, Ste. 6000, Midland, TX 79705	Telephone No.	(432) 685-5719
Facility Name	Federal 12 #2H	Facility Type	Drilling location
Surface Owner	BLM	Mineral Owner	API No. 30-015-41344

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	1	23S	30E	1159	South	1543	East	Eddy County, NM

Latitude N 32.32984° **Longitude** W 103.83012°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	45 bbls	Volume Recovered	20 bbls
Source of Release	Transfer from cellar to open-top tank and valve was left open causing water spill over	Date and Hour of Occurrence	03/18/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Bobby Girndt, BLM		
By Whom?	Tommy Sikes	Date and Hour	03/18/2014 at 6:30 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A transfer from cellar to open-top tank and the valve was left open causing 45 bbls of produced water to leak onto the ground. A vacuum truck recovered 20 bbls of produced water and the transfer/valve were closed.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 40' x 45' around the outside of the sub and along the pipe wrangler. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 01/26/2015 and approved by Sol Hughes of the BLM via email on 02/24/2015.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>C. F. Bullard Jr.</i>		OIL CONSERVATION DIVISION	
Printed Name: Charles F. Bullard Jr.		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Drilling HES Ops Advisor		Approval Date: 6/29/2015	Expiration Date: N/A
E-mail Address: Charles.Bullard@oxy.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/14/15	Phone: (432) 894-3769	FINAL	

* Attach Additional Sheets If Necessary

2RP-2341